



ELITE GROUP
INSPECTION PROFESSIONALS



800-494-8998

RESIDENTIAL



PROPERTY LOCATION: 207 W Buffalo Ave Santa Ana, CA 92706

INSPECTIONREPORT

CLIENT: Karina Stoltz -AGENT: Kevin Shuler Keller Williams Realty

Date of Inspection: 7/31/2026 at 10:00 AM

Year Built: 1922 Sq Ft: 1968

Weather: Sunny

Order ID: 404945

Inspector: Nate Armendariz

(909) 278-1463

natearmendariz@eliteinspections.com



customercare@eliteinspections.com



www.eliteinspections.com



Table Of Contents

Summary Page	2-6
OVERVIEW	7
INTERIOR	8-12
BATHROOMS	13-17
KITCHEN	18-22
LAUNDRY AREA	23-24
HEATING/AIR CONDITIONING	25
WATER HEATERS	26-28
ELECTRICAL/GAS SERVICE	29-32
ATTIC AREA	33-34
GARAGE AND/OR CARPORT	35-37
EXTERIOR AREAS	38-39
FOUNDATION	40-43
GROUNDS	44-46
ROOF	47-49
SEWER CAMERA INSPECTION	50-52
Glossary	53

Summary Page

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. Further evaluation is recommended for any item written in **red** text or marked "needs to be serviced" or "recommend servicing" on this report -- further evaluation often times will allow a contractor to find additional items needing repair beyond the scope of the inspection. Failure to further evaluate any item as recommended releases us of any liability.

INTERIOR		
Page 9 Item: 4	Window Conditions	• Older/distressed window(s) - we recommend maintenance/servicing by specialist • Missing sash/cables - needs to be serviced • Stuck in position - needs to be serviced • Cracked glass- needs to be serviced
Page 11 Item: 7	Electrical	• Ungrounded outlets present - needs to be serviced
BATHROOMS		
Page 17 Item: 12	GFCIs	• None installed recommend upgrade for increased safety @ 207½ • GFC tripped but would not reset - needs to be serviced
KITCHEN		
Page 21 Item: 7	Ovens	• Not operating - not reaching desired temperatures - gas smell detected when running fixture - needs to be serviced
Page 21 Item: 8	Exhaust Vents	• No exhaust vent in kitchen - needs to be serviced - proper ventilation needed
HEATING/AIR CONDITIONING		
Page 25 Item: 1	Heaters	• Thermostat not operating - unit not tested - needs to be serviced
Page 25 Item: 2	Thermostats	• Not operating - needs to be serviced
WATER HEATERS		
Page 26 Item: 1	Water Heaters Condition	• "Sediment knock" in tank noted; may decrease efficiency of the water heater - needs to be serviced
Page 27 Item: 7	Water Heater Temperature	• Temperature was above 120° F at the unit, this a potential scald hazard - needs to be serviced/adjusted
ELECTRICAL/GAS SERVICE		
Page 29 Item: 2	Panel Wiring	• Wiring type: tinned/nickel clad copper - this is an older type of wiring - an upgrade is recommended • Wiring method: Cloth wiring observed at various locations throughout the property - we recommend a licensed electrician for upgrade of all older materials • Wiring method: knob and tube present in areas of the structure - considered obsolete - recommend complete inspection by electrical contractor

Page 30 Item: 3	Breakers	• No visible labeling for breakers on panel cover - needs to be serviced
ATTIC AREA		
Page 33 Item: 2	Structure	• No visible roof sheathing at rafters - this is an irregular roofing installation
Page 34 Item: 5	Electrical	• Live knob and tube wiring present - this type of wiring is considered old technology and should be upgraded as soon as possible
GARAGE AND/OR CARPORT		
Page 35 Item: 2	Rafters & Ceilings	• Deteriorated wood members - needs to be serviced
Page 35 Item: 3	Main Automotive Doors	• Deteriorated wood present - needs to be serviced - consult termite report
Page 36 Item: 5	Walls	• Worn/stained/distressed wood members - older materials
Page 36 Item: 6	Anchor Bolts	• None visible - typical for estimated age - recommend upgrade
Page 37 Item: 7	Slab	• Cracked/soft areas present - signs of ground movement and settling - recommend servicing
EXTERIOR AREAS		
Page 38 Item: 1	Siding	• Worn/older materials - we recommend siding maintenance
Page 38 Item: 2	Eaves & Fascia	• Deteriorated wood - recommend evaluation by termite inspector
FOUNDATION		
Page 41 Item: 3	Sub Flooring	• Heavily deteriorated joist in areas - needs to be serviced/further evaluated by a specialist
Page 41 Item: 4	Posts and Girders	• Missing brackets at attachment points - recommend upgrade • Posts in contact with soil - needs to be serviced - consult the termite report • Cracked/sagging girder - needs to be serviced
ROOF		
Page 48 Item: 3	Gutters and Down Spouts	• Bent/dented gutter areas - recommend maintenance and repair as needed
SEWER CAMERA INSPECTION		
Page 50 Item: 1	Conditions of Sewer Line	Debris obstructing drain line in areas - needs to be serviced/further evaluated @ 69ft marker Major offset - separation gap observed @ 73ft marker - needs to be serviced/further evaluated

ABOUT YOUR INSPECTION - PLEASE READ ALL OF THE INFORMATION WE PROVIDE BELOW

In order for you to receive the full value of this inspection, please read all of the information we have provided.

ALL ITEMS IN RED PRINT ARE OF IMMEDIATE CONCERN TO THIS STRUCTURE AND SHOULD BE FURTHER EVALUATED BEFORE THE CLOSE IN ESCROW. HOWEVER, THE ENTIRE REPORT MUST BE READ FOR FULL DISCLOSURE, AS OTHER ITEMS WRITTEN IN THE REPORT MAY REQUIRE FURTHER EVALUATION AS DEEMED BY THE OPINION OF THE READER. IF A FURTHER EVALUATION IS NOT PERFORMED AND ADDITIONAL DEFECTS ARE FOUND AFTER THE CONTINGENCY PERIOD HAS EXPIRED, THEN ANY DISPUTES OR CLAIMS AGAINST THE INSPECTION WILL BE DENIED. SIMPLY PUT, IF YOU DO NOT FOLLOW THE ADVICE IN THIS REPORT, THEN YOU CANNOT HOLD THE INSPECTOR OR THE INSPECTION REPORT LIABLE AFTER YOU MOVE INTO THE INSPECTED STRUCTURE OR PROPERTY.

This IS a limited Inspection: It is impossible to inspect every square inch of every area of a home in a limited time frame. A home inspection is designed to reflect, as accurately as possible, the visible condition of the home at the time of the inspection only and does NOT reflect, anticipate or predict future conditions. Conditions at a home for sale can change radically in only a day or two, so a home inspection is not meant to guarantee what condition a home will be in when the transaction closes. It's not uncommon for conditions to change between the time of the inspection and the closing date. During this inspection your inspector did not dismantle equipment, dismantle any structural items, apply stress or destructive testing. Areas that are hidden, painted over, disguised and/or not readily visible are not covered in this report. Our report is not a guarantee or warranty on the condition of your property or its contents. This report provides an unbiased visual inspection only. Elite Group Inspection Professionals inspections are performed with consideration given to the age of the structure. Defects will be indicated and marked as such, even though the condition may be normal for the age, and should be inspected by the appropriate licensed contractor. Opinions vary from person to person and this report is the opinion of the inspector and must be considered as such. The Inspector does not determine the age or remaining life of any system or building material during this inspection. Cosmetic items are considered obvious and are often not included in your report. Your report does not include all items covered in the REAL ESTATE TRANSFER DISCLOSURE FORM. We recommend that you read the Disclaimers page in complete detail to understand the limitations of a Home Inspection.

An attorney and/or real estate broker should be consulted on additional items not included in this report.

ENVIRONMENTAL DISCLAIMER: Mold spores, asbestos, formaldehyde, radon, lead paint, Chinese drywall, poria and all other toxic items of concern cannot be identified as toxic and/or dangerous with this inspection report. Your inspector is not certified to identify any of these toxic or dangerous items and will not include any information on them in this report. It's recommended the client have the property tested by a certified expert in these areas, in all cases.

Houses/structures built between 1965 and 1974 have the possibility of aluminum wiring present throughout structure. It is recommend that a licensed electrician further evaluate houses built in this era for aluminum wiring. Houses/structures with galvanized or cast iron plumbing present are highly recommended to be further evaluated by a plumbing contractor regardless of the age of the plumbing.*

Houses/structures built prior to 1978 can contain asbestos materials. It is recommend that a licensed asbestos contractor/inspector further evaluate houses/structures built in this era for asbestos materials. The Home Inspector will not determine or include in the report if asbestos is present at any structure or in any materials at a structure.*

Houses/structures built prior to 1978 can contain lead paint. It is recommend that a licensed lead inspector further evaluate houses/structures built in this era for lead paint materials.*

***Elite Group Inspection Professionals will not engage in any claims regarding aluminum wiring, asbestos or lead paint.**

PHOTO DOCUMENTATION: Your report may include digitally imaged photos of certain problem areas (should they exist). Also included are pictures (General Views) to establish location and identification. It is not a requirement that your Home Inspector photograph every area or defect of the home; additional photos may be taken and included in your report as a courtesy. The Inspector CANNOT use photos provided by anyone else for the inspection report. Any photos included in the report must be taken by the Inspector only, with the Inspector's camera only!

ABOUT YOUR INSPECTION CONTINUED

Please carefully read your entire Inspection Report. Call your inspector after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible areas of the structure; inspection may be limited by vegetation, height restrictions, weather and possessions. Depending on the age of the structure, some items like GFCI outlets may not be installed; this report will focus on safety and function, **not current building codes**. This report identifies specific **non-building code**, non-cosmetic concerns that the inspector feels may need further investigation or repair. It is NOT a requirement that a home being sold be brought up to today's building code standards.

We advise you to check all building permits for all areas of the structures present, a home inspection is NOT a building code violation inspection. If the proper building permits have not been obtained and/or do not have final building inspection signatures, then you cannot assume that these areas were installed to applicable building codes. Further investigation beyond the scope of the home inspection may be needed.

"Needs to be serviced" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed and the item should be further evaluated. Often the items discovered by the Inspector are only clues to a potentially larger issue, further evaluation may uncover other items the inspector did not see or disclose during the inspection.

For your safety and liability purposes, we recommend that licensed contractors further evaluate and repair any and all concerns and defects noted in the report.

Lateral Sewer Line Camera Inspection: Underground drains cannot be viewed by the Inspector and can often have internal issues that do not reveal themselves during the home inspection. We highly advise you to have a sewer camera inspection prior to the release of inspection contingencies.

Every home or structure is different, therefore may be inspected in various formats. Inspections can take anywhere from 1 to 4 hours depending on the size of the structure or the age of the structure being inspected. The condition of the home or structure being inspected may also play a role in the time it takes for the inspection; the more defects there are to document, the longer the inspection will take. Inspection methods are generally the same among all inspectors, however experience and inspector's personal preferences may differ between Inspectors. This is the same for report writing. While Inspectors are provided with common statements to use in their report, they are also given the freedom to narrate or edit comments as they see fit for each inspection. The Inspector cannot predict or find every defect in a structure being inspected. The time frame for an inspection only allows the Inspector to examine areas in a location by location order. If a defect arises in another area of the structure (including the exterior) for which this defect was not present or visible at the time of the inspection, then the Inspector cannot be liable for notifying you of the defect. *For example:* The inspector evaluates the exterior of the home first and finds no defects...but later runs the water at the kitchen sink and the water is not visibly leaking under the kitchen sink, but somehow is leaking through the exterior wall to the exterior, the Inspector will not back-track and re-inspect the exterior and will likely not see this or note the defect.

During the inspection, the water is turned on at all visible and/or accessible fixtures at the structure. In most cases, no water fixtures should be left unattended while turned on. There is no set standard time frame for how long each fixture should be operated. The Inspector will operate the water fixtures as long as is needed to determine if both the hot and/or cold water is operating at the designated fixture. Leaks can only be documented if they are visible at the time of operating the designated fixture. Future leaks cannot be predicted! A home inspector cannot determine if there are plumbing leaks inside walls or ceilings unless visible moisture or explicit signs of moisture are present and visible at the time of the inspection. This inspection does not include confirmation of water conservation devices at any fixture.

Note that this report is a snapshot in time and not a prediction of future conditions. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide. Conditions can change at any time during escrow time periods. You are 100% responsible for verifying all conditions prior to close of escrow.

THIS REPORT IS NON-TRANSFERABLE TO ANOTHER PARTY, NO EXCEPTIONS.

THANK YOU FOR USING ELITE GROUP INSPECTION PROFESSIONALS

INSPECTION AGREEMENT

BY ACCEPTANCE OF OUR INSPECTION REPORT YOU AGREE TO THE TERMS OF THIS AGREEMENT AND THE TERMS AND CONDITIONS OF THE CONTRACT. YOU FURTHER AGREE THAT YOU UNDERSTAND THE LIMITATIONS OF A HOME INSPECTION AND HAVE READ THE DISCLAIMER PAGE OF THIS REPORT.

SCOPE OF THE INSPECTION / REPORT

We will perform a non-invasive visual examination designed to identify material defects in the systems, structures, and components of buildings located on the property to be inspected, as they exist at the time of the inspection. Our inspection will be limited to those specific systems, structures and components that are present and visually accessible. We will only operate components and systems with normal user controls and as conditions permit. Unless we agree otherwise, we will only inspect the primary building, and its associated primary parking structure on the property. Out structures are not included in our inspection: this exclusion encompasses exterior BBQs, appliances, fire pits, fire places, play equipment, ponds or fountains, sheds, workshops, lean-to structures, barns, etc.. We will also provide you with a written report that describes and identifies the inspected systems, structures and components and any visible material defects observed at the time of the inspection. We may amend the report within twenty-four (24) hours after completing the inspection.

RE-INSPECTION: A re-inspection may be scheduled with our office as needed to re-evaluate specific items that may have been repaired since our original inspection or that may have been obstructed and not visible or accessible during the original inspection. The fee for a re-inspection varies upon how many items are to be re-inspected and/or the length of time required to perform the re-inspection. A re-inspection is completed only for the items specified in writing by the buyer or buyer's Agent at the time of the re-inspection. A re-inspection does not include a complete inspection of the entire home or property, however the Inspector may update the inspection report with additional defects observed at the re-inspection that may not have been visible or accessible during the original inspection. It is recommended that you obtain all the necessary building permits, contractor receipts and any warranties provided by the manufacturer/installer/contractor for the repaired or replaced items. Unless we agree otherwise, we will perform the inspection, and issue the report, in accordance with the mandatory parts of the current Standards of Practice (Residential Standards - Four or Less Units) of the International Association of Certified Home Inspectors ("the InterNACHI Standards") and subject to the Definitions, Scope, Limitations, Exceptions and Exclusions in the InterNACHI Standards. Terms in this Agreement have the same meaning as the defined terms in the InterNACHI Standards. The InterNACHI Standards are available from InterNACHI's website: <http://www.nachi.org/>

IF YOU DISCOVER A DEFECT FOR WHICH YOU THINK WE MAY BE LIABLE TO YOU, YOU MUST NOTIFY US AND GIVE US A REASONABLE OPPORTUNITY TO RE-INSPECT THE PROPERTY BEFORE YOU REPAIR THE DEFECT. FAILURE TO FOLLOW THIS PROCESS WILL RESULT IN VOIDING THIS AGREEMENT AND CONTRACT. YOUR NOTICE MUST BE IN WRITING, INCLUDE A SIGNED COPY OF THIS AGREEMENT, AND BE MAILED TO OUR CORPORATE OFFICE:

Elite Group Inspection Professionals/Attn: Inspector Supervisor 9480 Utica Ave Ste 608 Rancho Cucamonga, CA 91730

OUR LIABILITY TO YOU FOR CLAIMS ARISING FROM OUR INSPECTION OR OUR REPORT, WHETHER SOUNDING IN TORT OR CONTRACT, WILL NOT BE MORE THAN THE LESSER OF ACTUAL DAMAGES OR THREE (3) TIMES THE INSPECTION FEE.

TEGPIS (The Elite Group Property Inspection Service, Inc.) AND CLIENT AGREE THAT CLIENT CANNOT FILE A LEGAL ACTION AGAINST TEGPIS OR ITS EMPLOYEES, WHETHER SOUNDING IN TORT OR CONTRACT, MORE THAN ONE YEAR AFTER THE CLIENT DISCOVERS, OR WITH THE EXERCISE OF REASONABLE DILIGENCE SHOULD HAVE DISCOVERED THE BREACH OR MATERIAL DEFECT.

Our report is NOT a warranty of the items inspected. However, The Elite Group may offer you additional warranties through a third party service provider. In all cases, you must contact your home warranty company first for any issues that arise after the date of the original home inspection. Failure to do so may result in voiding your home warranty.

Additional questions or concerns can be addressed through our Customer Service website: <https://eliteinspections.com/explanation-of-limited-guarantee>

Please read the "About Your Inspection" and "Disclaimers" pages prior to filing any online claims as this will help you to determine if your claim is valid and within the scope of the home inspection.

CONFLICT OF INTEREST DISCLOSURE AND STATEMENT OF COMMITMENT

Our goal is to provide valuable and unbiased information that helps consumers make informed decisions. A portion of our business may be based on relationships with other professions- real estate sales professionals, lawyers, lenders, vendors, etc., and our reports sometimes conflict with the business interests of these parties. We do not allow these relationships to compromise the integrity of our service. However, they do enable us to deliver more value to our clients. Our reports are intended to accurately reflect our impartial professional opinion, without exception.

YOU MUST PAY THE INSPECTION FEE AND SIGN THE CONTRACT BEFORE WE CAN DELIVER THE REPORT TO YOU.



OVERVIEW

1. Inspection Package - Directional Marker - Utilities Status - Occupancy - Other Info

Inspection type: **Elite** Home Inspection (Standard Inspection)

Multi-family Residence (multiple units) - Multi-Unit Inspection performed - General comments will be made throughout the report that are not specific to any particular unit and should be considered general conditions for all units, unless otherwise specified by unit number/letter. Specific major defects will be labeled by unit number/letter.

Front door faces South (approximate)

All Utilities are ON for this inspection

Vacant structure - some areas contain staging materials or personal items left behind - these items are not moved and will prevent a complete inspection and limit visible access to some areas (this applies to all areas inside and outside of the structure being inspected).

2. Main Utilities Location

- Main water valve shut off location: North side of structure
- Main gas valve shut off location: East side of structure
- Main electrical panel location: North side of structure

3. Who is present at the inspection?

- Buyer present during inspection
- Buyer's agent present during inspection

4. IMPORTANT NOTES

- This inspection is intended to identify major material defects only. Minor and cosmetic issues are excluded from inspection and report, but may be included in some comments as a courtesy. Small nail holes, drywall nail pops, small cracks, chipped areas, dirty areas and cosmetic blemishes are considered cosmetic in most cases.
- Small cracking may be found throughout the structure, this is normal for California construction and generally caused by settling, earthquake, and wind conditions.

INTERIOR

Interior page will include all bedroom items and the walls, ceilings, floors, windows, and doors of bathrooms, kitchen, and laundry area. "Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion, maintenance, repair, or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair, and/or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted Drywall contractor 909-488-4426, Flooring 626-828-2582, Microbial/Mold Inspection 800-494-8998, Windows/Doors 909-655-5224, Electrical 909-487-5019.

1. Wall Conditions

Observations:

- Some areas not accessible/visible due to access limitations/personal items
- No major visible defects at the time of the inspection
- Walls are worn with cosmetic blemishes - typical for the age







2. Ceiling Conditions

Observations: No major visible defects at the time of the inspection • Ceilings have normal wear for the age of the materials

3. Floor Conditions

Observations:

- Floors are worn with evidence of minor traffic - typical for the age
- Uneven areas throughout the structure - likely the result of foundation settling and ground soil movement - typical for older homes



Uneven areas throughout the structure

4. Window Conditions

Observations:

- Difficult to operate or slide - needs to be serviced
- Older/distressed window(s) - we recommend maintenance/servicing by specialist
- Missing sash/cables - needs to be serviced
- Stuck in position - needs to be serviced
- Cracked glass- needs to be serviced




Older/distressed window(s) - we recommend maintenance/servicing by specialist




Older single pane windows present in areas



Missing sash/cables - needs to be serviced



Cracked glass- needs to be serviced @ 207½



Stuck in position - needs to be serviced

5. Doors

Observations:

- Doors tested and operated at the time of the inspection
- Worn/weathered doors - recommend general maintenance

6. Fireplaces

Masonry

Observations:

- Small cracks/worn areas present at firebox - typical for age
- Recommend fire caulk/sealing any holes/gaps/cracks
- No gas present/visible
- No damper door - typical for age or type of system



No gas present/visible



No damper door - typical for age or type of system




Small cracks/worn areas present at firebox - typical for age

7. Electrical

Observations:

- A representative number of receptacles were tested
- Outlets/switches/fixtures had normal wear for age of the materials
- Ungrounded outlets present - needs to be serviced



8. Stairs & Handrails


Observations:



- Functional at time of inspection
- Normal wear for age during the inspection

9. Closets

Observations:

- No major visible defects observed






10. Smoke Detectors


Observations:

- Smoke and Carbon Monoxide combo unit is present with normal wear



11. Carbon Monoxide Detector

Observations: Carbon Monoxide detector present at the time of the inspection



BATHROOMS

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted plumbing company 714-735-0726. Electrical 909-487-5019

1. Counters

Observations:

- No major visible defects found at the time of the inspection



General view - 207½



General view - 207

2. Cabinets

Observations:


- No major visible defects found at the time of the inspection
- Worn cabinets doors/hardware - typical for the age




3. Sinks

Observations:

- No major visible defects observed at the time of the inspection
- Fixture operated at the time of the inspection



Sink fixture(s) tested and operated



4. Mirrors

Observations:

- Mirror functional at time of inspection
- Normal wear for age of material with no major visible defects

5. Bath Tubs

Observations:

- No major visible defects at the time of the inspection
- Fixture was tested and operating at the time of the inspection
- Bath fixture(s) had normal wear for the age of the materials



Tub fixture(s) tested and operated

6. Showers

Observations:

- No major visible defects found at the time of the inspection
- Fixture was tested and operating at time of inspection
- Shower fixture(s) had normal wear for the age of the materials
- Leak at shower line connection - needs to be serviced



Shower fixture(s) tested and operated



Leak at shower line connection - needs to be serviced @ 207

7. Shower Walls

Observations:

- The shower pan and shower walls are not waterproof tested for leaks. The Home Inspector cannot determine if shower walls or shower pans leak through or behind tile, fiberglass or other solid surface materials. The Inspector cannot see behind walls, floors or ceilings. We strongly recommend that you have all shower pans water tested for leaks. Cracking/missing grout, degraded or missing caulking may lead to leaks and should be immediately addressed in all cases and discoveries.
- Tile and grout present
- Shower walls/ pans are worn - typical for the age - we recommend routine maintenance to maintain water tight seals
- Shower pans are not long-term water tested for leaking - consult the termite report



8. Enclosures / Shower doors

Observations:

- No major visible defects observed at the time of inspection

9. Toilets

Observations:

- Tested and operational at time of inspection via normal fixture controls, flush test performed
- Toilet has normal wear for age at the time of the inspection - no major visible defects



10. Plumbing

Observations:

- The plumbing supply valves are visually inspected only and are not tested for functionality due to the potential for leakage - valves that are not used often will seize or freeze and are likely to leak when operated (opened/closed).
- No major visible defects found at the time of the inspection
- No visible leaks found at the time of the inspection after running water at fixtures



11. Electrical

Observations:

- A representative number of receptacles and switches were tested and found to be operational at time of inspection
- No major visible defects observed at the time of the inspection
- Outlets/switches/fixtures had normal wear for age of the materials



12. GFCIs

Observations:

- None installed recommend upgrade for increased safety @ 207½
- **GFCI** tripped but would not reset - needs to be serviced



GFCI tripped but would not reset - needs to be serviced @ 207

13. Exhaust Fans

Observations:

- Operated at time of inspection
- Worn/older fan - typical wear for age



KITCHEN

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted plumbing company 714-735-0726. Electrical 909-487-5019

1. Counters

Observations:

- Counter is worn and has typical wear for age
- Tile and grout is worn - recommend grout and sealer maintenance



General view - 207



General view - 207½





2. Cabinets

Observations:

- No major visible defects at the time of the inspection
- Worn cabinet doors/hardware - typical for the age
- Stained areas below sink - dry at time of inspection
- Evidence of past moisture in the cabinet under the sink - needs to be serviced





Stained areas below sink - dry at time of inspection




3. Sinks

Observations:

- No major visible defects at the time of the inspection
- Fixture operated at the time of the inspection



Sink fixture(s) tested and operated



4. Garbage Disposals

Observations:

- None installed

5. Plumbing

Observations:

- No major visible defects at the time of the inspection
- No visible leaks found at the time of the inspection after running water at fixtures
- Corrosion at angle stop valve(s) - evidence of slow leaking
- No angle stop valves - typical for older structures - recommend upgrade @ 207



6. Ranges

Observations:

- Gas supplied unit
- No major visible defects at the time of the inspection
- Tested and operational at time of inspection via normal controls
- Range has normal wear for the age of the unit
- Unit not fastened to cabinet/counter - needs to be serviced



Range/stove tested and operated



7. Ovens

Observations:

- Gas supplied unit
- No major visible defects at the time of the inspection
- Tested and operational at time of inspection via normal controls
- Oven has normal wear for the age of unit
- Anti-tip device is not visible/not tested - we recommend that an anti-tip device be installed to prevent a possible tip hazard
- Unit runs on extension cord - may be problematic
- **Not operating - not reaching desired temperatures - gas smell detected when running fixture - needs to be serviced**



Oven tested and operated



Unit runs on extension cord - may be problematic



Oven temperature = 350°+




Not operating - not reaching desired temperatures - gas smell detected when running fixture - needs to be serviced @ 207½


8. Exhaust Vents

Observations:

- **No exhaust vent in kitchen - needs to be serviced - proper ventilation needed**



No exhaust vent in kitchen - needs to be serviced - proper ventilation needed



No exhaust vent in kitchen - needs to be serviced - proper ventilation needed

9. Electrical

Observations:

- A representative number of receptacles and switches were tested and found to be operational at time of inspection
- No major visible defects observed at the time of the inspection
- Outlets/switches/fixtures had normal wear for age of the materials



10. GFCIs

Observations:

- None installed recommend upgrade for increased safety

LAUNDRY AREA

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted plumbing company 714-735-0726. Electrical 909-487-5019

1. Dryer Vent

Observations:

- No major visible defects observed at the time of the inspection
- Visible areas of the vent have normal wear
- No dryer vent installed- needs to be serviced @ 207½




No dryer vent installed- needs to be serviced @ 207½



2. Plumbing

Observations:

- No major visible defects observed at the time of the inspection
- No visible leaks at time of inspection
- Visible fixtures had normal wear for age at the time of the inspection



3. Gas Valve

Observations:

- No major visible defects at the time of the inspection
- Gas valve has normal wear at the time of the inspection



4. Electrical

Observations:

- No major visible defects observed at the time of the inspection
- Outlets/switches/fixtures had normal wear for age of the materials



5. GFCIs

Observations:

- None installed recommend upgrade for increased safety

HEATING/AIR CONDITIONING

Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted HVAC referral, please contact 714-735-0726.

1. Heaters

Type: Single sided wall heater

Observations:

- Worn/older furnace present - unit appears to be nearing the end of its expected useful life
- **Thermostat not operating - unit not tested - needs to be serviced**



Thermostat not operating - unit not tested - needs to be serviced @ 207½ **Thermostat not operating - unit not tested - needs to be serviced @ 207**

2. Thermostats

Observations:

- **Not operating - needs to be serviced**



3. Air Conditioning Compressors

Location: **NO CENTRAL A/C PRESENT**

WATER HEATERS

Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. Please review the manufacturer's specifications for installing water heater vents, condensation drain lines, and gas line requirements, as these can vary by manufacturer and model and not identified by the inspector. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted plumbing referral, please contact 714-735-0726.

1. Water Heaters Condition

Number of gallons: 40 gallons


Location/s: Laundry room

Observations:

- Operated at the time of the inspection - Gas unit
- No major visible defects at the time of the inspection
- Older water heater present - recommend annual seasonal maintenance to extend the life of the unit
- The water heater is visually inspected only, the combustion/pilot doors are not removed for flame or burner condition inspection due to the potential for draft to burn out the pilot flame - the Inspector does not estimate the age and cannot predict the remaining life of the unit.
- It is recommended that water heaters are flushed annually to remove sediment buildup
- **"Sediment knock" in tank noted; may decrease efficiency of the water heater - needs to be serviced**



Water heater tested and operated



Older water heater present - recommend annual seasonal maintenance to extend the life of the unit (9yrs)

2. Venting

Observations:

- No major visible defects found at the time of the inspection



- No major visible defects found at the time of the inspection
- Normal wear for the age of the materials



- **N/A**

- No major visible defects found at the time of the inspection
- Normal wear for the age of the unit
- The inspector visually inspects the TPRV only - this valve is not opened or tested during the inspection



- Temperature was above 120° F at the unit, this a potential scald hazard - needs to be serviced/adjusted



8. Strapping

Observations:

- No major visible defects observed at the time of the inspection
- Standard metal type straps present - normal wear on the day of the inspection

9. Gas Supply Valves and Pipes

Observations:

- No major visible defects found at the time of the inspection
- Gas valve has normal wear for age at the time of inspection



10. Combustion Air

Observations:

- **Combustion air** appears to be adequate at the time of the inspection

11. Platforms/Bases

Observations:

- No catch pan and drain: unit is installed over finished living space - recommend installing pan and drain accordingly



ELECTRICAL/GAS SERVICE

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. Our company is not responsible for any electrical panels that may be subject to recall, including but not limited to Square D panels or other brands. It is the responsibility of the property owner or installer to verify whether the electrical panel is impacted by any recalls. We recommend checking with the manufacturer or relevant authorities for up-to-date recall information. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted Electrician 909-487-5019

1. Main Panel


Location/s: North side of the structure

Observations:

- No major visible defects at the time of the inspection
- Main panel is worn/weathered - typical for age/weather exposure



General view - main panel




No major visible defects at the time of the inspection


2. Panel Wiring

Observations:

- Wiring type: copper
- Wiring method: non-metallic sheathed cable (romex)
- Unable to determine if this panel is properly grounded - recommend further evaluation by a licensed electrician
- Visible wiring was worn/weathered/older - signs of age/wear
- Consider upgrading the electrical services
- **Wiring type: tinned/nickel clad copper - this is an older type of wiring - an upgrade is recommended**
- **Wiring method: Cloth wiring observed at various locations throughout the property - we recommend a licensed electrician for upgrade of all older materials**
- **Wiring method: knob and tube present in areas of the structure - considered obsolete - recommend complete inspection by electrical contractor**



Wiring type: tinned/nickel clad copper - this is an older type of wiring - an upgrade is recommended



Wiring type: tinned/nickel clad copper - this is an older type of wiring - an upgrade is recommended



Wiring method: Cloth wiring observed at various locations throughout the property - we recommend a licensed electrician for upgrade of all older materials



Wiring method: non-metallic sheathed cable (romex)




Wiring method: knob and tube present in areas of the structure - considered obsolete - recommend complete inspection by electrical contractor @ attic


3. Breakers

Observations:

- Breakers have normal for the age of the materials
- ***Breakers are visually inspected only - the inspector does not perform any electrical stress tests on the system to determine if a breaker trips properly (consult an electrician for further evaluation, if this is a concern)***
- **No visible labeling for breakers on panel cover - needs to be serviced**



No visible labeling for breakers on panel cover - needs to be serviced



Breakers have normal for the age of the materials

4. Breaker Amp Capacity

Observations:

- 100 amp - while common for many structures, this may be considered low capacity for today's electrical uses - consider upgrading services




100amp

5. Cable Feeds

Observations:

- Service entrance cap/cables are worn and weathered - typical for the age of the structure



6. Main Gas Valve

Location: ***We recommend the gas supplier be contacted to safety check all fuel gas systems/appliances during the contingency period or at least prior to purchase and occupancy. The Inspector cannot determine if a gas leak is present in any area of the home or underground at any time during the inspection.*** • East side of the structure

Observations:

- Natural gas present
- Valve has normal wear for the age of the materials
- Recommend gas valve wrench be placed near valve for optimal preparedness
- No seismic safety valve present - recommend installation for increased safety



Gas Meter



Gas Valve

7. Gas Pipes and Valves

Observations:

- No major visible defects found at the time of the inspection
- Visible gas pipes are worn/weathered - typical for the age



ATTIC AREA

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted Electrician 909-487-5019, Flooring - 626-828-2582, Insulation- 800-494-8998, Structural- 323-403-4132 &(Need a 5 star Company to refer too), Pest Control- 818-463-0830

1. Access Entries

Observations:

- Inspection method: Inspected from access hole only - access limitations prevented complete entry into the attic - limited inspection
- Multiple access points present
- Access door is dirty with cosmetic blemishes present

2. Structure

Observations:

- **Consult termite report** for all wood areas in the attic
- Conventional framing present with worn/weathered materials - consult the termite report regarding the condition of wood members
- Cracking small at wood members - typical for age
- Visible daylight can be seen in areas - recommend sealing all holes/gaps
- Limited attic inspection - many areas are not accessible to to limited space, lack of proper walk boards, electrical, plumbing, ductwork, etc.
- **No visible roof sheathing at rafters - this is an irregular roofing installation**



3. Insulation

Material type: Loose fill

Approximate depth: 3 to 4 inches - more recommended

Observations:

- Visible insulation is worn/older/dirty - this structure would benefit from new insulation
- Inadequate insulation observed - this structure would benefit from new insulation - recommend servicing
- The inspector does not determine R-value of the insulation
- Insulation generally blocks visible inspection access to framing below level of insulation



4. Ventilation

Observations:

- Existing ventilation appeared to be adequate on the day of the inspection

5. Electrical

Observations:

- Live knob and tube wiring present - this type of wiring is considered old technology and should be upgraded as soon as possible



6. Plumbing

Observations:

- No visible plumbing vents or piping in the attic space - not inspected

GARAGE AND/OR CARPORT

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted; if you need a trusted garage door company- 909-413-4810.

1. Roof Condition

Notes: Roofing area is the same as main structure - see the main roof page

2. Rafters & Ceilings

Observations:

- Exposed wood rafters/joists - consult termite report for all wood
- Worn/stained/deteriorated wood members - needs to be serviced/further evaluated - consult the termite report
- New lumber/patched areas - consult seller for past repairs
- **Deteriorated wood members - needs to be serviced**



Deteriorated wood members - needs to be serviced

3. Main Automotive Doors

Type: Barn door wood

Observations:

- **Deteriorated wood present - needs to be serviced - consult termite report**



Deteriorated wood present - needs to be serviced

4. Exterior Doors


Observations:

- Operated at the time of inspection
- Worn/weathered door - typical for age, dented areas

5. Walls

Observations:

- **Consult termite report for any wood areas in garage**
- Walls are in a worn/older condition - we recommend maintenance/patching as needed
- Consult termite report for all exposed wood members in the garage
- **Worn/stained/distressed wood members - older materials**



Worn/stained/distressed wood members - older materials

6. Anchor Bolts

Observations:

- **None visible** - typical for estimated age - recommend upgrade



7. Slab

Observations:

- Cracked/soft areas present - signs of ground movement and settling - recommend servicing




Cracked/soft areas present - signs of ground movement and settling - recommend servicing

8. Electrical

Observations:

- A representative number of receptacles and switches were tested and found to be operational at time of inspection
- No major visible defects at the time of the inspection
- Ungrounded outlets present - recommend licensed electrician for upgrade



Ungrounded outlets present - recommend licensed electrician for upgrade

EXTERIOR AREAS


"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted.

1. Siding

Constructed of: Wood

Observations:

- Consult termite report for all exterior wood
- Older siding present - materials appear to be near the end of their useful
- **Worn/older materials - we recommend siding maintenance**



2. Eaves & Fascia

Observations:

- Consult termite report for all wood areas at the structure
- Note: exposed exterior wood will require seasonal maintenance and paint
- Wood members are weathered/peeling/cracking - indicative of age/weather exposure
- **Deteriorated wood - recommend evaluation by termite inspector**



Deteriorated wood - recommend evaluation by termite inspector



3. Exterior Paint

Observations:

- **Weathered and worn more than normal - needs to be serviced**
- *Paint is recommended to help maintain and seal the exterior areas of the structure*
- *Exterior paint will require maintenance every 3-5 years*
- *Some areas not accessible or visible due to vegetation/personal items*

FOUNDATION

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required before the close of escrow. We recommend further evaluation by a licensed foundation contractor for all river rock, block, or brick foundations, any area marked in **red**, or any foundation constructed prior to 1964. If you're interested in having your foundation assessed by a local expert, you can find more information and connect with professionals. [Click here to open the form](#) or call 323-553-4174 (for Raised Foundation) or 323-403-4132 (for Slab Foundations)

1. Access Panels

Observations:

- Access entry has normal wear at the time of the inspection with no major visible defects
- Debris/soil obstructing access in areas - confined areas in crawl space - very limited access



Debris/soil obstructing access in areas - confined areas in crawl space - very limited access



Debris/soil obstructing access in areas - confined areas in crawl space - very limited access



2. Foundation Walls

Observations:

- No major visible defects found at the time of the inspection
- Constructed of: concrete
- Visible foundation wall areas have normal wear for the age of the structure on the day of the inspection





3. Sub Flooring


Observations:

- Consult the termite report for all wood areas in the crawl space
- Wood is worn and stained in areas where visible
- Deteriorated wood observed - consult the termite report for all wood deterioration/moisture damage under structure
- Structure inspection limited due to access hindrances such as insulation/ductwork/pipes/wires - some areas of the sub floor are not visible or inspected
- Some areas of the sub floor are not visible or inspected
- **Heavily deteriorated joist in areas - needs to be serviced/further evaluated by a specialist**



Heavily deteriorated joist in areas - needs to be serviced/further evaluated by a specialist


Heavily deteriorated joist in areas - needs to be serviced/further evaluated by a specialist



4. Posts and Girders

Observations:

- Wood post are worn/older - recommend upgrade
- Irregularly shimmed posts - needs to be serviced
- **Missing brackets at attachment points - recommend upgrade**
- **Posts in contact with soil - needs to be serviced - consult the termite report**
- **Cracked/sagging girder - needs to be serviced**



Cracked/sagging girder - needs to be serviced



Cracked/sagging girder - needs to be serviced



Missing brackets at attachment points - recommend upgrade



Posts in contact with soil - needs to be serviced - consult the termite report



Posts in contact with soil - needs to be serviced - consult the termite report



Irregularly shimmed posts - needs to be serviced



Wood post are worn/older - recommend upgrade

5. Sill Plate

Observations:

- Worn/stained/cracked materials - typical for the age of the structure

6. Anchor Bolts

Observations:

- Anchor bolts present and have normal wear for age with no major visible defects



7. Ventilation

Observations:

- Existing ventilation appeared to be adequate on the day of the inspection

8. Plumbing

Observations:

- Distribution line appears to have been upgraded - **check permits** to ensure that proper workmanship was done in accordance with local building codes
- Copper piping present with normal wear - no major visible defects at the time of the inspection
- Drain line not visible/accessible



GROUNDS

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion; maintenance, repair or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair and / or replacement by an appropriate licensed contractor may be required. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. Please consult a licensed professional as noted.

1. Driveway/Walkway

Observations: Worn with common cracks/chips - typical for age of material • Small localized water ponding may occur in areas - area drains may be needed

2. Exterior Electrical

Observations:

- No major visible defects at the time of the inspection
- Accessible lights/switches/outlets were tested on the day of the inspection
- Exterior electrical is in a worn/older condition - recommend routine maintenance to maintain weathertight seals



Exterior light(s) tested and operated

3. GFCIs

Observations:

- No GFCI present/visible - installation of GFCI outlet recommended to prevent fires and shock - needs to be serviced

4. Exterior Plumbing and Faucets

Observations:

- Exterior plumbing is present and not original to the structure - check all installation permits to ensure installation to building code
- Exterior plumbing tested and operated at the time of the inspection
- Exterior plumbing was worn/weathered - typical for the age
- Bibb(s) not functional at one or more locations - needs to be serviced



Hose bibb(s) tested and operated



Bibb(s) not functional at one or more locations - needs to be serviced (**galvanized**)



Exterior plumbing is present and not original to the structure - check all installation permits to ensure installation to building code




5. Main Water Valve

Type of plumbing: Copper • Copper piping is not original to the structure - check all permits to ensure piping was installed to city/county plumbing codes

Observations:

- Location: north side
- No visible leaking found at the main valve area at the time of the inspection
- Main valve appears to have normal wear at the time of inspection



Copper piping present at main water valve

6. Water Pressure

Observations:


- Recommended water pressure is between 55 to 80 pounds per square inch (psi)
- Water Pressure can fluctuate depending upon time of day and municipal service adjustments
- Approximate pounds per square inch: 60



7. Pressure Regulator

Observations:

- None visible but we recommend adding pressure regulator to allow adjustments to water pressure



8. Fencing and Walls

Observations:

- No major visible defects observed at the time of the inspection
- Fencing/walls have normal wear for the age of the materials



9. Gates

Observations:

- Gate(s) locked - not tested

10. Grading

Observations:

- Grading improperly sloped in areas - localized water ponding may occur
- Small localized water ponding may occur in areas - monitor these areas as drains may be needed
- No drains visible at the property at the time of the inspection, drains are recommended to divert water away from structure

ROOF

"Needs to be serviced" and/or "recommend servicing" is a common phrase used throughout this report and means, in the Inspector's opinion, maintenance, repair, or upgrade is needed. Further evaluation of all items labeled with "needs to be serviced" is highly advised; general maintenance, repair, and/or replacement by an appropriate licensed contractor may be required. The inspector cannot determine if a roof (or any part of the roof system) leaks at any time or under any weather conditions; no water or hose testing is performed during this inspection. Roof underlayment cannot be inspected, and its condition cannot be determined with this inspection. Water intrusion and moisture staining are not always visible during the inspection and can appear after rainfall. If there are concerns about possible roof leaks, the condition of underlayment, or determining remaining roof life, please contact a licensed roofer to perform an additional inspection. If any area of this section is marked in **red**, we recommend further evaluation prior to the close of escrow. If you are in need of an additional roofing consultation with a licensed roofer, please call our office. To schedule a roofing consultation with a licensed roofer, please call our office at 800-494-8998. This applies to all roof areas evaluated during this inspection. Remaining roof life can only be determined by a licensed roofer.

1. Condition

Information: Inspection method - roof was walked • **Limited inspection - some areas are not visible due to height/angle - recommend roofer to evaluate as needed**

Constructed of: Asphalt shingles

Observations:

- No major visible defects found at the time of the inspection
- Visible materials show signs of normal wear for the age of the materials - we recommend continued seasonal maintenance to extend the life of the roof






2. Flashings

Observations:

- No major visible defects found at the time of the inspection
- Flashing has normal wear for the age of the materials



3. Gutters and Down Spouts

Observations:

- Partial gutter systems in areas – recommend gutters on all feasible sides of structure to help divert water away from the structure
- Bent/dented gutter areas - recommend maintenance and repair as needed



4. Vents and Vent Caps

Observations:

- No major visible defects found at the time of the inspection
- Normal wear at the time of the inspection



5. Chimneys

Observations:

- Couldn't fully access - limited visual inspection
- No major visible defects found at the time of the inspection
- Chimney is worn/weathered – typical for the age



6. Spark Arrestors

Observations:

- No spark arrestor/rain cap present - recommend installation



SEWER CAMERA INSPECTION

1. Conditions of Sewer Line

Report Details:

Drain line materials (sometimes difficult to tell with older pipes): Cast Iron & Clay

No workable clean out present - sewer camera inspection was performed through an available plumbing roof vent (this limits access and distance, limited inspection)

The sewer camera was unable to reach the main city connection due to issues with the piping design or layout of the sewer line

Sewer line is in a worn/older condition and will likely need a future upgrade - consult a plumber for further evaluation and possible upgrade costs

***Please follow the secure link below to view your sewer inspection video;

https://youtu.be/VzylweNm_9o?is=IVaH9oY2a5wAs8MC

Debris obstructing drain line in areas - needs to be serviced/further evaluated @ 69ft marker

Major offset - separation gap observed @ 73ft marker - needs to be serviced/further evaluated



**PLEASE READ THIS GENERAL INFORMATION**

The purpose of a sewer scope inspection is to determine the condition of the property's sewer line from the exit of the home to the city main and to determine if the system is functioning as designed. The inspection does not include drain lines which connect to the sewer line, depending on sewer line access location, may or may not include the sewer line under the structure. (no refunds will be given if the main is not reached).

A standard sewer scope inspection for a single-family residence takes approximately 30 minutes to one hour to complete (time may vary and is based on accessibility to the sewer cleanout location). Lack of a proper cleanout access WILL prevent a complete inspection. Some areas may be accessible from a roof plumbing vent; however, these inspections are often VERY limited and the camera may not be able to negotiate some turns within the sewer line piping.

Our Inspector/Technician will insert a mini video camera into the sewer line through the sewer cleanout (or sometimes a roof plumbing vent pipe). The cleanout may be located in the basement, crawlspace, garage or outside the structure - front, sides or rear. If no obstructions are encountered, we will inspect from the cleanout to the city main (if the main is reachable with the camera length limitations). If problems with the line are found, we will provide you with an approximate distance to the trouble area from the cleanout/camera entrance point. We advise you to consult with a plumber for additional fees associated with locating the actual pinpoint location of a problem.

Common sewer line problems are root intrusion, sewer sludge, pipe offsets, standing water, cracks, clogging and pipe separation. A functioning sewer line may have problems that do not currently affect the performance of the line; however, these problems may cause a future sewer backup leading to an unexpected emergency line repair or replacement. Roots may infiltrate sewer lines at rates of 1 to 3 inches per day during certain seasons, potentially extending several feet annually, and can significantly impair the functionality of the sewer system. NOTE: This inspection cannot determine if a sewer line leaks.

When the inspection is complete, if present, you will be verbally informed as to condition of the sewer line based on your Inspector's/Technician's opinion of what he viewed at that time, this verbal information may change upon the technicians review of the camera video prior to filing the final report, so please read your final report AND watch the full video for full disclosure. Your Inspector/Technician will send out a final report within 24 from the time of the original inspection (if you do not receive your report, you are expected to contact us by phone at 800.494.8998 so that we may send it to you again). Still photographs and video will be included in your final report. Upon receiving the report, You ARE expected to view the report, watch the

GENERAL INFORMATION CONTINUED

ENTIRE sewer line video and contact your Inspector with any questions, PRIOR to the release of contingencies. If any problems are found in the sewer line, we recommend that you contact a licensed plumber immediately for further evaluation or repair. Further evaluation may uncover additional defects.

Disclaimer: This is not a pass or fail inspection. This inspection does not cover plumbing codes or other building code violations. The Inspector/Technician cannot predict future problems or issues with the drainage system. If you view something in the video that you feel the inspector did not properly disclose on the written report, you ARE expected to contact your Inspector to discuss the condition and have the Inspector update the report as needed. Conditions can and often do change after the inspection; root intrusion, breakage, cracks, etc. can occur at any time without any previous signs during the inspection. The Inspector/Technician or The Elite Group are not responsible for damage found or damage occurring during the inspection. The hiring party is expected to have proper insurances and/or approvals for this inspection by the existing home owner. We do not provide pricing for any repairs.

A sewer camera inspection is intended to reduce risk, however, cannot eliminate all risk. The Client acknowledges that Inspector will not observe every square inch of the sewer system, and that Inspector could fail to see or note a defect, and that defects may exist that cannot be detected by visual inspection only. The Client agrees that the inspection and report in no way lessen the risk or likelihood of repairs or replacements being needed at any time in the future. The Client understands that in order for the Inspector to provide this service at a lower price than a licensed plumber, location devices will not be used to mark locations, technicians will not determine directions/schematic of any underground drain lines.

Sewer scope video recordings will be retained for a period of ninety (90) calendar days from the date of inspection.



Glossary

Term	Definition
Check permits	Home Inspectors cannot determine modification or alterations dates within any structure. The Home Inspector cannot determine building code violations. You are advised to check with the local city or county building and safety office regarding any planned or paid for construction/alterations permits to ensure that any alterations made to the structure were installed and or built to the proper building code standards for the date of the alteration. You are further advised to consult with your Realtor and the Seller/disclosures to understand the details of any and all alterations to the structure and/or contractor warranties that may apply to the alterations.
Combustion Air	The air flow openings designed to bring fresh outside air to the furnace and/or hot water heater or other appliances to be used in the combustion of fuels and the process of venting combustion gases. Normally, two separate supplies of air are brought in: one high and one low.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.
Galvanized	Although galvanized pipes have a general life expectancy of 50 years, their lifespan depends on many factors, from the frequency of use to the amount of water pressure. As such, they might come in need of replacement sooner or later than expected. Defects in galvanized pipes can manifest in multiple ways. The mounting build-up of mineral deposits resulting from corrosion can obstruct water pressure. Low water pressure around the house is usually a sign of a massive build-up of mineral deposits in galvanized pipes. Besides obstructing water pressure, the mineral build-up can also contaminate the water. They can give rise to discoloration in the water. Sometimes, discolored water from rusty galvanized pipes can leave visible brown stains on a porcelain sink. And as the corrosion eats deeper into the pipes, it weakens their integrity, inducing leakages across them. If any part of the galvanized pipes in an old house is leaking, then you should see further evaluation by a licensed plumber for other leakage spots that could break forth owing to years of gradual corrosion.
N/A	Not accessible, not inspected
consult termite report	Recommend evaluation by a licensed termite inspector. Our Termite vendor 562-573-1120.



DISCLAIMERS

Asbestos: The inspector is not licensed by the EPA and cannot determine, report on or test if asbestos materials exist in any area throughout the structure. Any structure built prior to 1978 may contain asbestos in one or multiple building materials used during that era of construction. If you have concerns about possible asbestos, it is solely up to you to arrange for asbestos testing by an appropriate licensed contractor. The Elite Group Property Inspections will not engage in any claims regarding asbestos.

Interior: Limited inspection on all occupied/staged structures. Personal property, furniture, moving boxes or other items are not moved and will prevent a complete inspection (this applies to all areas inside and outside of the structure being inspected). We recommend checking for permits on all additional construction or alterations including, but not limited to: window replacements, patio roofs, out structures, garage and attic conversions, roof alterations, etc. performed on the property after original construction. If multiple people are present at or arrive during this inspection and enter areas or operate appliances or fixtures after they have already been inspected or reported on by the home inspector; the home inspector is not responsible for the condition of these items or areas after they are inspected; the home inspector does not go back and re-inspect the items/areas during this limited time inspection. The Inspector cannot determine if past or present hidden pet damage exists in any part of the structure. The inspector is not a code violation inspector and will not report on building code requirements in any way. Built-in central vacuum systems are not inspected. Interior window shutters/blinds/coverings are not tested or inspected as part of this home inspection (this includes all windows at the structure). Tint/film over windows is not inspected and often is bubbled/loose/peeling/scratched - tint/film (if present) can prevent an accurate inspection of the window glass areas. Only accessible windows and doors are inspected, personal items are not moved to access or test all doors and windows. Broken double pane seals cannot be determined with this inspection, dirty windows can hide signs of condensation between panes. Vertical operating windows are known to have sash cable/spring problems, although the problem may not exist at the time of the inspection, we recommend that you check them often and repair these windows upon discovery of any sash cable or spring problems. Only the visible and accessible switches/outlets are testing during this inspection, personal items are not moved to access any outlets/switches behind them. Fireplace is visually inspected only, the fireplace is not lit to test flame color or condition. The internal cavity of the fireplace is not inspected. It is recommended that you have an internal inspection of the chimney and/or a Gas Company evaluation of the fireplace beyond the scope of this inspection. Ceiling fan mounts cannot be checked by the inspector. Smoke and carbon monoxide detectors that are out of reach are not tested for functionality, all battery operated smoke detectors should be within reach for testing and maintenance. We recommend any mold or moisture damaged areas noted in the report be further evaluated for cause and correction by the appropriate licensed contractor.

Bathrooms: Bathtub and sink overflow drains and spa tub jet hoses are not inspected and leaks in these areas cannot be detected with this inspection. Shower pans are not leak tested and cannot be determined if properly water-proofed by the inspector, consult the termite report for any shower pan tests. Exterior or interior access panels are only inspected if readily accessible and operable (not sealed or painted or screwed shut), second story access panels are not opened. The home inspector cannot determine if shower pans or tubs are properly pitched for drainage. We recommend upgrading all electrical outlets to GFCI protection within 6 feet of all potential wet locations, however this may not be a requirement for the sale of a home based on the age of the home (this also applies to kitchen sinks, wet bar sinks and laundry sinks).

Kitchen: Appliances receive a limited inspection for basic functionality only, additional features are not tested. Appliances are NOT disassembled to evaluate the internal working parts of each appliance. The inspection cannot determine how well the dishwasher cleans the dishes. Disposal blades are not inspected. It cannot be determine how well the oven, range/cook-top or microwave cook food. Age, remaining life, BTU's, CFM's and other forms of efficiency or effectiveness are not determined with this inspection. Water purifying systems, instant hot systems and water softeners are not inspected. Non built-in appliances and built-in refrigerators are excluded from this report.

Laundry: Supply valves, laundry drain, gas valve and dryer vent cannot be tested whether a washing machine is present or not. Washer and dryer units are not inspected or turned on for testing during this inspection and are excluded from this report. Washer and dryers are not moved to inspect the walls/floors/other components behind them. Water supply valves that are left in the on position for a long period of time tend to leak when turned off or do not shut off completely. Drains are not pressure tested.

Attic: The inspector cannot determine, report on or test if asbestos materials exist in any area throughout the structure. When attic insulation is covering ceiling joists, we cannot completely inspect some areas due to inspector safety concerns. Most attics are not completely accessible due to limited space. Attic insulation and limited space will prevent the inspector from performing a complete inspection of the attic area, not all areas are accessible and will be determined at the inspector's discretion. The Inspector does not determine the R-value of insulation present or the efficiency or effectiveness of HVAC duct layout or design. Attic insulation is not touched, moved or otherwise disturbed during the inspection. Temperature sensors and fans for attic exhaust systems are not tested. Rodents: If there is visible evidence of rodents or other pests, it will be noted as such. Most rodent/pest infestation exists under attic insulation, in walls or in areas not visible to the inspector and cannot be identified with this inspection. It's recommended a pest inspection be performed beyond the scope of a home inspection whether or not evidence exists.

Garage: The garage is often the location where most storage occurs and receives a limited inspection when items are present. Personal items or other materials/possessions are not moved in any way to provide access to areas for inspection - areas of rafters, ceilings, firewall(s) or other walls should not be considered fully inspected if personal items or storage is present - defects may be present behind these items and not visible to the inspector at the time of inspection. Doors, windows, cabinets, DISCLAIMERS CONTINUED

counters, closets, slab areas, electrical areas, ventilation, plumbing areas or soffit(s) not fully accessible are not inspected, tested or evaluated. Firewall: fire rating labels are often not visible on finished drywall and cannot be determined with this inspection. Garage doors, hardware, openers and associated safety devices can only be inspected if these areas are clear of stored items and can be safely operated without disturbing other items in the garage. Garage doors, hardware and openers require periodic maintenance and servicing. Remote controls for openers are not tested. Door opener activator button should be minimum 54-inches above floor for safety.

Pressure sensors/systems are generally not tested due to the risk of damage if they are not properly operating - we recommend having a general service completed prior to regular use. We recommend checking permits for any converted garage areas or additional walls/ceilings or other alterations made to the garage.

Heating & Air Conditioning: This report does not indicate if the heater is on recall, a follow up with RecallChek.com is recommended. Electronic or Ultra violet air filters are not inspected. Inspector cannot determine if there is a crack in the firebox or if carbon monoxide is leaking in any part of the system. Not all registers can be tested for pressure flow, due to location, condition and operation of the heating & air conditioning system. Adjustable registers that are closed are not opened by the Inspector. Missing manufacturer labels prevent RecallChek (this is true for all appliances/systems at the structure). Age, remaining life, size or efficiency cannot be determined by the Inspector. The air conditioning system freon or other refrigerant levels are not checked or determined if leaking by the Inspector. Heaters, coil boxes, condensers and air compressors are NOT disassembled to evaluate the internal working parts. This inspection does not determine if the evaporator coil BTU size is the same as condensing unit size or any other mechanical efficiency. Radiant heat is not inspected.

Water Heater: The water heater is visually inspected only, the combustion/pilot doors are not removed for flame or burner condition inspection due to the potential for draft to burn out the pilot flame. Circulation pumps, TPR Valves and pressure tanks cannot be tested with inspection. Solar water heaters are not inspected. Tankless units that are not original to the structure should be further evaluated by a qualified tankless technician as there are many aspects that are beyond of the scope of a general home inspection. Age, remaining life, size or efficiency cannot be determined by the Inspector. Gas lines are not measured or sized for water heater needs. The Inspector cannot light the pilot flame on the water heater or any other appliance where a pilot flame is not already on.

Roof: The inspector cannot determine if a roof (or any part of the roof system) leaks at any time or under any weather conditions, no water or hose testing is performed during this inspection. If there are concerns or signs of possible roof leaks, please contact a licensed roofer to perform an additional inspection. Remaining roof life can only be determined by a licensed roofer. This applies to all roof areas evaluated during this inspection. Tile roofs, metal roofs or roof areas not accessible with a 12-foot ladder will receive a limited inspection from the ground or eaves only. Tile, metal or other materials that can be damaged will not be walked on by the Inspector. Chimney cavities are excluded from this inspection, recommend an internal chimney inspection be performed beyond the scope of the home inspection. Solar panels and tube globes are excluded from this report. Solar panels will prevent inspection of roof areas beneath them.

Electrical/Gas: Electrical panels are visually inspected only, the inspector does not perform a load calculation to determine service capacity adequacy. Some wire types cannot be determined due to wire casings cover wires entering the breakers. Panels with excess wiring are not completely visible due to amount of wires inside panel. Breakers are visually inspected only - the inspector does not perform any electrical stress tests on the system to determine if a breaker trips properly - including AFCI and GFCI breakers (consult an electrician for further evaluation, if this is a concern). Electrical and gas fires due to poor installation of wiring and faulty gas pipes cannot be determined by the inspector. Only accessible GFCIs with test and reset buttons are tested, the inspector does not determine which GFCI outlets may be linked to other areas of the structure. Ungrounded outlets may be present in older structures (pre-1965) even if the main or sub panels have been upgraded. The inspector cannot determine if all wiring has been updated. Expect to find ungrounded outlets in older homes (pre-1965) - this is not a defect. We recommend the gas supplier be contacted to safety check all fuel gas systems/appliances prior to purchase and occupancy. The Inspector cannot determine if a gas leak is present in any area of the home or underground at any time during the inspection. Carbon monoxide poisoning cannot be detected with this inspection, including all gas and propane systems interior and exterior of the structure. Gas supply valves are not turned or operated during this inspection. The internal condition of gas appliance ventilation exhaust pipes cannot be detected. Pilot lights and fire places are not lit by the inspector at any time, for any reason. It is the responsibility of the client to ensure that the main gas and electrical systems are on prior to the inspection. The requirement of gas line sediment traps is not determined by the inspector.

Exterior Areas: For all wood areas or damaged wooden areas and moisture problems (mold/mildew), consult the termite inspection report. See interior section of the report for additional window and door information. In no way, shape or form can the inspector determine if the exterior of the home is water tight or is built to prevent moisture intrusion, no hose or water testing is performed at this inspection. Stucco and siding require periodic seasonal maintenance, consult an exterior finish contractor for maintenance tips/schedules/suggestions. Fire pits, exterior fireplaces and exterior BBQ's are excluded from this inspection. We recommend adding anti-siphon/backflow preventers (if not already present) on all exterior hose bibs for optimum potable water protection. Property boundary lines and encroachment determinations are beyond the scope of a home inspection and are not inspected or included in this report - Consult with another qualified professional as needed for evaluation if concerns exist in this area. Zero lot lines prevent a complete inspection of areas on other properties. Common areas controlled by Home Owner's Associations are not included in this inspection. Areas not visible or accessible due to height/angle/vegetation/other forms of limited access are not included in this inspection. Inspector does not use specialized instruments to detect moisture, if any, under stucco or siding surfaces.

Grounds: This inspection cannot determine if patio and porch roofs, balconies or patio enclosures are water tight, no water/hose

testing is performed. The Inspector does not perform any stress or destructive testing of the electrical system; Yard area electrical that is not readily visible and accessible may not be seen or inspected; Low voltage lighting/electrical systems, motion detectors, intercom, video/audio/security systems and electric outdoor heating systems are not inspected. Generally, it is typical for older homes not to have exterior outlets or switches, this is not a defect. Sprinklers on timers are not inspected, consult DISCLAIMERS CONTINUED

seller/HOA. Above ground pools, ponds, fountains, waterfalls, birdbaths, and associated equipment or pumps used for these items, are excluded from this report. Steep hillsides and inaccessible areas on the grounds are excluded from this report. It is highly recommend that all structures built on hillsides and slopes have a geological inspection performed to determine if the hillside/grading is stable.

This inspection cannot determine ground movement or drainage issues, the addition of drains may be needed in areas. Fences, walls or gates are not evaluated for security or design. The Inspector cannot determine if planter areas are leaking into the structure, consult seller disclosures or obtain further evaluation of these areas for any moisture intrusion issues.

Foundation: Sump pumps, septic tanks and sewer drain pipes from structure to street are excluded from this inspection. The Inspector does not perform calculations to determine exact square-feet of ventilation required at time of construction (this is also true for attic spaces). Some areas of a raised foundation may not be accessible due to limited space, plumbing piping, duct work obstructions, insulation, soil levels and stem walls. The inspector will not traverse any area deemed unsafe or where damage may be caused as a result, this is up to the sole discretion of the Inspector (this is also true for attic spaces). It is not always possible for the inspector to view every side/angle/connection of all plumbing pipes due to plumbing design/layout/approach angle/etc. Underground plumbing/pipes cannot be visually inspected. Pressure testing is not performed during this limited inspection. Drain scope inspections are recommended whether a defect is detected or not. Slab foundations are often covered and not visible; therefore the inspection is limited. Slab foundation leaks cannot be determined by the home inspector.

Pool: Solar panels/heating systems are excluded from report. Valves that are not labeled for the pool and/or spa jets are excluded from this report and may prevent proper testing and inspection. Underground plumbing cannot be inspected. Automatic pool fill float valves and electronic chlorine dispensers are excluded from this report. Ultraviolet light and/or salt chlorine generator type water treatment systems not included in this inspection. Water chemistry is not tested. Control panels/fixtures on the side of the pool or spa and any remote controls are not included in this inspection. Portable spas have a limited inspection - no internal parts are inspected. The inspector cannot determine if a pool or spa leaks. The inspector cannot determine the remaining life of any of the pool equipment. Safety pressure relief valves (if present) are not operated and are excluded from inspection; an internal evaluation of the heater parts is beyond the scope of this inspection. It is the buyer's full responsibility to ensure the pool area is in full compliance with the safety laws and codes. If there is no self containing fence around the pool, all doors from the structure leading to the pool and spa must be equipped with safety alarms and secondary latches above the reach of children. All gates leading to the pool must self close and be equipped with a latch five feet or higher from the ground. The fencing in all cases must be five feet tall.

Plumbing: Plumbing supply valves are visually inspected only and are not tested for functionality due to the potential for leakage - valves that are not used often will seize or freeze and are likely to leak when operated (opened/closed). Corrosion or rust is often a sign of slow leaking and should be further evaluated by a plumber if detected in the inspection or photos. If galvanized or cast iron plumbing is present in any part of the structure it is recommended that plumber further evaluate the plumbing system due to the age of the materials. Underground piping is not visible to the inspector, therefore cannot be evaluated by the inspector. Slab foundation leaks cannot be determined by the home inspector. The "plumbing type" section of the report includes a percentage approximation of the plumbing type, it is not a guarantee of the plumbing type in all areas. The inspector cannot see plumbing type or pinhole leaks inside walls, floors, slabs or other areas that may be covered. Leaks can occur after the inspection and are not the responsibility of the Inspector. Existing leaks, hidden leaks, or other leaks that occur from normal testing/inspection and subsequent damage from plumbing leaks are not the responsibility of the Inspector. This inspection also does not determine or identify geographic areas that are prone to defective materials or pinhole leaking issues. Consult seller's disclosures and qualified professionals/contractors if concerns exist in this area. Septic tanks, wells, pumps and associated equipment, water supply quantity and quality are not included in this inspection.

***Contractor References:** This report may contain a contractor reference and contractor contact information. Choosing a contractor is done solely at the risk of the client. The Elite Group cannot control the events that take place between contractors and customers and therefore cannot be held liable for any problems that may occur. References to contractors, their products and services, are provided "as is" without warranty of any kind, either expressed or implied. In no event shall The Elite Group be held liable for any incidental, indirect or consequential damages of any kind resulting from the information provided by each company and any business conducted as a result of such information. It is highly recommended that you check with your local licensing or business board for up to date and accurate information. When you contact a contractor you should:

1. Ask for and contact at least two customer references.
2. Find out how long they have worked in your area (familiarity with local building codes is important).
3. Ask if they are bonded (insured for damages and injuries on the job) Get a signed estimate for all parts and labor/installation.
4. You may wish to contact more than one contractor to ensure you are getting the best service and materials for your money.

This disclaimer applies to all references found on any and all of our report pages

SEE CONTRACT FOR ADDITIONAL INFORMATION AND DESCRIPTION OF ITEMS