



The Original DOBRICH & SONS SEPTIC SERVICE

P.O. BOX 1681 MAGALIA, CA. 95954

INVOICE

(530)-873-9901

JOB SITE: 14279 Carnegie Road

CITY Magalia	DATE ORDERED 1/21/2026	SCHEDULE DATE 1/22/2026	PUMP DATE
-----------------	---------------------------	----------------------------	-----------

ORDERED BY: Kerri Clark klclark530@yahoo.com 530-315-7470	REPORT TO:
--	------------

ESCROW COMPANY :	OFFICER :	ESCROW#
------------------	-----------	---------

SPECIAL NOTES:
 Septic inspection of a 1000 gallon concrete septic tank that's in fair condition. The septic tank is 12" deep. There was 0" of Scum and 10" of sludge in the inlet side of the tank. The inlet and the outlet tees are intact. The effluent in the septic tank is at normal operating level. The absorption field took the water that was introduced at the time of the hydraulic load test. The tank does not need pumped at this time.

ORDER	DONE	DESCRIPTION	PRICE
X	X	INSPECTION	\$150.00
		INLET REPAIR	
		OUTLET REPAIR	
		EXTRA LABOR	
		PUMP NEEDED	
		PUMP ORDERED	
		"Due in 5 days. 1.5% interest will be added for each week an invoice is late unless escrow is pending"	

***This hydraulic load test of the absorption field does not constitute a full hydraulic load test of the dispersal field. A full hydraulic load test can only be effectively done with more water and when the system has been in continual use.

SUBTOTAL	\$150.00
AMOUNT PAID	
AMOUNT OWED	
CHECK#	

***NOTE: IF YOU PAY WITH A CREDIT CARD OR DEBIT CARD:
 There will be a 4% mandatory processing charge added to the total of the Invoice.

WE ARE IN BUSINESS BECAUSE OF YOU

THANK YOU