



The Original DOBRICH & SONS SEPTIC SERVICE

P.O. BOX 1681 MAGALIA, CA. 95954

(530)-873-9901

INVOICE

JOB SITE: 731 North Cloud

CITY Paradise	DATE ORDERED 12/19/2024	SCHEDULE DATE 12/23/2024	PUMP DATE
------------------	----------------------------	-----------------------------	-----------

ORDERED BY:	REPORT TO:
Maurine Johnson	
maurinejo@aol.com	
530-877-1791	

ESCROW COMPANY :	OFFICER:	ESCROW#
------------------	----------	---------

SPECIAL NOTES:

Septic inspection of a 1000 gallon concrete tank that's in poor condition, the tank top is broken. The tank was 4" deep. There was 0" of scum and 9" of sludge in the inlet side of the tank. The inlet and the outlet tees are intact. The effluent level in the tank is at normal operating level. The absorption field is operating as it should. **The tank top is in 2 pieces, it is pulled apart and broken.**

ORDER	DONE	DESCRIPTION	PRICE
X	X	INSPECTION	\$200.00
		INLET REPAIR	
		OUTLET REPAIR	
		EXTRA LABOR	
		PUMP NEEDED	
		PUMP ORDERED	
		"Due in 5 days. 1.5% interest will be added for each week an invoice is late"	

This hydraulic load test of the absorption field does not constitute a full hydraulic load test of the dispersal field. A full hydraulic load test can only be effectively done with more water and when the system has been in continual use.

SUBTOTAL	\$200.00
AMOUNT PAID	
AMOUNT OWED	
CHECK#	

WE ARE IN BUSINESS BECAUSE OF YOU
THANK YOU

