

State of California
Well Completion Report
 Form DWR 188 Submitted 2/8/2022
 WCR2022-001829

Owner's Well Number _____ Date Work Began 01/31/2022 Date Work Ended 02/02/2022
 Local Permit Agency County of Riverside Department of Environmental Health
 Secondary Permit Agency _____ Permit Number WP0030367 Permit Date _____

Well Owner (must remain confidential pursuant to Water Code 13752)	Planned Use and Activity
Name <u>[REDACTED]</u>	Activity <u>New Well</u>
Mailing Address <u>[REDACTED]</u>	Planned Use <u>Water Supply Domestic</u>
City <u>Temecula</u> State <u>Ca</u> Zip <u>92592</u>	

Well Location					
Address <u>0 Lakeshore Drive</u>			APN <u>584-030-022</u>		
City <u>Aguanga</u>	Zip <u>92536</u>	County <u>Riverside</u>	Township <u>07 S</u>		
Latitude <u>33</u> <u>32</u> <u>15.5148</u> N	Longitude <u>-116</u> <u>48</u> <u>17.4635</u> W	Range <u>02 E</u>			
Deg. Min. Sec.	Deg. Min. Sec.	Section <u>29</u>			
Dec. Lat. <u>33.537643</u>			Dec. Long. <u>-116.804851</u>		
Vertical Datum _____		Horizontal Datum <u>WGS84</u>		Baseline Meridian <u>San Bernardino</u>	
Location Accuracy _____		Location Determination Method _____		Ground Surface Elevation _____	
				Elevation Accuracy _____	
				Elevation Determination Method _____	

Borehole Information	Water Level and Yield of Completed Well
Orientation <u>Vertical</u> Specify _____	Depth to first water _____ (Feet below surface)
Drilling Method <u>Downhole Hammer</u> Drilling Fluid <u>Foam</u>	Depth to Static _____
Total Depth of Boring <u>540</u> Feet	Water Level _____ (Feet) Date Measured <u>02/02/2022</u>
Total Depth of Completed Well <u>540</u> Feet	Estimated Yield* <u>75</u> (GPM) Test Type _____
	Test Length <u>4</u> (Hours) Total Drawdown _____ (feet)
	*May not be representative of a well's long term yield.

Geologic Log - Lite					
Depth from Surface Feet to Feet		Material Type	Material Color	Material Texture	Material Description
0	60	Other-Coarse Grained			
60	140	Granite			
140	160	Granite		Fractured	
160	240	Granite			
240	320	Granite		Fractured	
320	540	Granite		Fractured	

