



The Original DOBRICH & SONS SEPTIC SERVICE

P.O. BOX 1681 MAGALIA, CA. 95954

(530)-873-9901

INVOICE

JOB SITE: 14249 Sherwood Circle

CITY Magalia	DATE ORDERED 6/16/2026	SCHEDULE DATE 7/17/2026	PUMP DATE
ORDERED BY:		REPORT TO:	
Larry Knifong			
Debbie Finney			
ESCROW COMPANY :		OFFICER:	ESCROW#

SPECIAL NOTES:

Septic inspection of a 1000 gallon concrete tank in poor condition, the tank is leaking. The tank was 22" deep. There was 6" of scum and 6" of sludge in the inlet side of the tank. The inlet tee and the outlet tee are intact. The effluent in the tank is 24" lower than normal operating level. The hydraulic load test indicates there is an issue with the absorption filed, water ran back into the tank within 30 seconds of starting the test.

ORDER	DONE	DESCRIPTION	PRICE
X	X	INSPECTION	\$250.00
		INLET REPAIR	
		OUTLET REPAIR	
X	X	EXTRA LABOR Machine needed to locate and dig tank	\$350.00
		PUMP NEEDED	
		PUMP ORDERED	
			Paid -\$250.00
		"Due in 5 days. 1.5% interest will be added for each week an invoice is late"	Check # 2878

***This hydraulic load test of the absorption field does not constitute a full hydraulic load test of the dispersal field. A full hydraulic load test can only be effectively done with more water and when the system has been in continual use.

***NOTE: IF YOU PAY WITH A CREDIT CARD OR DEBIT CARD: There will be a 4% mandatory processing charge added to the total of the Invoice.

SUBTOTAL

\$350.00

AMOUNT PAID

AMOUNT OWED

CHECK#

WE ARE IN BUSINESS BECAUSE OF YOU

THANK YOU