

Improvements Per Inspection Report

- Note: Item B4-1 on the inspection report has since been determined to be inaccurate. The ceiling fan is operational; the controls were not located during the inspection.
- Note: Item A-1 on inspection report, microbial substance in attic, has since been remediated.
- Note: Per inspection report, Seller has extended all downspouts except for the ones releasing onto roof.
- Note: Per inspection report, Seller has tightened all loose receptacles.

***All information obtained is per Seller**



414.640.6118
osterny@shorewest.com
olivia.shorewest.com

