# SELLER REPAIRS

9910 N Corey Ln  Mequon

Information provided by seller:

- Weather caps (3) main chimney and repair clay flue (1).
- Woodpecker hole east side of house.
- Caulking or Grout 2nd bedroom shower
- Diverter tub hallway bathroom
- Leaky shower head hallway bathroom
- Caulk and Grout main bathroom shower
- Repair drywall main bathroom shower
- Leaking diverter tub master suite
- Caulking or Grout maintenance tub master suite
- Replace shower head basement shower
- Tile / carpet channel under door basement bathroom
- GFCI placed in laundry room
- Furnace room light repaired
- Ceiling fan master suite replaced
- Main chimney wood burning cleaned
- Carpets cleaned and sealed by Stanley Steamer