dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

PROPERTY LOCATED AT: 27 Powerhouse Road, Berwick, ME 03901

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☑ Public ☐ Private ☐ Seasonal _____ Unknown
☐ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any):	☑ N/A	☐ Yes	☐ No	☐ Unknown
Quantity:		☐ Yes	☐ No	☐ Unknown
Quality:		☐ Yes	☐ No	☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST:

Have you had the water tested?	☐ Yes	☑ No
If Yes, Date of most recent test: _____ Are test results available? ..	☐ Yes	☐ No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?	☐ Yes	☑ No
If Yes, are test results available?	☐ Yes	☑ No

What steps were taken to remedy the problem? NA

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: NA

Installed by: NA

Date of Installation: NA

USE: Number of persons currently using system: NA

Does system supply water for more than one household? ☐ Yes ☑ No ☐ Unknown

Comments: NA

Source of Section I information: Seller

Remax 360, 1 Park Ave. Ste 7-2 Hampton NH 03862 Phone: (702)497-7779 Fax: 6 Hinkley St. Lisbon,
Lloyd Ziel
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

PROPERTY LOCATED AT: 27 Powerhouse Road, Berwick, ME 03901

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☑ Public ☐ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected? ☐ Yes ☑ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ☐ Yes ☑ No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☐ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

Tank Size: ☐ 500 Gallon ☐ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☐ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: NA OR ☐ Unknown

Date installed: NA Date last pumped: NA Name of pumping company: NA

Have you experienced any malfunctions? ☐ Yes ☑ No

If Yes, give the date and describe the problem: NA

Date of last servicing of tank: NA Name of company servicing tank: _____

Leach Field: ☐ Yes ☐ No ☐ Unknown

If Yes, Location: NA

Date of installation of leach field: NA Installed by: NA

Date of last servicing of leach field: NA Company servicing leach field: NA

Have you experienced any malfunctions? ☐ Yes ☐ No

If Yes, give the date and describe the problem and what steps were taken to remedy: NA

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☑ No

If Yes, are they available? ☐ Yes ☑ No

Is System located in a Shoreland Zone? ☐ Yes ☑ No ☐ Unknown

Comments: NA

Source of Section II information: Seller

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

PROPERTY LOCATED AT: 27 Powerhouse Road, Berwick, ME 03901

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	forced hot water			
Age of system(s) or source(s)	2026			
TYPE(S) of Fuel	oil			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	unk			
Name of company that services system(s) or source(s)	unk			
Date of most recent service call	unk			
Malfunctions per system(s) or source(s) within past 2 years	NA			
Other pertinent information	NA			

Are there fuel supply lines? ☐ Yes ☐ No ☑ Unknown
Are any buried? ☐ Yes ☐ No ☑ Unknown
Are all sleeved? ☐ Yes ☐ No ☑ Unknown
Chimney(s): ☑ Yes ☐ No
If Yes, are they lined: ☐ Yes ☐ No ☑ Unknown
Is more than one heat source vented through one flue? ☐ Yes ☐ No ☑ Unknown
Had a chimney fire: ☐ Yes ☐ No ☑ Unknown
Has chimney(s) been inspected? ☐ Yes ☐ No ☑ Unknown
If Yes, date: na
Date chimney(s) last cleaned: na
Direct/Power Vent(s): ☐ Yes ☐ No ☑ Unknown
Has vent(s) been inspected? ☐ Yes ☐ No ☑ Unknown
If Yes, date: na
Comments: na
Source of Section III information: seller

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☑ Unknown
If Yes, are tanks in current use? ☐ Yes ☐ No ☑ Unknown
If no longer in use, how long have they been out of service? na
If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☑ Unknown
Are tanks registered with DEP? ☐ Yes ☐ No ☑ Unknown
Age of tank(s): na Size of tank(s): na
Location:

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

What materials are, or were, stored in the tank(s)? na

Have you experienced any problems such as leakage: ..... ☐ Yes ☐ No ☑ Unknown

Comments: na

Source of information: seller

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ..... ☐ Yes ☐ No ☑ Unknown

In the ceilings? ..... ☐ Yes ☐ No ☑ Unknown

In the siding? ..... ☐ Yes ☐ No ☑ Unknown

In the roofing shingles? ..... ☐ Yes ☐ No ☑ Unknown

In flooring tiles? ..... ☐ Yes ☐ No ☑ Unknown

Other: na ☐ Yes ☐ No ☐ Unknown

Comments: na

Source of information: seller

C. RADON/AIR - Current or previously existing:

Has the property been tested? ..... ☐ Yes ☐ No ☑ Unknown

If Yes: Date: na By: na

Results: na

If applicable, what remedial steps were taken? na

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☑ Unknown

Are test results available? ..... ☐ Yes ☑ No

Results/Comments: na

Source of information: seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? ..... ☐ Yes ☐ No ☑ Unknown

If Yes: Date: na By: na

Results: na

If applicable, what remedial steps were taken? na

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☐ Unknown

Are test results available? ..... ☐ Yes ☑ No

Results/Comments: na

Source of information: seller

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☑ No ☐ Unknown

Comments: na

Source of information: seller

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

F. LEAD-BASED PAINT/PAINT HAZARDS - *(Note: Lead-based paint is most commonly found in homes constructed prior to 1978)*

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? ..... ☐ Yes ☑ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: built in 1980

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☑ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ..... ☐ Yes ☑ No

Comments: na

Source of information: seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL:	☐ Yes	☐ No	☑ Unknown
LAND FILL:	☐ Yes	☐ No	☑ Unknown
RADIOACTIVE MATERIAL:	☐ Yes	☐ No	☑ Unknown

Other: na

Source of information: seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☐ Yes ☑ No ☐ Unknown

If Yes, explain: _____

Source of information: seller

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☑ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? na

Road Association Name (if known): na

Source of information: seller

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

PROPERTY LOCATED AT: 27 Powerhouse Road, Berwick, ME 03901

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

(1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or

(2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ……. ☐ Yes ☐ No ☑ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ……... ☐ Yes ☐ No ☑ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ……. ☐ Yes ☐ No ☑ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ……... ☐ Yes ☐ No ☑ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? …… ☐ Yes ☐ No ☑ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? …….. ☐ Yes ☑ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map? na

Relevant Panel Number: na Year: na (Attach a copy)

Comments: na

Source of Section VI information: seller

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

PROPERTY LOCATED AT: 27 Powerhouse Road, Berwick, ME 03901

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?..... ☐ Yes ☑ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☐ No ☐ Unknown

Are there any actual or alleged violations of a shoreland zoning ordinance including those that are imposed by the state or municipality? ……..... ☐ Yes ☐ No ☑ Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: na

Year Principal Structure Built: 1980 What year did Seller acquire property? 2026

Roof: Year Shingles/Other Installed: 2026

Water, moisture or leakage: na

Comments: na

Foundation/Basement:

Is there a Sump Pump? ..... ☑ Yes ☐ No ☐ Unknown

Water, moisture or leakage since you owned the property: ..... ☐ Yes ☑ No ☐ Unknown

Prior water, moisture or leakage? ..... ☐ Yes ☑ No ☐ Unknown

Comments: _____

Mold: Has the property ever been tested for mold? ..... ☐ Yes ☐ No ☑ Unknown

If Yes, are test results available? ..... ☐ Yes ☐ No

Comments: na

Electrical: ☐ Fuses ☑ Circuit Breaker ☐ Other: ☐ Unknown

Comments: na

Has all or a portion of the property been surveyed? ..... ☐ Yes ☐ No ☑ Unknown

If Yes, is the survey available? ..... ☐ Yes ☐ No ☑ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... ☐ Yes ☑ No ☐ Unknown

Modular ..... ☐ Yes ☑ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... ☐ Yes ☑ No ☐ Unknown

Comments: na

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: na

Comments: na

Source of Section VII information: seller

09/14/26 10:59 AM EDT dotloop verified

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

dotloop signature verification: dtlp.us/TUoc-LFlp-wo4J

PROPERTY LOCATED AT: 27 Powerhouse Road, Berwick, ME 03901

SECTION VIII - ADDITIONAL INFORMATION

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... ☐ Yes ☑ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SELLER	DATE	Humberto Andrade dotloop verified 09/14/26 10:59 AM EDT FME2-JCQN-HCWJ-IMQS SELLER	DATE
SELLER	DATE	SELLER	DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
BUYER	DATE	BUYER	DATE

Maine Association of REALTORS®/Copyright © 2025.
All Rights Reserved. Revised September 2024.

EQUAL HOUSING OPPORTUNITY

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Fact Sheet: Arsenic Treated Wood

Department of Health and Human Services
11 State House Station
Augusta, ME 04333

Maine CDC
Environmental and Occupational Health Program
Toll Free in Maine: 866-292-3474
Fax: 207-287-3981
TTY: 207-287-8066
Email: ehu@maine.gov

IF YOU WORK WITH CCA WOOD

- **NEVER** burn CCA wood.
- Wear gloves when handling CCA wood
- Wear a dust mask when sanding or cutting CCA wood
- Don't work with CCA wood in an enclosed area (like a garage)

Apply a coating to seal the wood every 1-2 years

TO LEARN MORE

Eric Frohmberg
Environmental and Occupational Health Program
Maine CDC
Toll-free in Maine 866-292-3474
TTY: 207-287-8066
www.maine.gov/dhhs/eohp

Does Your New Home Have Arsenic (CCA) Treated Wood?

About half of all Maine homes have a deck, or playground or some other structure that is made of wood treated with arsenic. This wood is called "CCA pressure-treated wood" or just "pressure-treated" wood. The wood was treated with arsenic to protect against rot and insects.

Too much arsenic can cause cancer. So it is good to prevent arsenic getting into your body when you can. When you touch wood treated with arsenic, you can get arsenic on your hands. The arsenic on your hands can get into your mouth if you are not careful about washing before eating. Young children are most at risk because they are more likely to put their hands in their mouths. The good news is that there are simple things you can do to protect yourself and your family from arsenic treated wood. This fact sheet will tell you how.



Children touching unsealed treated wood, and then putting their hands in their mouths is the biggest concern.

First: Does your house have arsenic treated (CCA) wood?

When arsenic treated wood is new, it tends to have a greenish tint. When CCA wood is older, it is harder to tell. Ask your realtor if the seller knows whether CCA wood was used. You can also test the wood to find out if it contains arsenic. Call us to find out how.

Second: If so, reduce contact with the arsenic.

You can lower the amount of arsenic on the surface of the wood by applying a coating on the wood every 1-2 years. Oil-based sealants, varnishes, or polyurethane work best for sealing arsenic in the wood. Be sure to wash your children's hands when they finish playing on or near CCA wood.

Third: If you have any questions, call us toll-free in Maine: 866-292-3474

Common Questions

What is CCA wood?

CCA wood is made by dipping the wood in a mixture of chemicals. These chemicals include chromium, copper, and arsenic. This protects the wood against insects and rot. This wood is known as CCA wood or "pressure treated" wood. Most pressure treated wood in the U.S. is CCA wood. After December 31, 2003, no more CCA wood will be made for use around homes. CCA wood may still be sold for home use until April 1, 2004 in the state of Maine.

What is Arsenic?

Arsenic is found in soil and rocks. Most people get a little arsenic every day from the food they eat. Also, some people have arsenic in their private wells, which is why it is important that anyone with a well have it tested for arsenic. People who are exposed to too much arsenic over many years are more likely to get cancer.