STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See Below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

Building No. Street City Zip	Date of Completion
709 Catalina Av., Santa Ana, CA 92706	03/19/2026

BUGMASTERS
Termite Control Services since 1974!

350 E. Orangethorpe #8
Placentia, CA 92870
Office: 800-982-2131
www.bugmasters.com

Report # W56114
Lic. Registration # PR 0894
Escrow #

Ordered By:	Property Owner and/or Party of Interest:	Completion Sent To:
Lynda Romoff 709 Catalina Av. Santa Ana, CA 92706	Lynda Romoff 709 Catalina Av. Santa Ana, CA 92706	Lynda Romoff 709 Catalina Av. Santa Ana, CA 92706

The following recommendations on the above designated property, as outline in Wood Destroying Pests and Organisms Inspection Report dated 02/26/2026 **have been and/or have not been completed.**

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations:

7B, 11B, 11C, 11D

Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:

Cost of work completed:

Cost : $780.00
Inspection Fee :
Other :
Total : $780.00

Recommendations not completed by this firm: Estimated Cost :

7A, 8A, 11A Not Completed
9A was not repaired by this company. The work visibly appears completed in a workmanlike manner. This company was not present at the time of repairs and has no knowledge of materials or quality of work performed, nor issues any warranty.

Remarks:

Signature

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years upon payment of a search fee to: Structural Pest Control Board, 2005 Evergreen Street, Ste. 1500, Sacramento, California 95815.
NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov