

Strong Septic Service

3249 Hwy. 49 S. Mariposa, Ca. 95338
(209) 966-7474

Septic Certification:

On March 16, 2022 a septic inspection was concluded at 5223 Boyer Rd. Mariposa, Ca. 95338. The following facts and conclusions are based on county records and onsite evaluation.

The system serviced a two bedroom mobile home that has been removed. The septic tank was located, excavated and reviewed. The septic tank is approx. 3ft. in depth. The fluid level is at the invert of the outlet (normal level). The septic tank does not have significant mat or sludge and does not require pumping at this time. The septic tank is 1,200 gallon a precast concrete tank with no cracks or leaks. The baffle and sanitary tees are intact.

The distribution box was located, excavated and reviewed. A new distribution box lid was installed to replace the broken lid. An approx. 300 gallon flow test was performed on both leach lines and the system is accepting proper water flow at this time. No above ground discharge noted.

The system is certified in operational condition at this time.
No warranties either expressed or implied accompany this report.

Russell K. Strong

Owner/Operator
Strong Septic Service
NAWT/COWA Certified Inspector ID# 11470ITC