


WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 1401	Street, City, Zip EL NORTE PKWY SPACE 198, SAN MARCOS, CA 92069-2255	Date of Inspection 05/20/2026	No. of Pages 5
 Orkin 12710 Magnolia Avenue Riverside, CA 92503		Ordered By: VERONICA SHOOP 1401 EL NORTE PKWY SPACE 198 SAN MARCOS, CA 92069-2255	
Firm Registration No. PR6199	Report No. 38595413-2	Escrow No.	
Property Owner: VERONICA SHOOP 1401 EL NORTE PKWY SPACE 198 SAN MARCOS, CA 92069-2255	Party of Interest: VERONICA SHOOP 1401 EL NORTE PKWY SPACE 198 SAN MARCOS, CA 92069-2255	Report Sent To: VERONICA SHOOP 1401 EL NORTE PKWY SPACE 198 SAN MARCOS, CA 92069-2255	
COMPLETE REPORT ☒ LIMITED REPORT ☐ SUPPLEMENTAL REPORT ☐ REINSPECTION REPORT ☐			
General Description: This is a 1 story, mobile home, single family residence. It has no garage or carport and an attached patio. It has a rolled roof and was vacant at the time of inspection.		Inspection Tag Posted: Hot Water Heater Enclosure Other Tags Posted:	
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.			
Subterranean Termites ☐ Drywood Termites ☐ Fungus / Dry rot ☐ Other Findings ☐ Further Inspection ☐ If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.			



Inspected By Martinez, Gabriel State License No FR 59722 Signature _____

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, CA 95815.

NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (REV. 04/2015)

PAGE 2 OF 5 STANDARD INSPECTION REPORT ON PROPERTY AT:

Building No. 1401	Street, City, Zip EL NORTE PKWY SPACE 198, SAN MARCOS, CA 92069-2255	Date of Inspection 05/20/2026	Report No. 38595413-2
----------------------	---	----------------------------------	--------------------------

NOTES, CAUTIONS AND DISCLAIMERS

NOTE:

Hidden damage is possible any time evidence of Subterranean Termites, Drywood Termites, fungus (Dry Rot), beetles, faulty grade, earth grade, earth-to-wood contact, Dampwood Termites, shower leaks or excessive moisture is noted on this report. This company is not responsible for hidden damage.

NOTE:

We recommend all items in our report be completed. We assume no responsibility for infestations, infections, or damage resulting from any items not completed by this company.

NOTE:

Although plumbing may have been inspected in some areas for leaks, we are not licensed plumbers. A plumbing leak may occur at any time.

NOTE:

This company guarantees areas treated for one year from the date of completion unless: A) otherwise stated in this report or service agreement, B) our guarantee may be annually renewable. See contract for any restrictions.

NOTE:

The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractors State License Board.

NOTE:

A reinspection will be performed if requested by the person who ordered the original inspection. The request for reinspection must be made within 4 months of the original inspection. The reinspection will be performed within 10 working days of the request for a fee not more than the original inspection fee.

"Notice: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company."

The pest control industry recognizes a structure to have certain areas both inaccessible and not inspected. These areas include but are not limited to: Inaccessible and/or insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls; the crawl space underneath a deck less than 12"; covered ceilings; spaces between a floor or porch deck and the ceiling below; areas where there is no access without defacing or tearing lumber, masonry, or finished work; areas underneath, behind or below appliances or beneath floor coverings or furnishings or storage, locked areas, and areas requiring an extension ladder; areas where encumbrances, storage, conditions, or locks make inspection impractical; and areas or timbers around eaves that would require use of an extension ladder.

Slab floor construction has become more prevalent in recent years. Floor covering may conceal cracks in the slab that will allow infestations to enter. Infestations may be concealed by plaster, sheetrock or other wall coverings so that a diligent inspection may not uncover the true condition. The roof was not inspected due to lack of accessibility, qualification and licensing. These areas are not practical to inspect because of health hazards, damage, obstruction or inconvenience and unless specified or described in this wood destroying pests and organisms inspection report. This company shall exercise due care during inspections and treatments but assumes no liability for any damage to tiles, slates, shingles or other roofing materials, including patio covers, aluminum awnings, solar heating, plants, shrubbery or paint during any type of treatment.

In the performance of corrective measures, it may be necessary to drill into concealed areas and/or to cut or remove plants. The termite exterminator will not be liable for plumbing, heating, electrical, gas lines and equipment in or under a slab, nor to plants which may be damaged during treatments and/or repairs.

Guarantee policy: This guarantee excludes structures with sub slab heating/air conditioning systems, plenum construction with air conditioning and heating duct in use, a well or cistern within fifty feet and areas that are inaccessible for treatment. Additional exclusions include structures with damage to or from excessive moisture, inadequate construction, areas of inaccessibility, deteriorating materials, masonry failure, grade alteration, pipes and conduits beneath concrete slab, furnishings or contents, etc. No guarantee will be issued for any work that is a secondary recommendation unless specified in your service agreement. Orkin does not guarantee work performed by others.

Guaranteed for thirty days are any plumbing, grouting, caulking and resetting of commodes, sinks or enclosures. All other work performed by this company shall be guaranteed for the duration of one year.

This wood destroying pests and organisms inspection report does not include work which requires contact with materials containing asbestos. Termite inspectors have no expertise or license in asbestos analysis. Asbestos is a natural occurring mineral fiber used extensively in construction prior to 1978. The owner, employee or contractor must determine the asbestos status prior to the commencement of work on a project. Occupants and employees must be protected from asbestos fiber release. Should asbestos be observed during any construction or demolition, work must stop. The owner shall obtain the services of an asbestos abatement contractor to evaluate the situation, provide the necessary services and certify the area safe before work may resume.

PAGE 3 OF 5 STANDARD INSPECTION REPORT ON PROPERTY AT:

Building No. 1401	Street, City, Zip EL NORTE PKWY SPACE 198, SAN MARCOS, CA 92069-2255	Date of Inspection 05/20/2026	Report No. 38595413-2
----------------------	---	----------------------------------	--------------------------

Asbestos statement ref: Ab2040, sb2572 and general industry safety order number 5208.

Note:

This property was not inspected for the presence or absence of health related molds or fungi. By California law we are neither qualified, authorized nor licensed to inspect for health related molds or fungi. If you desire information about the presence or absence of health related molds, you should contact an industrial hygienist.

Note:

Certain areas recognized by the industry as inaccessible and/or for other reason not inspected. These include but are not limited to: Inaccessible and/or insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls; spaces between a floor or porch deck and the ceiling below; areas where there is no access without defacing or tearing out lumber, masonry, or finished work; areas behind stoves, refrigerators or beneath floor coverings, furnishings; areas where encumbrances, storage, conditions, or locks make inspection impractical; and area or timbers around eaves that would require use of an extension ladder. Slab floor construction has become prevalent in recent years. Floor coverings may conceal cracks in the slab that will allow infestation to enter. Infestations may be concealed by plaster so that a diligent inspection may not uncover the true condition. These areas are not practical to inspect because of health hazards, damage to the structure, or inconvenience. They were not inspected unless described in this report. We recommend further inspection if there is any question about noted areas. Re: Structural Pest Control Act, Article 6 Section 8516 (B), paragraph 1990 (J) Amended, effective March 1, 1974.

Section 1991 of the Structural Pest Control Act states: "Local treatment is not intended to be an entire structure treatment. If infestations of wood-destroying pests extend or exist beyond the area(s) of local treatment, they may not be exterminated."

Note:

"This is a separated report which is defined as Section 1 / Section 2 conditions evident on the date of the inspection. Section 1 contains items where there is visible evidence of active infestation, infection, or conditions that have resulted in or from infestation or infection. Section 2 items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section 1 or Section 2."

Certification: "This is to certify that the above property was inspected on 5/20/26 in accordance with the Structural Pest Control Act and rules and regulations adopted pursuant thereto, and that no evidence of active infestation or infection was found in the visible and accessible areas."

"This is a separated report which is defined as Section 1 / Section 2 conditions evident on the date of the inspection. Section 1 contains items where there is visible evidence of active infestation, infection, or conditions that have resulted in or from infestation or infection. Section 2 items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section 1 or Section 2."

COMMENTS AND OTHER INFORMATION

INSPECTION REPORT PESTICIDE NOTIFICATION

"State law requires that you be given the following information:

CAUTION-PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency.

Registration is granted when the state finds that based on existing scientific evidence there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized."

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center (800-876-4766) and your pest control company immediately."

PAGE 4 OF 5 STANDARD INSPECTION REPORT ON PROPERTY AT:

Building No. 1401	Street, City, Zip EL NORTE PKWY SPACE 198, SAN MARCOS, CA 92069-2255	Date of Inspection 05/20/2026	Report No. 38595413-2
----------------------	---	----------------------------------	--------------------------

"For further information, contact any of the following: Orkin Pest Control (800-767-1471); for Health Questions-the County Health Department (626-430-5450); for Application Information-the County Agricultural Commissioner (626-575-5471) and for Regulatory Information-the Structural Pest Control Board (916-561-8700; 2005 Evergreen Street, Ste. 1500, Sacramento, Ca. 95815)."

Other symptoms not typical of influenza may include a burning feeling in the eyes and throat, blurred vision, or slurred speech.

SEE THE LIST AT THE END OF THIS SECTION FOR ADDITIONAL PHONE NUMBERS FOR ABOVE MENTIONED AGENCIES.

If this report recommends treatment of Subterranean Termites, the following pesticides may be used:

TERMIDOR	Active Ingredients:	FIPRONIL
TIM-BOR	Active Ingredients:	DISODIUM OCTABORATE TETRAHYDRATE
PREMISE 2	Active Ingredients:	IMIDACLOPRID
SENRICON RECRUIT HD	Active Ingredients:	NOVIFLUMURON
ALPINE FOAM	Active Ingredients:	DINOTEFURAN

If this report recommends treatment of Carpenter Ants, the following pesticides may be used:

TERMIDOR	Active Ingredients:	FIPRONIL
TIM-BOR	Active Ingredients:	DISODIUM OCTABORATE TETRAHYDRATE
PREMISE 2	Active Ingredients:	IMIDACLOPRID
PREMISE FOAM	Active Ingredients:	IMIDACLOPRID
ALPINE FOAM	Active Ingredients:	DINOTEFURAN

If this report recommends fumigation of Drywood Termites or Wood Boring Beetles, the following fumigant may be used:

VIKANE Active Ingredients: SULFURYL FLUORIDE
NOTE: CHLOROPICRIN will be added to the above fumigant as a warning agent.

ZYTHOR Active Ingredients: SULFURYL FLUORIDE
NOTE: CHLOROPICRIN will be added to the above fumigant as a warning agent.

If this report recommends treatment of Drywood Termites or Wood Boring Beetles, the following pesticides may be used:

TERMIDOR	Active Ingredients:	FIPRONIL
TIM-BOR	Active Ingredients:	DISODIUM OCTABORATE TETRAHYDRATE
PREMISE 2	Active Ingredients:	IMIDACLOPRID
PREMISE FOAM	Active Ingredients:	IMIDACLOPRID
ALPINE FOAM	Active Ingredients:	DINOTEFURAN
BORA-CARE	Active Ingredients:	DISODIUM OCTABORATE TETRAHYDRATE

POISON CONTROL CENTER - 800-876-4766 (To be connected to your county)

YOUR PEST CONTROL OPERATOR - ORKIN PEST CONTROL - 800-767-1471 (24hr response)

STRUCTURAL PEST CONTROL BOARD - SACRAMENTO - 916-561-8700

COUNTY	HEALTH DEPARTMENT	AG COMMISSIONER
ALAMEDA	510-267-8000	510-670-5232
ALPINE	530-694-2235 Option 2	530-621-5520
AMADOR	209-223-6407	209-223-6487
CALAVERAS	209-754-6460	209-754-6504
CONTRA COSTA	925-608-5200	925-608-6600
EL DORADO	530-621-6100	530-621-5520
FRESNO	559-600-3200	559-600-7510
IMPERIAL	442-265-1444	442-265-1500
INYO	760-873-3305	760-873-7860
KERN	661-321-3000	661-868-6300
KINGS	559-584-1401	559-852-2830
LAKE	707-263-1000	707-263-0217
LASSEN	530-251-8183	530-251-8110
LOS ANGELES	833-540-0473	626-575-5451
MADERA	559-675-7893	559-675-7876
MARIN	415-473-4163	415-473-6700
MARIPOSA	209-966-3689	209-966-2075
MERCED	209-381-1200	209-385-7431
NAPA	707-253-4270	707-253-4357

PAGE 5 OF 5 STANDARD INSPECTION REPORT ON PROPERTY AT:

Building No. 1401	Street, City, Zip EL NORTE PKWY SPACE 198, SAN MARCOS, CA 92069-2255	Date of Inspection 05/20/2026	Report No. 38595413-2
----------------------	---	----------------------------------	--------------------------

NEVADA	530-265-1450	530-470-2690
ORANGE	800-564-8448	714-955-0100
PLACER	530-889-7141	530-889-7372
PLUMAS	530-283-6337	530-283-6365
RIVERSIDE	951-358-5000	951-955-3045
SACRAMENTO	916-875-5881	916-875-6603
SAN BERNARDINO	800-782-4264	909-387-2105
SAN DIEGO	619-542-4170	858-694-2739
SAN FRANCISCO	415-554-2500	415-252-3830
SAN JOAQUIN	209-468-3400	209-953-6000
SAN LUIS OBISPO	805-788-2903	805-781-5910
SAN MATEO	650-573-2346	650-363-4700
SANTA CLARA	408-792-5040	408-918-4600
SOLANO	707-784-8600	707-784-1310
SONOMA	707-565-4400	707-565-2371
STANISLAUS	209-558-7000 Option 1	209-525-4730
SUTTER	530-822-7215	530-822-7500
TULARE	559-624-8480	559-684-3350
TUOLUMNE	209-533-7401	209-533-5691
VENTURA	805-981-5101	805-388-4222
YOLO	530-666-8645	530-666-8140