

BOB'S POOL BUILDERS, INC.

912 Front St

Ste B

Sullivan, WI 53178-9602 USA

2625935242

sales@bobspoolbuilders.com



Estimate

ADDRESS

Jessica & Chad Rebstock
Rebstock
N39 W32963 High Hill Court
Nashotah, WI 53058

ESTIMATE # 1391**DATE 08/31/2026**

DESCRIPTION	QTY	RATE	AMOUNT
NOTE: Replacement liner installations are not typically done during the opening season March 15th through May 31st. We recommend opening your pool as usual to maintain, clear and balanced water until your liner installation is scheduled by your office. Please note that liner installations cannot be performed when overnight temperatures are near or below freezing, as freezing conditions may cause damage to the vermiculite base.	1	0.00	0.00T
Pool Liner: Custom 20 Mil Merlin Standard, Value-Max, Super Value-Max, Including the following: Water removal, liner removal and disposal, New gaskets and face plates for skimmers, main drain, and returns. Bottom Repair with up to one batch of vermiculite.	1	6,914.00	6,914.00T
New gaskets in face plates will be provided and installed for the following: skimmers, main drains, returns.	1	0.00	0.00T
Loads of Water. Each Load Is Approximately 6500 Gallons. *Allowance - Subject to change based on delivery additions such as long driveway, small truck only access, etc** This may not fill your pool - you could fill from your hose or call for another load*	3	400.00	1,200.00T
UPGRADES AND OPTIONS	1	0.00	0.00T
Under liner mold and algae chemical treatment application	1	79.00	79.00T
Acid Wash fiberglass or plastic entry stairway in wall ladder (Results may vary depending on condition of the unit)	1	79.00	79.00T
Liner replacement Start Up Chemicals including: Algaecide 60%, Stain and scale, and three bags of shock	1	39.00	39.00T
1/8 inch wall foam installed between steel walls and liner if necessary due to rust or deteriorating foam	0	0.00	0.00T
27 mil thickness upgrade available in specific patterns only see brochure *upgrade*	0	0.00	0.00T
Merlin Aqua-Max: Upgrade UV and Weathering Protection. This upgrade is available in specific patterns only see brochure. *upgrade*	0	0.00	0.00T
Merlin Aqua Intense liner. This upgrade is available in specific patterns	0	0.00	0.00T

DESCRIPTION	QTY	RATE	AMOUNT
only. *See brochure for available patterns* Upgrade			
ITEMS/ OPTIONS BELOW ARE NOT INCLUDED IN THE TOTAL	1	0.00	0.00T
Ground water pumping, mold removal, or retroweling sand bottoms, are not included, and are billed at time and material. Repairs other than the liner replacement are not included unless specified in the estimate.	1	0.00	0.00T
NOT INCLUDED: Gaskets and face plates for fiberglass or plastic entry stairway or in-wall ladders.	1	0.00	0.00T
Vinyl liner stairways: minor puckering or wrinkling may be visible in the liner retention areas, tight corners or over sharp edges. These conditions are considered normal with an industry standards and do not affect the performance or longevity of the liner.	1	0.00	0.00T
light ring face plate 10 hole	0	0.00	0.00T
Bottom Repair with up to one batch vermiculite included. Extra batches billed @ Time and material. If a sand bottom is found customer will be billed at Time and material for fresh sand and retroweling.	1	0.00	0.00T

SUBTOTAL	8,311.00
TAX	415.55
TOTAL	\$8,726.55

Accepted By

Accepted Date