

Updates

Exterior tuckpointing and brick work

2 roof repairs

2 window lintels replaced

All full size windows replaced and wrapped, all windows wrapped

New hot water heater for the building

Concrete work and mud jacking out back

Landscaping and grading

South side window wells completely repaired and replaced

Basement glass block windows installed

Glass block windows installed on all the bathroom windows

Unit 1, 3, 8 renovated and upgraded

Hallways repainted and lights upgraded

New flooring and drywall work in hallway

Plumbing supply lines

replaced to multiple units

Plumbing shut off valves added for the supply lines to the units

East basement wall excavated and repaired

Front door repair

New sump pump

Added power to laundry room