Estimate

2611-1013-0568
2026-11-10

Concrete PolyFix
PO Box 2148
Iowa City Iowa 52244
contact@concretepolyfix.com
(319) 535-2401

Realty 87 - Carla Stevens
2030 Rosewood Ridge Dr
Marion IA 52302
carlastevens@realty87.com
(319) 893-4363

Job Location: 2030 Rosewood Ridge Dr, Marion, IA, 52302
Job Name: Carla Stevens

Poly

Description	*Quantity*	*Total*
Driveway Reduce lip going into garage all across. Bringing back up to half inch drop from garage floor. Lifting front walk to match	148.15	$2,000.00
	148.15	$2,000.00

Discount

Description	*Total*
Discount	$-300.00
	$-300.00

Total $1,700.00

Compensation & Project: The client shall pay as set forth above. With the customer's approval, the price is subject to change. If the void under the slab is greater than anticipated and additional material is needed, cost will be priced per unit of material used. All things listed in the estimate above are included in the quote. **If the client would like additional work such as caulking, expansion joint, or grinding, it must be noted in the estimate before the project is started.** The only movement of concrete our process allows for is raising. We cannot move concrete side to side, lower heaved-up concrete, or close gaps between slabs.

Polyurethane Warranty and Liability Waiver: **All polyurethane material is lifetime. Any service provided by this material warrants a 2-year service agreement, any shifting or movement will be assessed at no charge under these terms and conditions. Concrete Polyfix will re-level once in a two-year period. The warranty is void if resettling is**

due to drainage issues. Warranties do not become effective until full payment is received. The chances of damage to concrete while lifting are rare, but not impossible. Concrete Polyfix is not responsible for any cracks or chips made in the concrete. The client must inform Concrete Polyfix of the exact location of any latent underground improvements (such as, without limitation, irrigation and sprinkler systems, downspout tile, plumbing lines, electric animal fences, etc.)..Unless Concrete Polyfix is grossly negligent or intentionally harms any persons or property, Concrete Polyfix will not be responsible or liable for any personal or property damage caused by Concrete Polyfix while performing work on Client's property. Concrete Polyfix shall not be held liable for any damages in caulking resulting from natural causes or environmental factors, including but not limited to animal or human steps, leaves, dirt, debris, or other act of nature affecting the caulking. The customer acknowledges that caulking requires a curing period of 24-48 hours.

Payment: Payment is due upon project completion. You can pay the crew by check. Any amount billed which is not paid by the customer within thirty (30) days of billing shall bear interest at the rate of 1.5% per month until paid in full. **Credit card transactions will incur a 3% processing fee.** If the customer fails to pay in full, the customer shall pay all costs associated with such non-payment including, but not limited to, accumulated interest for late payments as set forth above, return check fees (in the amount of $30.00), insufficient fund fees, third party collection agency fees, attorney fees, and court costs.

Signature:
Date:

oop signature verification: dtlp.us/AGIa-rMIN-lt3A

EXTERIOR/SITE/GROUND DRIVEWAY

FLAG **s-33:** Typical settling at garage entrance which creates a trip hazard. This typically only needs addressed when you are unable to drive a smaller vehicle up into garage. Most drives will raise & lower with frost. This homes drive appears to have settled to much(Approx 3") & needs addressed either by raising concrete or replacing portions of concrete. The common difference in height is about 1/2"-1".







