

STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See Below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

<small>Building No.</small>	<small>Street</small>	<small>City</small>	<small>Zip</small>	<small>Date of Completion</small>
1412 Larch St, Alhambra, CA 91801				01/16/2026
 <p>Golden Dragon Termite Control Inc 9718 Planter St. Pico Rivera, CA 90660 (626) 623-0653 goldendragontermite@gmail.com</p>			<small>Report #</small>	W8542
			<small>Lic. Registration #</small>	PR 9795
			<small>Escrow #</small>	
<small>Ordered By:</small>	<small>Property Owner and/or Party of Interest:</small>		<small>Completion Sent To:</small>	
Property Owner 1412 Larch St Alhambra, CA 91801	Property Owner 1412 Larch St Alhambra, CA 91801		Property Owner 1412 Larch St Alhambra, CA 91801	

The following recommendations on the above designated property, as outline in Wood Destroying Pests and Organisms Inspection Report dated 01/08/2026 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations:

1A, 8A, 8B, 8C, 8D, 9A, 9B, 10A, 10B, 11A, 11B

Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:

Cost of work completed:

Cost :	\$4,850.00
Inspection Fee :	
Other :	
Total :	\$4,850.00

Recommendations not completed by this firm: Estimated Cost : _____

1B and 8E were not completed by Golden Dragon Termite Control. Owner hire contractor for further inspection and make necessary repair.

Remarks:

This is to certify that the property described herein is now free of evidence of active infestation or infection in the visible and accessible areas.

Signature _____ 

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years upon payment of a search fee to: Structural Pest Control Board, 2005 Evergreen Street, Ste. 1500, Sacramento, California 95815.
NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov