

STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

Building No. 1077	Street WESTPARK LN	City CORONA	ZIP 92882	Date of Completion 04/09/2026
----------------------	-----------------------	----------------	--------------	----------------------------------



Goldenbear Termite Control Corp

2989 S BUENA VISTA AVE
Corona CA 92882
(949) 298-0841
info@goldenbeartermite.com
GOLDENBEARtermite.com

Report # : 10264 - 1
Registration # : PR8454
Escrow # :
 CORRECTED REPORT

Ordered By: WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States	Property Owner and/or Party of Interest: <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States</td> <td style="width: 50%;">WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States</td> </tr> </table>	WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States	WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States	Completion Sent To: WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States
WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States	WALT ROLOSON 1077 WESTPARK LN CORONA CA 92882 United States			

The following recommendations on the above designated property, as outlined in Wood Destroying Pests and Organisms Inspection Report dated 03/07/2026 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations:
Structural Fumigation completed on 04/09/2026 using Vikane® (Sulfuryl Fluoride, EPA Reg. No.#62719-4) 15 Lbs, for drywood termites. on 04/09/26.

Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:
Wood repair work Completed on 04/14/2026. At completion of treatment, structure was found clear of visible evidence of active termite infestation.

Cost of work completed:	Cost: \$ <u>0.00</u>
	Inspection Fee: \$ <u>0.00</u>
	Other: \$ <u>0.00</u>
	Total: \$ <u>0.00</u>

Recommendations not completed by this firm:

Estimated Cost: \$ _____

Remarks:
This is to certify that the property described herein is now free of evidence of active infestation or infection in the visible and accessible areas.

Inspected By: Richard Alamillo State License No. OPR13630 Signature:

You are entitled to obtain copies of all reports and completion notices on this property reported to the Board during the preceding two years upon payment of a search fee to: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815.

NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-44 (Rev.10/01)