



Action Pumping, Inc.

P.O. Box 654
Yucca Valley , CA 92286

INVOICE	#6287
SERVICE DATE	Mar 11, 2019
DUE	Upon receipt
AMOUNT DUE	\$320.00

██████████
59773 Applegate Way
Landers, CA 92285

☎ ██████████
✉ ██████████

CONTACT US

☎ (760) 365-0861
✉ sales@actionpumpinginc.com

Service completed by: Ty Spraggins

INVOICE

Services	amount
----------	--------

Septic Pumping - Landers	\$180.00
--------------------------	----------

This tank is extremely old and needs replacement also, water flows to the tank but inlet line is not sticking far enough into the tank for a smooth flow, there is a small amount of buildup and roots around the mainline right as it comes into the tank blocking the contents from making it into the tank properly and will most likely cause a blockage if this is not repaired.

There is also a small amount of dirt and trash inside of this tank and which has been empty for what appears to be a long time Inlet and Outlet lid are completely rotten and need replacement.

There is an old mat layer resting at the bottom of the tank indicating that either the liquids leaked out through a crack in the tank or it evaporated, which would take a large amount of years, or that just the water was pumped out. Recommend an outlet line change and an exploratory. Drainage took water up to 30 mins. Good access for all equipment. Marked for UTI as well.

Septic Inspection - Report	\$50.00
----------------------------	---------

SEPTIC TANK

What size tank:750gal

Type of tank: Metal

Condition of tank:

Did all toilets flush into septic tank: Unable to flush toilet, but water dose make it into the tank.

LEACHFIELD

Are there wet spots, or any other indication of drainage failure?: no

Did drainage system accept water?: yes

Required Repairs & Comments: refer back to the notes

NOTICE TO BUYER: It is not practical to inspect the actual drainfields as they are buried in the ground. The above elevation only measures the ability of the drainfield to handle the quantity of

water/effluent it has been recently processing. It does not insure that it will not fail under a greater load. All drainfields will fail if they received more water than can be absorbed into the ground immediately surrounding the field.

Materials - Lid-Plastic	\$90.00
Replacement lid for metal or fiberglass septic tanks	

Total **\$320.00**

State contractors lic. no. 436154 (C-36 & C-42)

Thank you for your business. If balance is not paid within 30 days a 2% late fee will be applied.