


DigiSign Verified: 48C3ACBD-B277-45D2-9C9A-96F58DF49B30



DigiSign Verified: 48C3ACBD-B277-45D2-9C9A-96F58DE48B30



DigiSign Verified: 48C3ACBD-B277-45D2-9C9A-96F58DE48B30



SOIL DESCRIPTION AND CLASSIFICATION (Location of Observation Holes Shown Above)

Observation Hole #1 ☒ Test Pit ☐ Boring

" Depth of Organic Horizon Above Mineral Soil

Depth Below Mineral Soil Surface (inches)	Texture	Consistency	Color	Mottling
0–10	COBBLY GRAVELLY LOAMY SAND	FRIABLE	DARK YELLOWISH BROWN 10YR 4/6	
10–20				
20–30	LARGE ROCK			
30–40				
40–50				

Soil Classification	Slope	Limiting Factor	
3 / C (Profile / Condition)	____ %	28"	[ ] Ground Water [ ] Restrictive Layer [ ] Bedrock [X] Pit Depth

Observation Hole _____ ☐ Test Pit ☐ Boring

" Depth of Organic Horizon Above Mineral

Depth Below Mineral Soil Surface (inches)	Texture	Consistency	Color	Mottling
0–10				
10–20				
20–30				
30–40				
40–50				

Soil Classification	Slope	Limiting Factor	
Profile / Condition	____ %	____"	[ ] Ground [ ] Restric [ ] Bedro [ ] Pit D

James H. Mauricio — 747 — Dec 12, 2020

Site Evaluator Signature — SE # — Date

HF

DigiSign Verified: 48C3ACBD-B277-45D2-9C9A-96F58DE48B30

