eurofins | Environment Testing

Eurofins Auburn
Laboratory Report

A Builders View
Tom Leblanc
37 Rolling Meadow Drive
Norway, ME 04268

Job ID:	**295-14750-1**
Date Received:	**7/28/2026 12:45 PM**
Sample Collected In:	**Maine**
Job Desc:	**Hansen**

The analytical test results presented in this report meet all requirements of the associated regulatory program listed in the Certification Summary section, unless otherwise noted. This certificate shall not be reproduced, except in full, without the written approval of the analyzing laboratory. The results presented in this report relate to the samples listed on the following pages in the condition in which they were received. Data qualifiers and/or narrative comments are included to explain any exceptions, if applicable. Regulated compliance samples (e.g. SDWA, NPDES) must comply with associated agency requirements/permits.

Receipt
The sample was received on 7/28/2026 12:45 PM. Unless otherwise noted below, the sample arrived in good condition, and, where required, properly preserved and on ice. The temperature of the cooler at receipt time was 21.0°C.

Certification Summary
Certifications for this job are presented below. Note that not all certifications may be applicable to your report and certifications for subcontracted laboratories are available upon request. Analytes not considered to be certified under the certifications associated with this report will have an asterisk next to their names. Evidence of certification for laboratories within Eurofins Environmental Testing can be found on the following website: https://www.eurofinsus.com/environment-testing/resources/certifications/

Eurofins Auburn (AUB), 155 Center Street, Building C, Auburn, ME 04210
Maine, Lab ID: ME01076
Maine (Rad), Lab ID: SPC20, RSP50083

Action Limit Summary
Sample results for 295-14750-1 have been evaluated against the following action limits and/or Maximum Contaminant Levels:
- EPA Primary Limits: Maine EPA Primary DW MCL
- EPA Secondary Limits: Maine EPA Secondary DW MCL
- State Limits: 295 - Maine - Guidelines

Definitions regarding the evaluations presented within this report are presented below:
- EPA Primary Limits: Legally enforceable standards known to affect human health.
- EPA Secondary Limits: Non-enforceable standards that may cause cosmetic or aesthetic effects.
- Pass: Result is below the action limit and/or MCL.
- Fail: Result is above the action limit and/or MCL.
- Attention: Result indicates a potential pathway for contaminants to enter the system that warrants investigation.
- No Limit: No action limit or MCL is available.

Analysis Related Notes
DF: "Dilution factor" means the ratio of the volume of the final (dilution) solution to the volume of sample.
MDL: "Minimum Detection Limit" means the minimum result which can be reliably distinguished from a blank with predetermined confidence level.
ND: Non-detected at the reporting limit (or MDL or EDL if shown).
RL: "Reporting limit" means the lowest level of an analyte that can be accurately recovered from the matrix of interest.
Data qualifier flags provide additional information in regards to the receipt, analysis or quality control of a sample. If any such flags are associated with the results of this report, they will be listed below along with their definitions.

eurofins | Environment Testing

Legend	
Passes	✓
Fails EPA Primary	⊗
Fails EPA Secondary	▽
Fails State Guideline	✕
Attention	⚠

CERTIFICATE OF ANALYSIS FOR DRINKING WATER

CLIENT SAMPLE ID: 393 Bush Row Road, Denmark, ME 04022
SAMPLE ID #: 295-14750-1
CLIENT JOB #:
OTHER SAMPLE INFO: Drilled Well
SAMPLED BY: A Builders View Home Inspections
COLLECTION DATE/TIME: 07/28/26 09:50

Test Description (SM7500_Rn_B)	Results	Units	Pass/ Fail	DQ Flag	RL	DF	Limit	Analyst /Lab	Date & Time Prepared	Date & Time Analyzed
Radon	24385	pCi/L	X		100	1	4000	TT - AUB		07/29/26 22:16

Job ID: 295-14750-1

Authorized By: Amber Cusson, Operations Manager
Phone: (207)784-5354

7/30/2026

Eurofins-Auburn

Eurofins Drinking Water and Wastewater Northeast, LLC

155 Center Street Bldg C, P.O. Box 1507, Auburn, Maine 04211

(207) 784-5354

295-14750 COC
Loc: 295
14750
#1 A
Radon

Reason for Testing: ❑ Personal Information ❑ Real Estate Transaction (If checked section below must be c

Real Estate Transactions

If you are buying or selling a home, you cannot legally test for radon yourself. You must hire a Maine state registered ra...
For a current list visit: http://www.MaineRadiationControl.org
State of Maine registration # SME 361

Fill out both boxes below. Failure to do so will delay reporting results.

Report To:

Name
Address ABUILDERSVIEW.
City Home inspections
State @gmail.com Zip
Phone
Email

Property Address:

Name RICHARD HANSEN
Address 393 Bush Row RD
City DENMARK
State ME Zip 04022
Phone
Person Sampling: ABUILDERSVIEW. Home inspections @gmail.com
Zip Code Required

Please enclose payment in the amount of $40.00 for a water radon

Building Type: Residence Apartment Building Commercial Building

Area Tested: Dug Well Drilled Well Well Point Spring Lake Other

Mitigation System: Yes / No (Is there currently a system in place to remove water radon?)

Comments:

Collection Date: 7-28-26 **Collection Time:** 9:50 AM / PM

Eurofins-Auburn considers these results to be the property of the person or institution named in the "Report To" section of this document. Hard copies of the results WILL NOT be forwarded to any other party. Verbal results will be given out only by providing Eurofins-Auburn with the serial number. No information will be released wither verbally or in writing without

Sample MUST be received and processed in the lab within 4 days from the collection time.

PLEASE READ INSTRUCTIONS ON REVERSE SIDE

For Laboratory Use Only

Date/Time Received: 7/28/26 12:45

On Ice YES ❑ NO ☒ Initial Temp [°C]: 21 Corrected Temp [°C]: 21 IR Gun# 579

Method of Delivery: Walk In❑ Mail❑ UPS❑ Courier❑ Drop Box❑

Paid 2400 Bill Hold No Charge Initials MF

☒ CK# 941 ❑ CC Test Result: pCi/L Calculation by: