Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

PROPERTY LOCATED AT: **699 North High Street, Bridgton, ME. 04009**

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal ---------- ☒ Unknown
☒ Drilled ☐ Dug ☐ Other ----------

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): ..... ☐ N/A ☐ Yes ☒ No ☐ Unknown
Quantity: ..... ☐ Yes ☒ No ☐ Unknown
Quality: ..... ☐ Yes ☒ No ☐ Unknown
If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ..... ☒ Yes ☐ No
If Yes, Date of most recent test: **Approx.** Are test results available? .. ☐ Yes ☒ No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? ..... ☐ Yes ☒ No
If Yes, are test results available? ..... ☐ Yes ☒ No
What steps were taken to remedy the problem? **A whole house filtration system was installed.**

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: **Left side of home.**
Installed by: **Unknown**
Date of Installation: **Approx. 1996**

USE: Number of persons currently using system: **3**
Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: **New pump installed 2016**

Source of Section I information: **Seller, Listing Agent.**

F.O. Bailey Real Estate, 183 US-1 Falmouth ME. 04105 Phone: 2076154346 Fax: 2076154346 Annette Kimbal
Misti Fecteau
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

PROPERTY LOCATED AT: **699 North High Street, Bridgton, ME. 04009**

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public ---------- ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected? ..... ☐ Yes ☒ No

If Yes, what results: **N/A**

Have you experienced any problems such as line or other malfunctions? ..... ☐ Yes ☒ No

What steps were taken to remedy the problem? **N/A**

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: ----------

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: ----------

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: ----------

Location: **Next to the side porch** OR ☐ Unknown

Date installed: **2021** Date last pumped: **N/A** Name of pumping company: **N/A**

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

If Yes, give the date and describe the problem: **N/A**

Date of last servicing of tank: **N/A** Name of company servicing tank: **N/A**

Leach Field: ..... ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **Hill behind the house**

Date of installation of leach field: **Unknown** Installed by: **Unknown**

Date of last servicing of leach field: **N/A** Company servicing leach field: **Unknown**

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: **N/A**

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ No

If Yes, are they available? ..... ☐ Yes ☒ No

Is System located in a Shoreland Zone? ..... ☐ Yes ☒ No ☐ Unknown

Comments: **None**

Source of Section II information: **Seller, Listing Agent.**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com Annette Kimbal

PROPERTY LOCATED AT: **699 North High Street, Bridgton, ME. 04009**

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	**FHW- Oil**	**Wood Stove**	----------	----------
Age of system(s) or source(s)	**Unknown**	**Approx. 2001**	----------	----------
TYPE(S) of Fuel	**Oil**	**Wood**	----------	----------
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	**Unknown** **Unknown**	**Not Used** ----------	---------- ----------	---------- ----------
Name of company that services system(s) or source(s)	**Ken Austin**	**N/A**	----------	----------
Date of most recent service call	**Serviced 2025**	**NA**	----------	----------
Malfunctions per system(s) or source(s) within past 2 years	**None**	**None**	----------	----------
Other pertinent information	**Cleaning done in Fall of 2025**	**None** ----------	---------- ----------	---------- ----------

Are there fuel supply lines? ..... [X] Yes [ ] No [ ] Unknown

Are any buried? ..... [X] Yes [ ] No [ ] Unknown

Are all sleeved? ..... [ ] Yes [X] No [ ] Unknown

Chimney(s): ..... [X] Yes [ ] No

If Yes, are they lined: ..... [X] Yes [ ] No [ ] Unknown

Is more than one heat source vented through one flue? ..... [ ] Yes [X] No [ ] Unknown

Had a chimney fire: ..... [ ] Yes [X] No [ ] Unknown

Has chimney(s) been inspected? ..... [ ] Yes [X] No [ ] Unknown

If Yes, date: **N/A**

Date chimney(s) last cleaned: **Approx. 8 yrs. ago**

Direct/Power Vent(s): ..... [ ] Yes [X] No [ ] Unknown

Has vent(s) been inspected? ..... [ ] Yes [X] No [ ] Unknown

If Yes, date: **N/A**

Comments: **Newer hot water heater (within last 5 yrs.).**

Source of Section III information: **Seller, Listing Agent.**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ..... [ ] Yes [X] No [ ] Unknown

If Yes, are tanks in current use? ..... [ ] Yes [X] No [ ] Unknown

If no longer in use, how long have they been out of service? **N/A**

If tanks are no longer in use, have tanks been abandoned according to DEP? [ ] Yes [X] No [ ] Unknown

Are tanks registered with DEP? ..... [ ] Yes [X] No [ ] Unknown

Age of tank(s): **N/A** Size of tank(s): **N/A**

Location: **N/A**

Initial

Buyer Initials _____ _____ _____ _____ Seller Initials ak _____ _____ _____ _____

Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

What materials are, or were, stored in the tank(s)? **N/A**

Have you experienced any problems such as leakage: ..... ☐ Yes ☒ No ☐ Unknown

Comments: **No underground storage tanks.**

Source of information: **Seller, Listing Agent.**

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ..... ☐ Yes ☒ No ☐ Unknown

In the ceilings? ..... ☐ Yes ☒ No ☐ Unknown

In the siding? ..... ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ..... ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ..... ☐ Yes ☒ No ☐ Unknown

Other: **N/A** ☐ Yes ☒ No ☐ Unknown

Comments: **None**

Source of information: **Seller, Listing Agent.**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ..... ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **Unknown** By: **Unknown**

Results: **Above the actionable level of 4.0 pi/L**

If applicable, what remedial steps were taken? **Radon mitigation system installed.**

Has the property been tested since remedial steps? ..... ☐ Yes ☒ No ☐ Unknown

Are test results available? ..... ☐ Yes ☒ No

Results/Comments: **None**

Source of information: **Radon system installed by Air Quality & Control. Seller, Listing Agent.**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ..... ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **Unknown** By: **Air Quality & Control**

Results: **Unknown**

If applicable, what remedial steps were taken? **A whole house radon mitigation system installed.**

Has the property been tested since remedial steps? ..... ☐ Yes ☒ No ☐ Unknown

Are test results available? ..... ☐ Yes ☒ No

Results/Comments: **Seller decided to put a whole house filtration system in just to be on the safe side**

Source of information: **Installed by Air Quality & Control. Seller, Listing Agent.**

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: **None**

Source of information: **Seller, Listing Agentl.**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com Annette Kimbal

Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

F. LEAD-BASED PAINT/PAINT HAZARDS - *(Note: Lead-based paint is most commonly found in homes constructed prior to 1978)*

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .... ☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: **Very small portion of home was built in 1850**

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: **N/A**

Are you aware of any cracking, peeling or flaking paint? ..... ☒ Yes ☐ No

Comments: **Home has some exterior flaking paint.**

Source of information: **Seller, Listing Agent.**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL:	☐ Yes	☒ No	☐ Unknown
LAND FILL:	☐ Yes	☒ No	☐ Unknown
RADIOACTIVE MATERIAL:	☐ Yes	☒ No	☐ Unknown

Other: **None**

Source of information: **Seller, Listing Agent.**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **N/A**

Source of information: **Seller, Listing Agent, Deed.**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? **N/A**

Road Association Name (if known): **N/A**

Source of information: **Seller, Listing Agent.**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com Annette Kimbal

Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

(1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or

(2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? …… ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ……... ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

_____

Relevant Panel Number: **23005C0059F** Year: **2024** (Attach a copy)

Comments: **Area of minimal Flooding**

Source of Section VI information: **Seller, Listing Agent.**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Annette Kimbal

Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

PROPERTY LOCATED AT: **699 North High Street, Bridgton, ME. 04009**

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?..... [X] Yes [ ] No [ ] Unknown

If Yes, explain: **Homestead Exemption**

Is a Forest Management and Harvest Plan available?..... [ ] Yes [X] No [ ] Unknown

Are there any actual or alleged violations of a shoreland zoning ordinance including those that are imposed by the state or municipality? ……..... [ ] Yes [X] No [ ] Unknown

If Yes, explain: **None**

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **None**

Year Principal Structure Built: **1850 / 1997** What year did Seller acquire property? **Approx. 1996**

Roof: Year Shingles/Other Installed: **Metal & Shingle roof. Shingled section is newer (approx. 8 yrs.).**

Water, moisture or leakage: **None**

Comments: **Seller, Listing Agent.**

Foundation/Basement:

Is there a Sump Pump? ..... [X] Yes [ ] No [ ] Unknown

Water, moisture or leakage since you owned the property: ..... [X] Yes [ ] No [ ] Unknown

Prior water, moisture or leakage? ..... [ ] Yes [X] No [ ] Unknown

Comments: **In heavy rain - sump pump.**

Mold: Has the property ever been tested for mold? ..... [ ] Yes [X] No [ ] Unknown

If Yes, are test results available? ..... [ ] Yes [X] No

Comments: **Seller, Listing Agent.**

Electrical: [ ] Fuses [X] Circuit Breaker [ ] Other: **N/A** [ ] Unknown

Comments: **Seller, Listing Agent.**

Has all or a portion of the property been surveyed? ..... [ ] Yes [X] No [ ] Unknown

If Yes, is the survey available? ..... [ ] Yes [X] No [ ] Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... [ ] Yes [X] No [ ] Unknown

Modular ..... [ ] Yes [X] No [ ] Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... [ ] Yes [X] No [ ] Unknown

Comments: **None**

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **See section VIII / Additional Information**

Comments: **None**

Source of Section VII information: **Seller, Listing Agent.**

Buyer Initials _____ _____ _____ _____ Seller Initials Initial _____ _____ _____ _____

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: BAEC5DBA-75E2-8B8A-838E-F66ECC850191

PROPERTY LOCATED AT: **699 North High Street, Bridgton, ME. 04009**

SECTION VIII - ADDITIONAL INFORMATION

Original footprint of the house is 1850. The house has been completely rebuilt in 1997. The Seller is aware that some decking boards exhibit wood rot and may require repair/replacement. A section of exterior clapboard is missing, some doghouse singles need replacing. LR flooring boards iare damaged. There is wood rot around the basement door casing and on portions of the front porch. Small foundation crack previously repaired. Single wide mobile home on site.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... [X] Yes [ ] No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: Annette Kimball 8/17/2026
SELLER E40BEB17BB848B... DATE

SELLER DATE

SELLER DATE

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

Maine Association of REALTORS®/Copyright © 2025.
All Rights Reserved. Revised September 2024.

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Annette Kimbal