Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

PROPERTY LOCATED AT: **98 Salmon Falls Rd, Hollis,**

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): ..... ☐ N/A ☐ Yes ☒ No ☐ Unknown
Quantity: ..... ☐ Yes ☒ No ☐ Unknown
Quality: ..... ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ..... ☒ Yes ☐ No

If Yes, Date of most recent test: **10/2/26** Are test results available? .. ☒ Yes ☐ No

To your knowledge, have any test results ever:

a) Been reported as unsatisfactory or satisfactory with notation?..... ☐ Yes ☒ No
b) Detected perfluoroalkyl and polyfluoroalkyl (PFA) substances? ☐ Yes ☒ No

~~If Yes to (a) and/or (b) above, are test results available~~? ..... ☐ Yes ☐ No

What steps were taken to remedy the problem? **NA**

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: **Front Yard**
Installed by: **High Pine Well Drilling**
Date of Installation: **Unk**

USE: Number of persons currently using system: **0**
Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: **None**

Source of Section I information: **Inspection Company/Personal Rep**

Initial KK PR

Buyer Initials _____ _____ _____ _____ Seller Initials _____ _____ _____ _____

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

~~Have you had the sewer line inspected?~~ ..... ☐ Yes ☐ No

~~If Yes, what results:~~ _____

~~Have you experienced any problems such as line or other malfunctions~~? ..... ☐ Yes ☐ No

W~~hat steps were taken to remedy the problem~~? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☐ 1000 Gallon ☒ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: **Back Left of Home** OR ☐ Unknown

Date installed: **UNK** Date last pumped: _____ Name of pumping company: _____

Have you experienced any malfunctions? ..... ☒ Yes ☐ No

If Yes, give the date and describe the problem: **Needs new outlet baffle.**

Date of last servicing of tank: _____ Name of company servicing tank: _____

Leach Field: ..... ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **Left side of House**

Date of installation of leach field: **UNK** Installed by: **UNK**

Date of last servicing of leach field: **UNK** Company servicing leach field: **UNK**

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

~~If Yes, give the date and describe the problem and what steps were taken to remedy~~: _____

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ No

~~If Yes, are they available?~~ ..... ☐ Yes ☐ No

Is System located in a Shoreland Zone? ..... ☐ Yes ☒ No ☐ Unknown

Comments: **Septic Tank Size-told two different things by A1 and Attentive Septic-Buyer should do their own due diligence**

Source of Section II information: **Inspector/Personal Representative**

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

PROPERTY LOCATED AT: **98 Salmon Falls Rd, Hollis,**

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	**FHA/Oil**	**Gas Stove**	**na**	**na**
Age of system(s) or source(s)	**UNK**	**2013?**	**na**	**na**
TYPE(S) of Fuel	**OIL**	**Propane**	**na**	**na**
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	**Unknown-Home has been vacant.**	**Unknown-Home has been vacant.**	**na**	**na**
Name of company that services system(s) or source(s)	**Steve Frost**	**unknown**	**na**	**na**
Date of most recent service call	**Furnace Cleaned 10/1**	**unknown**	**na**	**na**
Malfunctions per system(s) or source(s) within past 2 years	**UNK**	**na**	**na**	**na**
Other pertinent information	**New Filter Installed 10/3**	**Eastern Propane**	**na**	**na**

Are there fuel supply lines? ..... [X] Yes [ ] No [ ] Unknown

Are any buried? ..... [ ] Yes [X] No [ ] Unknown

Are all sleeved? ..... [ ] Yes [ ] No [X] Unknown

Chimney(s): ..... [X] Yes [ ] No

If Yes, are they lined: ..... [ ] Yes [ ] No [X] Unknown

Is more than one heat source vented through one flue? ..... [ ] Yes [X] No [ ] Unknown

Had a chimney fire: ..... [ ] Yes [X] No [ ] Unknown

Has chimney(s) been inspected? ..... [ ] Yes [ ] No [X] Unknown

If Yes, date: _____

Date chimney(s) last cleaned: **UNK**

Direct and/or Power Vent(s): ..... [ ] Yes [X] No [ ] Unknown

~~Has vent(s) been inspected~~? ..... [ ] Yes [ ] No [ ] Unknown

If Yes, date: _____

Comments: **Chimney needs Crown Cap**

Source of Section III information: **Personal Rep**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ..... [ ] Yes [ ] No [X] Unknown

If ~~Yes, are tanks in current use?~~ ..... [ ] Yes [ ] No [ ] Unknown

If no longer in use, how long have they been out of service? _____

~~If tanks are no longer in use, have tanks been abandoned according to DEP~~? [ ] Yes [ ] No [ ] Unknown

Are tanks registered with DEP? ..... [ ] Yes [ ] No [ ] Unknown

~~Age of tank(s):~~ _____ ~~Size of tank(s)~~: _____

~~Location:~~ _____

Initial KK PR

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

~~What materials are, or were, stored in the tank(s)?~~

~~Have you experienced any problems such as leakage: ...~~ ☐ Yes ☐ No ☐ Unknown

Comments: **Personal Representative has no knowledge of underground tanks**

Source of information: **Personal Representative**

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☐ No ☒ Unknown

In the ceilings? ☐ Yes ☐ No ☒ Unknown

In the siding? ☐ Yes ☐ No ☒ Unknown

In the roofing shingles? ☐ Yes ☐ No ☒ Unknown

In flooring tiles? ☐ Yes ☐ No ☒ Unknown

Other: ☐ Yes ☐ No ☒ Unknown

Comments: **PR has never lived at property. Has no knowledge of Asbestos.**

Source of information: **Personal Representative**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **10/2** By: **First Light Home Inspections**

Results: **Average 2.1 pCi/L Maximum 3.9 pCi/L**

If applicable, what remedial steps were taken? **NA**

~~Has the property been tested since remedial steps?~~ ☐ Yes ☐ No ☐ Unknown

Are test results available? ☒ Yes ☐ No

Results/Comments: **See Attached Report**

Source of information: **First Light Home Inspections**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **10/2** By: **First Light Home Inspections**

Results: **<150 pCi/L**

If applicable, what remedial steps were taken? **NA**

~~Has the property been tested since remedial steps?~~ ☐ Yes ☐ No ☐ Unknown

Are test results available? ☒ Yes ☐ No

Results/Comments: **See Attached Report**

Source of information: **First Light Home Inspections/NE Labs**

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: **None**

Source of information: **Personal Representative**

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

F. LEAD-BASED PAINT/PAINT HAZARDS - *(Note: Lead-based paint is most commonly found in homes constructed prior to 1978)*

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? ..... ☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: **NA**

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: **NA**

Are you aware of any cracking, peeling or flaking paint? ..... ☒ Yes ☐ No

Comments: **Back Porch**

Source of information: **Agent**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL:	☐ Yes	☐ No	☒ Unknown
LAND FILL:	☐ Yes	☐ No	☒ Unknown
RADIOACTIVE MATERIAL:	☐ Yes	☐ No	☒ Unknown

Other: **na**

Source of information: **Personal Representative has no knowledge of Hazardous Materials**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **na**

Source of information: **Personal Representative**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? **NA**

Road Association Name (if known): **NA**

Source of information: **Public Records**

Initial KK PR

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

(1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or

(2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **NA**

Have any flood events affected a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **NA**

Has any flood-related damage to a structure occurred on the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **NA**

Has there been any flood insurance claims filed for a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: **NA**

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? …… ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: **NA**

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ……... ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

NA

Relevant Panel Number: **23031C0281G** Year: **2024** (Attach a copy)

Comments: **None**

Source of Section VI information: **Public Records**

Initial KK PR

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?..... [X] Yes [ ] No [ ] Unknown

If Yes, explain: **Homestead**

Is a Forest Management and Harvest Plan available?..... [ ] Yes [X] No [ ] Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... [ ] Yes [X] No [ ] Unknown

If Yes, explain: **NA**

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, solar panels, wind turbines): Type: **Propane Tank**

From Whom: **Eastern Propane**

Year Principal Structure Built: **1860s?** What year did Seller acquire property? **1958**

Roof: Year Shingles/Other Installed: **2024**

Water, moisture or leakage: **No**

Comments: **Personal Representative has no knowledge or moisture or leakage. Age of home unknown, PR was told maybe 1860s.**

Foundation/Basement:

Is there a Sump Pump? ..... [X] Yes [ ] No [ ] Unknown

Water, moisture or leakage since you owned the property: ..... [ ] Yes [ ] No [X] Unknown

Prior water, moisture or leakage? ..... [ ] Yes [ ] No [X] Unknown

Comments: **Personal Rep has no knowledge or moisture, but it is a dirt/stone basement. Crawl Space needs moisture barrier. Basement needs new support posts.**

Mold: Has the property ever been tested for mold? ..... [ ] Yes [ ] No [X] Unknown

~~If Yes, are test results available~~? ..... [ ] Yes [ ] No

Comments: **None**

Electrical: [ ] Fuses [X] Circuit Breaker [ ] Other: _____ [ ] Unknown

Comments: **100 AMP**

Has all or a portion of the property been surveyed? ..... [ ] Yes [X] No [ ] Unknown

~~If Yes, is the survey available~~? ..... [ ] Yes [ ] No [ ] Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... [ ] Yes [X] No [ ] Unknown

Modular ..... [ ] Yes [X] No [ ] Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... [ ] Yes [X] No [ ] Unknown

Comments: **None**

Initial KK PR

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 24CC1779-2D36-8AD5-823F-D1C6B07E1B6C

PROPERTY LOCATED AT: **98 Salmon Falls Rd, Hollis,**

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **Please see attached Pre-Inspection for any updates that may be needed to home.**

Comments: **PR has never resided at property. Has limited knowledge of property.**

Source of Section VII information: **Personal Representative**

SECTION VIII - ADDITIONAL INFORMATION

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... [X] Yes [ ] No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by:
Kathleen Kendrick Pers. rep
050F33AE414887A...

SELLER	DATE	SELLER	DATE 11/5/2026
Estate of Shirley Walker,		**Kathleen Kendrick, PR**	
SELLER	DATE	SELLER	DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
BUYER	DATE	BUYER	DATE

Maine Association of REALTORS®/Copyright © 2026.
All Rights Reserved. Revised August 2026.

REALTOR®

EQUAL HOUSING OPPORTUNITY

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com