FORM F Rev. 07/11a

SOIL PROFILE / CLASSIFICATION INFORMATION

DETAILED DESCRIPTION OF SUBSURFACE CONDITIONS AT PROJECT SITES

Project Name:	Applicant Name:	Project Location (municipality):
Snow Farm Road Subdivision	Bill Troiano	Nobleboro

Exploration Symbol # TB-1.1 ☐ Test Pit ☒ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. 97

24 " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0	Fine Sandy Loam	Friable	Brown	None
10			Yellow Brown	
20		Firm	Olive Brown	Few Faint
30				
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	
3 Profile / C Condition	4 Percent	18 " Depth	☐ Groundwater ☒ Restrictive Layer ☐ Bedrock

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

Exploration Symbol # TB-1.2 ☐ Test Pit ☒ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. 107

18 " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0	Fine Sandy Loam	Friable	Brown	None
10			Yellow Brown	
20		Bedrock		
30				
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	
3 Profile / AIII Condition	8 Percent	18 " Depth	☐ Groundwater ☐ Restrictive Layer ☒ Bedrock

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

Exploration Symbol # TB-1.3 ☐ Test Pit ☒ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. 102

36 " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0	Fine Sandy Loam	Friable	Brown	None
10	Sandy Loam		Yellow Brown	
20				
30	Coarse Sandy Loam		Olive Brown	Common
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	
2 Profile / C Condition	3 Percent	22 " Depth	☒ Groundwater ☐ Restrictive Layer ☐ Bedrock

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

Exploration Symbol # TB-1.4 ☐ Test Pit ☒ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. 99

36 " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0	Fine Sandy Loam	Friable	Brown	None
10	Sandy Loam		Yellow Brown	
20				
30	Coarse Sandy Loam		Olive Brown	Common
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	
2 Profile / C Condition	4 Percent	22 " Depth	☒ Groundwater ☐ Restrictive Layer ☐ Bedrock

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

INVESTIGATOR INFORMATION AND SIGNATURE

Signature	Date 4/1/2025
Name Printed Joseph Stevenson	Cert/Lic/Reg. # 416

Title ☒ Licensed Site Evaluator ☐ Certified Soil Scientist ☐ Certified Geologist ☐ Professional Engineer

STATE OF MAINE
JOSEPH F. STEVENSON
LSE 416
LICENSED SITE EVALUATOR

FORM F Rev. 07/11a

SOIL PROFILE / CLASSIFICATION INFORMATION

DETAILED DESCRIPTION OF SUBSURFACE CONDITIONS AT PROJECT SITES

Project Name:	Applicant Name:	Project Location (municipality):
Snow Farm Road Subdivision	Bill Troiano	Nobleboro

Exploration Symbol # TB- 1.5 ☐ Test Pit ☒ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. 97

24 " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0	Fine Sandy Loam	Friable	Brown	None
10	Sandy Loam		Yellow Brown	
20			Olive Brown	Common
30	Boulders			
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	Groundwater	Restrictive Layer	Bedrock
2 Profile / C Condition	3 Percent	18 " Depth	☒	☐	☐

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

Exploration Symbol # _____ ☐ Test Pit ☐ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. _____

_____ " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0				
10				
20				
30				
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	Groundwater	Restrictive Layer	Bedrock
Profile / Condition	Percent	Depth "	☐	☐	☐

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

Exploration Symbol # _____ ☐ Test Pit ☐ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. _____

_____ " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0				
10				
20				
30				
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	Groundwater	Restrictive Layer	Bedrock
Profile / Condition	Percent	Depth "	☐	☐	☐

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

Exploration Symbol # _____ ☐ Test Pit ☐ Boring ☐ Probe

_____ " Organic horizon thickness Ground surface elev. _____

_____ " Depth of exploration or to refusal

Depth below mineral soil surface (inches)	Texture	Consistency	Color	Redox Features
0				
10				
20				
30				
40				
50				
60				

Soil Details by S.E. ▸▸ S.S. ▸▸

Soil Classification	Slope	Limiting Factor	Groundwater	Restrictive Layer	Bedrock
Profile / Condition	Percent	Depth "	☐	☐	☐

Soil Series/Phase Name: ☐ Hydric ☐ Non-hydric Hydrologic Soil Group

INVESTIGATOR INFORMATION AND SIGNATURE

Signature	Date 4/1/2025
Name Printed Joseph Stevenson	Cert/Lic/Reg. # 416

Title ☒ Licensed Site Evaluator ☐ Certified Soil Scientist ☐ Certified Geologist ☐ Professional Engineer

STATE OF MAINE JOSEPH F. STEVENSON LSE 416 SITE EVALUATOR