Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

PROPERTY LOCATED AT: **6 Snowhill Lane, South Thomaston, ME 04858**

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☐ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any):	☐ N/A	☐ Yes	☒ No	☐ Unknown
Quantity:		☐ Yes	☒ No	☐ Unknown
Quality:		☐ Yes	☒ No	☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ..... ☐ Yes ☒ No

~~If Yes, Date of most recent test: _____ Are test results available? .. ☐ Yes ☐ No~~

~~To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? ..... ☐ Yes ☐ No~~

~~If Yes, are test results available? ..... ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem? _____~~

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: **Across driveway from front of house in middle of garden bed**

Installed by: **Knowlton**

Date of Installation: **Unknown**

USE: Number of persons currently using system: **2**

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: **Water treatment system is not in use. It's for iron & manganese. Softener for hard water.**

Source of Section I information: **Seller, Broker Observation**

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected? ..... ☐ Yes ☐ No~~

~~If Yes, what results: _____~~

~~Have you experienced any problems such as line or other malfunctions? ..... ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____
☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☒ 500 Gallon ☐ 1000 Gallon ☒ Unknown ☐ Other: _____

Tank Type: ☐ Concrete ☐ Metal ☐ Unknown ☒ Other: **2-250 gal. terra cotta tanks**

Location: **outside kitchen window** OR ☐ Unknown

Date installed: **Unknown** Date last pumped: **2008** Name of pumping company: **Interstate Septic**

Have you experienced any malfunctions? ..... ☒ Yes ☐ No

If Yes, give the date and describe the problem: **Recent inspection indicated system has failed and needs replacement.**

Date of last servicing of tank: **Unknown** Name of company servicing tank: **Interstate Septic**

Leach Field: ..... ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **Back of house**

Date of installation of leach field: **Unknown** Installed by: **Unknown**

Date of last servicing of leach field: **Unknown** Company servicing leach field: **Unknown**

Have you experienced any malfunctions? ..... ☒ Yes ☐ No

If Yes, give the date and describe the problem and what steps were taken to remedy: **Recent inspection indicated system has failed and needs replacement.**

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ No

If Yes, are they available? ..... ☐ Yes ☒ No

Is System located in a Shoreland Zone? ..... ☐ Yes ☒ No ☐ Unknown

Comments: **Septic system has failed and will need replacement.**

Source of Section II information: **Seller**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	**FHA**	**Electric-Studio above barn**	**Propane/Oven & Stove**	
Age of system(s) or source(s)	**2008**	**Unknown**	**Unknown**	
TYPE(S) of Fuel	**Oil**		**Propane**	
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	**01/2025-12-2025 831 Gal**		**277 gal.**	
Name of company that services system(s) or source(s)	**Maritime Energy**		**Maritime Energy**	
Date of most recent service call	**06/20/2025**			
Malfunctions per system(s) or source(s) within past 2 years	**None**		**None**	
Other pertinent information				

Are there fuel supply lines? ..... [X] Yes [ ] No [ ] Unknown
Are any buried? ..... [ ] Yes [X] No [ ] Unknown
Are all sleeved? ..... [X] Yes [ ] No [ ] Unknown
Chimney(s): ..... [X] Yes [ ] No
If Yes, are they lined: ..... [X] Yes [ ] No [ ] Unknown
Is more than one heat source vented through one flue? ..... [ ] Yes [X] No [ ] Unknown
Had a chimney fire: ..... [ ] Yes [X] No [ ] Unknown
Has chimney(s) been inspected? ..... [ ] Yes [X] No [ ] Unknown
~~If Yes, date:~~ _____
Date chimney(s) last cleaned: **Unknown**
Direct and/or Power Vent(s): ..... [ ] Yes [X] No [ ] Unknown
Has vent(s) been inspected? ..... [ ] Yes [X] No [ ] Unknown
~~If Yes, date:~~ _____

Comments: **Furnace chimney is lined. Not sure about other.**
Source of Section III information: **Seller/Old invoice when work was done in 2008**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ..... [ ] Yes [X] No [ ] Unknown
~~If Yes, are tanks in current use?~~ ..... [ ] Yes [ ] No [ ] Unknown
~~If no longer in use, how long have they been out of service?~~ _____
~~If tanks are no longer in use, have tanks been abandoned according to DEP?~~ [ ] Yes [ ] No [ ] Unknown
~~Are tanks registered with DEP?~~ [ ] Yes [ ] No [ ] Unknown
~~Age of tank(s):~~ _____ ~~Size of tank(s):~~ _____
~~Location:~~ _____

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

~~What materials are, or were, stored in the tank(s)?~~

~~Have you experienced any problems such as leakage:~~ ☐ Yes ☐ No ☐ ~~Unknown~~

~~Comments:~~

Source of information: **Seller**

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work?	☐ Yes	☐ No	☒ Unknown
In the ceilings?	☐ Yes	☐ No	☒ Unknown
In the siding?	☐ Yes	☐ No	☒ Unknown
In the roofing shingles?	☐ Yes	☐ No	☒ Unknown
In flooring tiles?	☐ Yes	☐ No	☒ Unknown
Other:	☐ Yes	☐ No	☒ Unknown

~~Comments:~~

Source of information: **Seller**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

~~If Yes: Date: By:~~

~~Results:~~

~~If applicable, what remedial steps were taken?~~

~~Has the property been tested since remedial steps?~~ ☐ ~~Yes~~ ☐ ~~No~~ ☐ ~~Unknown~~

~~Are test results available?~~ ☐ ~~Yes~~ ☐ ~~No~~

~~Results/Comments:~~

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

~~If Yes: Date: By:~~

~~Results:~~

~~If applicable, what remedial steps were taken?~~

~~Has the property been tested since remedial steps?~~ ☐ ~~Yes~~ ☐ ~~No~~ ☐ ~~Unknown~~

~~Are test results available?~~ ☐ ~~Yes~~ ☐ ~~No~~

~~Results/Comments:~~

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

~~Comments:~~

Source of information: **Seller**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

F. LEAD-BASED PAINT/PAINT HAZARDS - *(Note: Lead-based paint is most commonly found in homes constructed prior to 1978)*

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? ..... ☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: **Home predates 1978**

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe:

Are you aware of any cracking, peeling or flaking paint? ..... ☒ Yes ☐ No

Comments: **Several areas around the exterior of the house**

Source of information: **Seller, Broker Observation**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL:	☐ Yes	☒ No	☐ Unknown
LAND FILL:	☐ Yes	☒ No	☐ Unknown
RADIOACTIVE MATERIAL:	☐ Yes	☒ No	☐ Unknown

Other:

Source of information: **Seller**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **ROW through property for Snow Hill Lane. Easement for subidivision leach field.**

Source of information: **Deeds, Seller**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? **Snowhill Lane Road Association**

Road Association Name (if known): **Snowhill Lane Road Association. Seller contributes on average $500 yr. and has voting rights.**

Source of information: **Seller**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

(1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or

(2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? …… ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? …….. ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

_____

Relevant Panel Number: **23013C0361D** Year: **2016** (Attach a copy)

Comments: **No hazards**

Source of Section VI information: **FIRMette**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **Propane Tanks-Maritime Energy**

Year Principal Structure Built: **1860** What year did Seller acquire property? **2013**

Roof: Year Shingles/Other Installed: **Unknown**

Water, moisture or leakage: **Occassional leak in kitchen and around back kitchen door. Also south side of main roof (temporary repair)**

Comments: _____

Foundation/Basement:

Is there a Sump Pump? ..... ☒ Yes ☐ No ☐ Unknown

Water, moisture or leakage since you owned the property: ..... ☒ Yes ☐ No ☐ Unknown

Prior water, moisture or leakage? ..... ☒ Yes ☐ No ☐ Unknown

Comments: **Recent new pump**

Mold: Has the property ever been tested for mold? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ..... ☐ Yes ☒ No

Comments: _____

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: _____

Has all or a portion of the property been surveyed? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ..... ☐ Yes ☒ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... ☐ Yes ☒ No ☐ Unknown

Modular ..... ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... ☐ Yes ☒ No ☐ Unknown

Comments: **There is a mortgage survey available**

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: C5905B50-85D6-86A5-8248-39F2ABA0D3CD

PROPERTY LOCATED AT: **6 Snowhill Lane, South Thomaston, ME 04858**

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **Much of the property in need of restoration. Being sold "as-is"**

Comments:

Source of Section VII information: **Seller, Broker Observation**

SECTION VIII - ADDITIONAL INFORMATION

Gas log stove needs replacement, not to code and can no longer get parts. One upstairs bathroom has hot water only in shower. Dishwasher has been disconnected. Many cracks in the plaster, some window sills need replacing, wooden gutters are rotting, decks need replacing.
Property being sold "as-is"

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by: SYMON F. RANKINE 8/14/2026
SELLER F1384BB7C99433... DATE
Symon F. Rankine

Signed by: Sarah Dunne 8/14/2026
SELLER DF7B38321EC400... DATE
Sarah Dunne

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

Maine Association of REALTORS®/Copyright © 2025.
All Rights Reserved. Revised October 2025.
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com