Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

PROPERTY LOCATED AT: **74 Hinkley Rd, Livermore, ME 04253**

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): ..... ☐ N/A ☐ Yes ☒ No ☐ Unknown
Quantity: ..... ☐ Yes ☒ No ☐ Unknown
Quality: ..... ☒ Yes ☐ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ..... ☒ Yes ☐ No

If Yes, Date of most recent test: **2021** Are test results available? .. ☒ Yes ☐ No

To your knowledge, have any test results ever:

a) Been reported as unsatisfactory or satisfactory with notation?..... ☒ Yes ☐ No
b) Detected perfluoroalkyl and polyfluoroalkyl (PFA) substances? ☐ Yes ☒ No

If Yes to (a) and/or (b) above, are test results available? ..... ☒ Yes ☐ No

What steps were taken to remedy the problem? **Iron slightly elevated. All else within limits no action taken, PFA not**

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: **Front left of camp when looking at camp from the road**

Installed by: **Goodwin Well**

Date of Installation: **5+/- Years Ago**

USE: Number of persons currently using system: **4**

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: **Well is located on camp's 5.48 acres and currently provides water to only the home not the camp. Could be connected to camp in the future if Buyer desires.**

Source of Section I information: **Seller**

Buyer Initials _____ _____ _____ _____ Seller Initials Initial FB Initial kDT _____ _____

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

PROPERTY LOCATED AT: **74 Hinkley Rd, Livermore, ME 04253**

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected? ..... ☐ Yes ☐ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ..... ☐ Yes ☐ No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: **Back of the home off the breezeway** OR ☐ Unknown

Date installed: **2022** Date last pumped: **NA** Name of pumping company: **NA**

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

If Yes, give the date and describe the problem: **NA**

Date of last servicing of tank: **NA** Name of company servicing tank: **NA**

Leach Field: ..... ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **Back of the home off the breezeway**

Date of installation of leach field: **2022** Installed by: **Justin Knox with Terry Pinkham inspecting and Approved**

Date of last servicing of leach field: **NA** Company servicing leach field: **NA**

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: **NA**

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ..... ☒ Yes ☐ No

Is System located in a Shoreland Zone? ..... ☐ Yes ☒ No ☐ Unknown

Comments: **Home septic information above. Seller has a septic design for the camp that has not been installed.**

Source of Section II information: **Seller**

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com Bellefleur &

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

PROPERTY LOCATED AT: **74 Hinkley Rd, Livermore, ME 04253**

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	**FHA**	**Propane Fireplace**	**Pellet Stove**	**Camp Woodstove**
Age of system(s) or source(s)	**2022**	**2022**	**2025**	**2022**
TYPE(S) of Fuel	**Propane**	**Propane**	**Pelletts**	**Wood**
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	**800+/- Gal**	**included in FHA**	**2.5 Tons**	**Very little - Sellers heat for a day at a time**
Name of company that services system(s) or source(s)	**Suburban**	**Suburban**	**Don's Stove Shop**	**None**
Date of most recent service call	**2024**	**2026**	**2026**	**None**
Malfunctions per system(s) or source(s) within past 2 years	**None**	**None**	**None**	**None**
Other pertinent information	**None**	**None**	**Upgraded with Computerized Control of Heating**	**None**

Are there fuel supply lines? ..... [X] Yes [ ] No [ ] Unknown

Are any buried? ..... [X] Yes [ ] No [ ] Unknown

Are all sleeved? ..... [X] Yes [ ] No [ ] Unknown

Chimney(s): ..... [X] Yes [ ] No

If Yes, are they lined: ..... Metalbestos Chimney ..... [ ] Yes [ ] No [ ] Unknown

Is more than one heat source vented through one flue? ..... [ ] Yes [X] No [ ] Unknown

Had a chimney fire: ..... [ ] Yes [X] No [ ] Unknown

Has chimney(s) been inspected? ..... [X] Yes [ ] No [ ] Unknown

If Yes, date: **2022**

Date chimney(s) last cleaned: **2022**

Direct and/or Power Vent(s): ..... [X] Yes [ ] No [ ] Unknown

Has vent(s) been inspected? ..... [X] Yes [ ] No [ ] Unknown

If Yes, date: **2026**

Comments: **3 Heating options for home. Propane FP is primary heating source used. Wood Stove heats Camp**

Source of Section III information: **Seller**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ..... [ ] Yes [X] No [ ] Unknown

If Yes, are tanks in current use? ..... [ ] Yes [ ] No [ ] Unknown

If no longer in use, how long have they been out of service? _____

If tanks are no longer in use, have tanks been abandoned according to DEP? [ ] Yes [ ] No [ ] Unknown

Are tanks registered with DEP? ..... [ ] Yes [ ] No [ ] Unknown

Age of tank(s): _____ Size of tank(s): _____

Location: _____

Initial FB Initial kDT

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

What materials are, or were, stored in the tank(s)?

Have you experienced any problems such as leakage: ..... ☐ Yes ☐ No ☐ Unknown

Comments: **Seller is not aware of Underground Storage tanks at the home.**

Source of information: **Seller**

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work?	☐ Yes	☒ No	☐ Unknown
In the ceilings?	☐ Yes	☒ No	☐ Unknown
In the siding?	☐ Yes	☒ No	☐ Unknown
In the roofing shingles?	☐ Yes	☒ No	☐ Unknown
In flooring tiles?	☐ Yes	☒ No	☐ Unknown
Other: _____	☐ Yes	☒ No	☐ Unknown

Comments: **Home built in 2022**

Source of information: **Seller**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ..... ☐ Yes ☒ No ☐ Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☐ Unknown

Are test results available? ..... ☐ Yes ☐ No

Results/Comments: **Property built on a slab**

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ..... ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **2022** By: **State of Maine**

Results: **Under EPA limits**

If applicable, what remedial steps were taken? **NA**

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☐ Unknown

Are test results available? ..... ☐ Yes ☒ No

Results/Comments: **Seller reports Radon air limits below EPA standards when tested**

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: **Seller is not aware of any methamphetamine at the home**

Source of information: **Seller**

Buyer Initials _____ _____ _____ _____

Seller Initials Initial FB Initial KDT _____ _____

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

F. LEAD-BASED PAINT/PAINT HAZARDS - *(Note: Lead-based paint is most commonly found in homes constructed prior to 1978)*

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? ..... ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

~~If Yes, describe location and basis for determination:~~

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: **Home built 2022**

Are you aware of any cracking, peeling or flaking paint? ..... ☐ Yes ☒ No

Comments: **None**

Source of information: **Seller**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL:	☐ Yes	☒ No	☐ Unknown
LAND FILL:	☐ Yes	☒ No	☐ Unknown
RADIOACTIVE MATERIAL:	☐ Yes	☒ No	☐ Unknown

Other: **Seller is not aware of any other hazardous materials at the home**

Source of information: **Seller**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **Deeded First Right of Refusal & Right of Way**

Source of information: **Deed & Seller**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? **Homeowners on "driveway" which is shared ROW Hinkley is publicly maintained**

Road Association Name (if known): **NA**

Source of information: **Seller**

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

(1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or

(2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ……. ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ……... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? …… ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ……... ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

NA

Relevant Panel Number: **23001C0029E** Year: **7/8/2013** (Attach a copy)

Comments: **Per FEMA Map property in Zone X**

Source of Section VI information: **FEMA**

Initial FB Initial KDT

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

PROPERTY LOCATED AT: **74 Hinkley Rd, Livermore, ME 04253**

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **Homestead & Veterans**

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **NA**

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, solar panels, wind turbines): Type: **3 Propane Tanks**

From Whom: **Suburban**

Year Principal Structure Built: **2022** What year did Seller acquire property? **2020**

Roof: Year Shingles/Other Installed: **2022**

Water, moisture or leakage: **None**

Comments: **None**

Foundation/Basement:

Is there a Sump Pump? ..... ☐ Yes ☐ No ☐ Unknown

Water, moisture or leakage since you owned the property: ..... ☐ Yes ☐ No ☐ Unknown

Prior water, moisture or leakage? ..... ☐ Yes ☐ No ☐ Unknown

Comments: **Built on a slab**

Mold: Has the property ever been tested for mold? ..... ☐ Yes ☒ No ☐ Unknown

~~If Yes, are test results available? ..... ☐ Yes ☐ No~~

Comments: **Seller is not aware of any mold at the property**

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: **200 AMP service**

Has all or a portion of the property been surveyed? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ..... ☒ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... ☒ Yes ☐ No ☐ Unknown

Modular ..... ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... ☐ Yes ☒ No ☐ Unknown

Comments: **Seller is not aware of any defects or hazardous materials at the home**

Initial FB Initial kDT

Produced with Lone Wolf Transact 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

PROPERTY LOCATED AT: **74 Hinkley Rd, Livermore, ME 04253**

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **Seller is not aware of any material defects at the home**

Comments: **None**

Source of Section VII information: **Seller**

SECTION VIII - ADDITIONAL INFORMATION

Seller built this home in 2022 and paid for every upgrade imaginable causing this home to be nicer than most stick built homes. Here are some examples: Upgraded Tie Downs. Ceramic Backsplash, Drywall Walls, 5/12 Roof Pitch 8' Flat Ceiling, Upgraded Siding, Ice Guard, Stretch 5 Feet (so the home is larger by 4 feet aka 26'8"X56'), Propane Furnace, R27 Floor Insulation, R39 Roof Insulation, Dix appliances, Continued... See Addendum Additional information 1

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... [X] Yes [ ] No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by: Faye Bellefleur 9/12/2026
DF1815258C14D5...
SELLER DATE
Faye Bellefleur

Signed by: Kenneth D Timberlake 9/12/2026
1812...
SELLER DATE
Kenneth D Timberlake

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

Maine Association of REALTORS®/Copyright © 2026.
All Rights Reserved. Revised August 2026.

Docusign Envelope ID: 20DFF8C7-C296-83E3-8233-91B568CF1EB5

ADDENDUM

PROPERTY: **74 Hinkley Rd, Livermore, ME 04253**

1) Additional information

Stone Fireplace, Propane Fireplace, 36" Interior Doors, Transom Window in Bath, 2 Extra Porch Lights, Ceiling Fan in Living Room, TV Jack, 40 Gallon Propane Water Heater, Tile Shower, Utility Cabinets, Decorative Panel Box, Sweater Box in Master, Dormer, 200 AMP Service, White Shake in Dormer, Insulated Auto-Vented Skirting, New Upgraded Front Door, Upgraded Flooring, Upgraded Closet Shelving, Oversized kitchen Island. Primary bedroom has a large en-suite bathroom with large tile shower and walk in closet. 4 Car garage 30'X36' attached to the home through a beautiful spray foam insulated breezeway heated by a 1 year old pellet stove. Insulated Garage Doors are 2@10'X9' and 1 @ 8'X9'. 4th door on garage is French Doors. Garage has LED lighting. Whole home generator serviced every year. Town has Camp and Home listed on the wrong acreage. R11-4A is Camp with 5.43 Acres and R11-4C is home with 1.82 acres. Properties are on the same deed and being sold together. Camp has septic design available (not installed). Well is on Camp lot R11--4A and serves only the home at this time. Buyer could connect camp to well if desired. This Disclosure is for Map R11 Lots 4A & 4C

Date: 9/12/2026

DocuSigned by:
Signature DF18151258C14D5...

Date: 9/12/2026

Signed by:
Signature 45D1A6FF01194D6...

Date:

Signature

Date:

Signature