

Radon Inspection Report

Test Location:

Alliance Home Inspections
3 Harbor View Dr
Stockton Springs ,

Test For:

Alliance Home Inspections
3 Harbor View Dr
Stockton Springs ,

Inspected By:

14 Carriage Lane
Hampden, ME 04444
207-290-1235
Lic/Cert. # smc-402

Test Result: Pass

Overall Average:

3.6 pCi/l

EPA Average:

3.7 pCi/l

Test Device Details:

Serial Number: 300003554
Model Number: 1028XP
Last Calibration: 10/24/2025
Next Calibration: 10/24/2026
Cal-Factors: 2.35
Motion Error: No

Test Site Condition:**Test Summary:**

<u>CRM Location:</u>	<u>Start:</u> 09/03/2026 08:02 AM	<u>Stop:</u> 09/05/2026 08:02 AM	<u>Interval:</u> 1 hr	<u>Duration:</u> 48 hr
*First 4 hrs of data excluded	<u>Min:</u>	<u>Max:</u>	<u>Average:</u>	<u>Measurement Units:</u>
Radon Concentration:	1.3	6.8	3.7	pCi/l

Comments:

Lic/Cert Signature

Test device manufactured by SunRADON, LLC

Inspection Report Date: 09/08/2026

Radon Inspection Chart



Test Table

* Data from first 4 hours excluded from EPA calculations

<u>Date/Time</u>	<u>Radon(pCi/l)</u>	<u>Flags</u>
09/03/26 09:02 AM	2.1	-
09/03/26 10:02 AM	1.3	-
09/03/26 11:02 AM	3.8	-
09/03/26 12:02 PM	3.8	-
09/03/26 01:02 PM	2.1	-
09/03/26 02:02 PM	6.0	-
09/03/26 03:02 PM	1.7	-
09/03/26 04:02 PM	4.3	-
09/03/26 05:02 PM	3.0	-
09/03/26 06:02 PM	2.6	-
09/03/26 07:02 PM	3.8	-
09/03/26 08:02 PM	3.0	-
09/03/26 09:02 PM	1.7	-
09/03/26 10:02 PM	4.7	-
09/03/26 11:02 PM	6.0	-
09/04/26 12:02 AM	1.3	-
09/04/26 01:02 AM	3.8	-
09/04/26 02:02 AM	5.1	-
09/04/26 03:02 AM	3.8	-
09/04/26 04:02 AM	3.8	-
09/04/26 05:02 AM	1.7	-
09/04/26 06:02 AM	4.7	-
09/04/26 07:02 AM	3.4	-
09/04/26 08:02 AM	2.6	-
09/04/26 09:02 AM	3.8	-
09/04/26 10:02 AM	6.8	-
09/04/26 11:02 AM	5.5	-
09/04/26 12:02 PM	6.4	-
09/04/26 01:02 PM	3.0	-
09/04/26 02:02 PM	1.7	-
09/04/26 03:02 PM	5.5	-
09/04/26 04:02 PM	3.8	-
09/04/26 05:02 PM	3.0	-
09/04/26 06:02 PM	3.4	-
09/04/26 07:02 PM	5.1	-
09/04/26 08:02 PM	2.6	-
09/04/26 09:02 PM	3.4	-
09/04/26 10:02 PM	3.0	-
09/04/26 11:02 PM	4.3	-
09/05/26 12:02 AM	2.6	-
09/05/26 01:02 AM	5.1	-
09/05/26 02:02 AM	4.7	-
09/05/26 03:02 AM	2.1	-
09/05/26 04:02 AM	2.6	-

Test Result: Pass

Test Location: 3 Harbor View Dr Stockton Springs ,

Inspection Report Date: 09/08/2026

Test device manufactured by SunRADON, LLC

Test Table

* Data from first 4 hours excluded from EPA calculations

<u>Date/Time</u>	<u>Radon(pCi/l)</u>	<u>Flags</u>
09/05/26 05:02 AM	3.0	-
09/05/26 06:02 AM	5.1	-
09/05/26 07:02 AM	2.1	-
09/05/26 08:02 AM	4.7	-

Test Result: Pass

Test Location: 3 Harbor View Dr Stockton Springs ,

Inspection Report Date: 09/08/2026

Test device manufactured by SunRADON, LLC

Radon Test Information

Maine Notice to Clients

As per 22 MRSA, Sec. 771, results of this test will be reported to the Maine Dept. of Health and Human Services. Any questions, comments, or complaints concerning individuals or firms providing radon related services in Maine should be directed to: Radiation Control Program 11 State House Station Augusta, ME 04333-0010 (207-287-5698).

Test Result: Pass

Test Location: 3 Harbor View Dr Stockton Springs ,

Inspection Report Date: 09/08/2026

Test device manufactured by SunRADON, LLC