

Onsite Wastewater Management Zone Evaluaton Report

The onsite wastewater system evaluation report will provide evidence that the system has been evaluated for compliance with current regulations. This onsite wastewater treatment and disposal system report is a true and complete record of the onsite wastewater treatment and disposal system on the date of the evaluation. No warranty is given or implied regarding the remaining life of this system.

Assessor's Parcel No. _____ Evaluation Date: 8/30/25
 Owners Name: For Shane Copeland
 Property Address: 13640 Ed Ct
 City, State, Zip: Magalia, Ca 95954
 Evaluator: Levi Magneson License No. 1034559

Septic Tank Observations

Access Riser(s) in Place	Yes
Sanitary Tree, Inlet	Yes
Scum Depth, Inlet Compartment	0 inches
Sludge Depth, Inlet Compartment	0 inches
Structural Tank Condition	Good
Liquid Operating Level	Normal
Baffle Condition	Good
Septic Tank Volume	1500 Gallons
Addl. Tank Volume	Gallons
Riser Condition	Good
Sanitary Tee, Outlet	Yes
Scum Depth, Outlet Compartment	0 inches
Sludge Depth, Outlet Compartment	0 inches
Tank Material	Concrete
Septic Tank Pumping Required	No
Was Septic Tank Pumped	No
Date Septic Tank(s) Previously Pumped	
Depth to Septic Tank Access Lid	0 inches
Effluent Pump	No

Absorption Field Observations

Effluent Line Diverter Valave	No
Well on Property	No
Common Area Absorption Field	No
Absorption Field Type	Standard
Surfacing Effluent	No
Hydraulic Load Test	Yes
Hydraulic Load Test Results	Good
Down Slope Seepage	No
Saturated Absorption Field	No
Multiple Systems	No
Graywater Discharge	No

Comments/Observations

Comments: Newer tank. System operating as intended at time of inspection.