

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 8505	Street Santa Cruz	City Atascadero	ZIP 93422	Date of Inspection 01/23/2026	Number of Pages 4
----------------------	----------------------	--------------------	--------------	----------------------------------	----------------------



## STORY TERMITES & PEST

P.O. BOX 2796  
Atascadero CA 93423  
(805) 347-4707 (805) 460-0650  
Storytermite@gmail.com

Report # : 17381  
Registration # : PR 9988  
Escrow # :  
 CORRECTED REPORT

Ordered by:	Property Owner and Party of Interest: Kirk Richardson 8505 Santa Cruz Atascadero CA 93422	Report sent to: Jaime Silveira Malik Real Estate Group 7450 Morro Rd. Atascadero CA 93422
-------------	--	---


COMPLETE REPORT       LIMITED REPORT       SUPPLEMENTAL REPORT       REINSPECTION REPORT

GENERAL DESCRIPTION: FURNISHED AND OCCUPIED TWO STORY STUCCO FRAMED RESIDENCE ON A RAISED FOUNDATION AND DETACHED TWO CAR GARAGE	Inspection Tag Posted: Meter Box
	Other Tags Posted:

An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.

Subterranean Termites       Drywood Termites       Fungus / Dryrot       Other Findings       Further Inspection   
**If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.**

### Diagram Not To Scale



Inspected By: Dave Story      State License No. OPR10259      Signature:

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.  
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov.      43M-41 (Rev. 04/2015)

# STORY TERMITE & PEST

Page 2 of 4 inspection report

8505	Santa Cruz	Atascadero	CA	93422
Address of Property Inspected		City	State	ZIP
01/23/2026	17381			
Date of Inspection	Corresponding Report No.		Escrow No.	

**WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.**

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

**The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.**

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

**NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.**

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

# STORY TERMITE & PEST

Page 3 of 4 inspection report

8505	Santa Cruz	Atascadero	CA	93422
Address of Property Inspected		City	State	ZIP
01/23/2026	17381			
Date of Inspection	Corresponding Report No.	Escrow No.		

**THIS IS A SEPARATED REPORT WHICH IS DEFINED AS SECTION I/SECTION II CONDITIONS EVIDENT ON THE DATE OF THE INSPECTION.**

**SECTION I** CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

**SECTION II** ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

**FURTHER INSPECTION** ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

The sub-floor is insulated below the substructure, This insulation could conceal infestations. We assume no responsibility for any infestations concealed by this insulation.



Finding 3A

## SECTION I:

### 3A - Fungus / Dryrot

FINDING-Fungus infection and damage noted at the door jamb of the side door.

RECOMMENDATION- Remove and replace approximately 6 to 8 inches of damaged door jamb as necessary.

## SECTION II:

### 4A - Other Findings

FINDING- Cracked or missing grout noted at the stall shower.

RECOMMENDATION- Owner to contact the proper trades for recommendation and repair.

### 4B - Other Findings

FINDING- Water stains noted at the attic framing around the roof jacks. It could not be determined if stains are caused from previous or current leakage.

RECOMMENDATION- Owner to contact the proper trades for recommendation and repair.

## OTHER:

### Note A

Note- A raised wood floor has been constructed in the substructure, making the area under the flooring inaccessible for inspection. No visible evidence of active infestation or infection noted to warrant further inspection. Parties of interest should satisfy themselves of this condition.



Finding 4A



Finding 4B

Recommendations not being performed by Story Termite & Pest must be inspected during the progress by a licensed Wood-destroying Pest and Organism Inspector. Story Termite & Pest is not responsible for, nor implies any knowledge as to the quality of work performed by others.

# STORY TERMITE & PEST

Page 4 of 4 inspection report

8505	Santa Cruz	Atascadero	CA	93422
Address of Property Inspected		City	State	ZIP
01/23/2026	17381			
Date of Inspection	Corresponding Report No.		Escrow No.	

**BY RELYING ON THIS WOOD DESTROYING ORGANISM REPORT YOU AGREE THAT ANY CONTROVERSY OR CLAIM ARISING OUT OF OR RELATING TO STORY TERMITE & PEST INSPECTION AND/OR THIS REPORT SHALL BE SETTLED BY ARBITRATION IN ACCORDANCE WITH THE CONSTRUCTION INDUSTRY ARBITRATION RULES OF THE AMERICAN ARBITRATION ASSOCIATION, AND JUDGMENT UPON THE AWARD RENDERED BY THE ARBITRATOR(S) MAY BE ENTERED IN ANY COURT HAVING JURISDICTION THEREOF.**

THANK YOU FOR CHOOSING STORY TERMITE & PEST. IF YOU HAVE ANY QUESTIONS OR CONCERNS PLEASE CONTACT US AT [805-347-4707](tel:805-347-4707)



STORY TERMITE & PEST

P.O. BOX 2796
Atascadero CA 93423
(805) 347-4707 (805) 460-0650
Storytermite@gmail.com

WORK AUTHORIZATION

Report #: 17381

No work will be performed until a signed copy of this agreement has been received.

Address of Property : 8505 Santa Cruz
City: Atascadero
State/ZIP: CA 93422

The inspection report of the company dated, 01/23/2026 is incorporated herein by reference as though fully set forth.
The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$ \_\_\_\_\_. This total amount is due and payable within 30 days from completion repair work and/or chemical application.

THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of ninety (90) days. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

ITEMS

Table with 5 columns: Prefix, Section I, Section II, Further Inspection, Other. Rows include 3A, 4A, 4B, Note A, Total, and GRAND TOTAL.

Property Owner: Date: Inspected By: Date:
Owner's Agent: Date:



**INVOICE / STATEMENT**

**STORY TERMITE & PEST**  
P.O. BOX 2796  
Atascadero CA 93423  
(805) 347-4707 (805) 460-0650  
Storytermite@gmail.com

Date: 01/23/2026  
Report Number: 17381  
Invoice Number: 17381-1  
Escrow Number:

Property 8505 Santa Cruz  
Inspected: Atascadero, CA 93422

Bill To: Kirk Richardson  
8505 Santa Cruz  
Atascadero, CA 93422

(909) 297-0977  
kvich7@gmail.com

Inspection fee: \$	100.00
<b>Invoice Total: \$</b>	<b>100.00</b>
Payments: \$	100.00
<b>Total Due: \$</b>	<b>0.00</b>

We appreciate your business!  
Paid Credit Card

RETAIN THIS COPY FOR YOUR RECORDS

Payments made by credit card may be subject to a 3.5% processing fee.

CUT HERE

CUT HERE

CUT HERE



**INVOICE / STATEMENT**

**STORY TERMITE & PEST**  
P.O. BOX 2796  
Atascadero CA 93423  
(805) 347-4707 (805) 460-0650  
Storytermite@gmail.com

Date: 01/23/2026  
Report Number: 17381  
Invoice Number: 17381-1  
Escrow Number:

Property 8505 Santa Cruz  
Inspected: Atascadero, CA 93422

Bill To: Kirk Richardson  
8505 Santa Cruz  
Atascadero, CA 93422

(909) 297-0977  
kvich7@gmail.com

Inspection fee: \$	100.00
<b>Invoice Total: \$</b>	<b>100.00</b>
Payments: \$	100.00
<b>Total Due: \$</b>	<b>0.00</b>

We appreciate your business!  
Paid Credit Card

RETURN THIS COPY WITH REMITTANCE

Payments made by credit card may be subject to a 3.5% processing fee.