

Seller Updates on 27061 Alabastro

(The fireplace is not functional. It has been capped and sellers do not plan to replace or fix it. They can provide reports about the issue upon request.)

2020:

- Replaced entire HVAC System
- Replaced water heater
- Replaced electrical panel

2021:

- Exterior Paint

2023:

- Hall Bath remodeled
- Built-Ins added in primary closet and kitchen “office” space

2024:

- Interior Paint