

Tuolumne County
Environmental Health Division

Office: 209-533-8440 Inspection Line: 209-533-6452

APN: 9A-320-14 EHD: 2007-00160
 Site Address: 20782 Buttercup Circle City: _____ Type System: _____
 Septic Contractor: Miller & Co. Phone: _____ Permit Issue Date: 5-1-07
 Consultant: _____ Phone: _____ Permit Expiration Date: 5-1-08
 Owners Name: Mullin # of Bedrooms: 3
 Comments: _____

Required if	INSPECTION	CONSTRUCTION APPROVALS				Correction Notice
		Consultant	Date	Inspector	Date	See Back of Card
	Site preparation, system layout					
<u>1/1</u>	Open Excavation (trenches and tank hole)			<u>DA</u>	<u>5/2/07</u>	
<u>1/1</u>	Open install (materials in trench, inspection risers)			<u>DA</u>	<u>5/27/07</u>	
<u>1/1</u>	Water tight test for septic tank and pump basin (pre-backfill)			<u>DA</u>	<u>4/7/07</u>	re-tested on 5/2/07 re-pumped on 5/21/07
	Final: special design/alternative systems (pressure test, alarm, monitoring wells)					re-tested on 4/2/07
	Other: drains, erosion control, etc.					

RE-INSPECTIONS WILL WARRANT ADDITIONAL FEES

FINAL APPROVED/CERTIFICATION TO CDD

Michael Mullin
ENVIRONMENTAL HEALTH SPECIALIST

4/10/09
DATE

POST IN A CONSPICUOUS LOCATION ON JOB SITE

-has to be re-tested