

DEBRIS REMOVAL FINAL SIGNOFF FORM WOOLSEY/HILL INCIDENT

DEBRIS REMOVAL FINAL SIGNOFF FORM

SITE ADDRESS: 26137 Fairside Rd Malibu LA California 90265 US

APN: 4457-010-028

Debris Removal Complete

☒ Yes ☐ No

Confirmation Sampling Approved

☒ Yes ☐ No

Erosion Control Complete

☒ Yes ☐ Waived

Erosion Control Level/BMP

 1 ☒ 2 3 (Please attached drawing for Level 3)

Debris Removal Project Approved

☒ Yes ☐ No

FINAL APPROVAL DATE: 2019-05-23

Noted Observations:

Front driveway intact but damaged. Back driveway intact. Two footings/piers left in place.

Retaining wall left in place. Garden wall damaged on corner. Back wooden stairway not burned,

left in place. Septic intact. Propane tank left in place. Erosion control in place. Statue of dog left


in garden. Unbroken window (auto) and rubber seal left in garden box.

Stephen Snavelly

Print Name



CalRecycle-Operations Chief



County of Los Angeles/County Ventura

WOOLSEY-HILL INCIDENT STRUCTURAL DEBRIS REMOVAL

CONFIRMATION SAMPLING – UNIFIED COMMAND APPROVAL FORM

SITE ADDRESS: 26137 FAIRSIDE RD APN: 4457-010-028

Sample Identification: WHI-4457-010-028-CF


Date(s) Sample Collected: 4/17/2019

Laboratory: Test America Laboratories, Inc.

Cleanup Goals: See the Background Sampling and Cleanup Goals for the Woolsey-Hill Incident. The cleanup goals are based on either the calculated soil background, US EPA Regional Screening Levels, and/or the California Environmental Protection Agency (CalEPA), California Human Health Screening Levels (CHHSLs; 2009).

Date Approved: 4/27/2019

Observations: 4/17/2019 A01, A02, A03, A04, A05, B01, B02, C01, D01



Joni Kropf
Joni Kropf, PG
Arcadis Senior Environmentalist



Todd Thalhamer
Todd Thalhamer, PE
CalRecycle Area Chief