


PERFORMANCE PUMPING

Septic Service • C-42 Certs
Leach Systems Repair & Replace
Sewer hook-Ups
Back Hoe & Dump Truck




45654 E. Florida Ave • Hemet, CA 92544

Septic Certification Map

Property Address:

23485 Marshall Rd

Perns CA 92570




SHED

TREE

CARAGE

PERFORMANCE PUMPING

Septic Service • C-42 Certs
Leach Systems Repair & Replace
Sewer hook-Ups
Back Hoe & Dump Truck



45654 E. Florida Ave • Hemet, CA 92544

Septic Tank Certification

Date of Inspection: 8-25-26

1. Certificate of existing subsurface-sewage disposal system

23485 Marshall

(Property Address)

(Owner's Name)

2. I examined the existing subsurface sewage disposal system at the above location on:

8/25/26 and determined the tank is 1,000 gallons.

3. A. Construction of septic tank:

Concrete ☒ Fiberglass ☐ Steel ☐ Other ☐

B. Condition of tank: (answer yes or no for each question)

	YES	NO
Inlet tee present?	☒	☐
Outlet tee present?	☒	☐
Two compartments?	☒	☐
Tank structure deteriorated?	☐	☒

If yes, briefly explain and indicate appropriate correction suggested:

4. A. Was the liquid level in the tank above the outlet tee?

Y ☒ N

B. Was the area around the lids oxidized?

Y ☒ N

C. Is the design of the system gravity fed?

Y ☒ N

D. Were wells observed on this or adjacent property?

Y ☒ N

If yes, indicate distance of well from:

Septic tank ☒ ft

Leach lines ☒ ft

Seepage pits ☒ ft

E. Flow tested leach system for 30 minutes:

Pass ☒ Fail ☐

f. Septic tank was pumped?

Yes ☒ No ☐

5. It is to my opinion that the system appears to be in good working order and can be expected to function properly with proper maintenance. Yes ☒ No ☐

If you have further questions, please contact us at the above address or phone.

I certify under the penalty of perjury that the following is true and correct.

Brad Hamby

C-42 license# 799834