



Analytical Report

Oilfield Environmental & Compliance, Inc.

Cari Thomas
Miller Drilling Company
329 North Main Street
Templeton, CA 93465

OEC Work Order: **2606873**

Report Date: **August 14, 2026 15:37**

Project: **Miller Drilling**

Number: **#31799 -- Gabriel Concepcion**

Enclosed is an analytical report for the above referenced project. The samples included in this report were received on August 12, 2026 12:35 and analyzed in accordance with the attached chain-of-custody.

Unless otherwise noted, all analytical testing was accomplished in accordance with the guidelines established in our Quality Manual, applicable standard operating procedures, and other related documentation. The results in this analytical report are limited to the samples tested and any reproduction thereof must be made in its entirety.

If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Authorized for release by:

Meredith Sprister, Business Director

msprister@oecusa.com

This laboratory is accredited in accordance with the recognised International Standard ISO/IEC 17025. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO/ILAC-IAF Communiqué dated April 2017)

307 Roemer Way, Suite 300
Santa Maria, CA 93454

Main: (805) 922-4772

Fax: (805) 925-3376



client.oec.com/reports
www.oecusa.com

TNI 2016 & ISO/IEC 17025:2017
CA-ELAP 2438, TNI 02666



Oilfield Environmental & Compliance, Inc.

Miller Drilling Company
329 North Main Street
Templeton CA, 93465

Project: Miller Drilling
Project Number: #31799 -- Gabriel Concepcion
Project Manager: Cari Thomas

WO & Reported:
2606873
08/14/2026 15:37

Sample Summary

Sample ID	Laboratory ID	Client Matrix	Lab Matrix	Date Sampled	Date Received
#31799 -- Gabriel Concepcion, 4470 Farousee Way	2606873-01	Drinking Water	Drinking Water	08/12/2026 08:00	08/12/2026 12:35

Sample Batch Preparation Summary

Analysis	Batch ID	Preparation Date/Time
Microbiological Parameters by APHA Standard Methods		
Coliform, Total P/A SM9223B	B6H0410	08/12/2026 14:22
E.coli P/A SM9223B	B6H0410	08/12/2026 14:22

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

CA-ELAP 2438, TNI02666
307 Roemer Way, Santa Maria, CA 93454

Client Connect: client.oec.com/reports
www.oecusa.com

TEL: (805) 922-4772
FAX: (805) 925-3376



Oilfield Environmental & Compliance, Inc.

Miller Drilling Company
329 North Main Street
Templeton CA, 93465

Project: Miller Drilling
Project Number: #31799 -- Gabriel Concepcion
Project Manager: Cari Thomas

WO & Reported:
2606873
08/14/2026 15:37

Analytical Report for Samples

Sample ID : **#31799 -- Gabriel Concepcion, 4470 Farousee Way**
Matrix : Drinking Water
Lab ID : 2606873-01

Sampled : 08/12/26 08:00
Sampled by :
Field Data : NA

Analyte	Result	RL	Units	Dilution	Batch	Analyzed	Method	Notes
---------	--------	----	-------	----------	-------	----------	--------	-------

Microbiological Parameters by APHA Standard Methods

Coliform, total	Absent	1.0		1	B6H0410	08/13/26 08:37	SM 9223B	
E. Coli	Absent	1.0	"	"	"	"	"	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

CA-ELAP 2438, TNI02666
307 Roemer Way, Santa Maria, CA 93454

Client Connect: client.oec.com/reports
www.oecusa.com

TEL: (805) 922-4772
FAX: (805) 925-3376



Oilfield Environmental & Compliance, Inc.

Miller Drilling Company
329 North Main Street
Templeton CA, 93465

Project: Miller Drilling
Project Number: #31799 -- Gabriel Concepcion
Project Manager: Cari Thomas

WO & Reported:
2606873
08/14/2026 15:37

Sample Method Summary

Analysis	Method	Matrix	Laboratory & Certification
----------	--------	--------	----------------------------

Microbiological Parameters by APHA Standard Methods

Coliform, Total P/A SM9223B	SM 9223B	Drinking Water	OEC, Internal
E.coli P/A SM9223B	SM 9223B	Drinking Water	OEC, Internal

Notes and Definitions

Qualifier	Definition
-----------	------------

MDL	Method Detection Limit
RL	Reporting Limit (Quantitation Limit)
ND	Analyte NOT DETECTED at or above the method limit (MDL)
RPD	Relative Percent Difference

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

CA-ELAP 2438, TNI02666
307 Roemer Way, Santa Maria, CA 93454

Client Connect: client.oec.com/reports
www.oecusa.com

TEL: (805) 922-4772
FAX: (805) 925-3376



Sample Receipt

Work Order Review is Complete

Work Order

2606873

Refresh

Client Name

Temp °C

Thermometer ID

Refrigerator(s)

COC Received

Login

Miller Drilling Company

3.5

3

MF

08 / 12 / 2026 12:35

08 / 12 / 2026 13:09

Recorded Corrected, Acceptable Range 0°C to 6°C (See Exception Notes Below)

Sample Transport

☒ OEECourier/Sampler

☐ After Hours Drop Off

☐ Delivery (Other than OEC)

☐ Shipment Carrier

Tracking#

Custody Seals

☒ None Present

Cooler(s)

☐ Present, Intact

☐ Present, Not Intact

☐ None

Sample(s)

☐ Present Intact

☐ Present, Not Intact

☐ None

Condition/Preservation

Yes No N/A

☒ Received On Ice Within Range (Acceptable)

☐ Received Outside Range(Acceptable)

☐ Direct from Field on Ice

☐ Ambient: Air or Filter Matrix

☐ Received Ambient, Placed on Ice

☐ Sample Temperature Accetable for Analysis

☐ Received Outside Range [Exception]*

☐ Insufficient Ice or Unknown

☐ Excessive Free Liquid

Completed COCs Received with Sample(s)

Correct Container(s) Preserve for Analysis

Container(s) Intact and Good Condition

Container Label(s) Consistent with COC

OEC Preservation Added**

Sample Quantity Sufficient

☒

☐

☒

☐

☒

☐

☒

☐

☒

☐

Containers, COC Changes, And/Or Corrections


Container ID (COC)	Container Description	Home	Matrix	Preservative	pH/Chlorine /Sulfur	Comments
01A	125mL Bacti Poly Na2S2O3, sterile (100mL fill)	Micro-Bio Fridge	Drinking Water			

Receipt Login By:

QGV-08/13/26 09:19

Receipt Reviewed By:

LGB-08/14/26 10:21



200873

Rev 02/09/2021

[illegible]



CHAIN OF CUSTODY

Page _____ of _____

[illegible]

