Excavating and Septic Service
530-514-4432
steve@eliteexcavatingandseptic.com

SEPTIC SYSTEM EVALUATION REPORT

Assessor's Parcel No. _____ Evaluation Date 6/24/25

Owner's Name: Barbera Wallin Phone No. 530-990-8662

Property Address: 4215 Paiute DR.

City, State, Zip: Oroville CA 95965

Mailing Address: _____

Evaluator: Steve Gonzales

SEPTIC TANK OBSERVATIONS

Access Riser(s) in Place	[ ] No	[✓] Yes
Sanitary Tee, Inlet	[ ] No	[✓] Yes
Scum Depth, inlet Compartment	0	Inches
Sludge Depth, Inlet Compartment	3	Inches
Structural Tank Condition	[✓] Good [ ] Fair	[ ] Poor
Liquid Operating Level	[ ] **High**	[✓] **Normal** [ ] **Low**
Baffle Condition	[✓] Good [ ] Fair	[ ] Poor
Septic Tank Volume	1200	Gallons
Addl. Tank Volume	0	Gallons
Riser Condition	[✓] Good [ ] Fair	[ ] Poor
Sanitary Tee, Outlet (Pump System)	[ ] No	[✓] Yes
Scum Depth, Outlet Compartment	0	Inches
Sludge Depth, Outlet Compartment	3	Inches
Tank Material	[✓] Concrete [ ] Poly/Fiberglass	[ ] Other
Septic Tank Pumping Required	[✓] **No**	[ ] **Yes**
Was Septic Tank Pumped	[✓] **No**	[ ] **Yes**
Date Septic Tank (s) Previously Pumped	N/A	Date
Depth To Septic Tank Access Lid	6"	Inches
Effluent Pump	[ ] No	[✓] Yes

ABSORPTION FIELD OBSERVATIONS


Effluent Line Diverter Valve	[✓] No	[ ] Yes
Well on Property	[ ] No	[✓] Yes
Common Area Absorption Field	[✓] No	[ ] Yes
Absorption Field Type	[ ] Standard	[✓] Alternative
Surfacing Effluent	[✓] **No**	[ ] **Yes**
Hydraulic Load Test	[ ] **No**	[✓] **Yes**
Hydraulic Load Test Results	[✓] **Excellent** [ ] **Good**	[ ] **Satisfactory**
	[ ] **Marginal** [ ] **Poor**	[ ] **FAILURE**
Down Slope Seepage	[✓] No	[ ] Yes
Saturated Absorption Field	[✓] **No**	[ ] **Yes**
Multiple Systems	[✓] No	[ ] Yes
Graywater Discharge	[✓] No	[ ] Yes

Repairs or Upgrades Required.....[✓] Yes [ ] No (If yes describe below)

All Repairs Complete and Paid

Comments/Recommendations: _____

Site Map:



[✓] PASS **[ ] FAILED**

Evaluators Signature: _____ **Date:** 6/24/25

Company License # 1100571

This onsite wastewater treatment and disposal system evaluation report is a true and complete record of the onsite wastewater treatment and disposal system on the date of the evaluation. No warranty is given or implied regarding the remaining life of the system. I certify that this onsite wastewater treatment and disposal system reflects conditions observed on the above property(s) during the routine inspection of the onsite wastewater treatment and disposal system.