


CURVE	DELTA ANGLE	RADIUS	ARC	TANGENT	CHORD	CHORD BEARING
C 1	02° 30' 00"	820.00'	35.78'	17.89'	35.78'	N 13° 27' 29" E
C 2	07° 53' 43"	25.00'	38.35'	24.10'	34.70'	N 50° 09' 02" E
C 3	10° 26' 23"	370.00'	106.16'	53.45'	105.80'	S 71° 41' 01" E
LINE	BEARING	DISTANCE				
L 1	S 63° 27' 50" E	12.03'				
L 2	S 20° 32' 39" W	57.66'				

- Notes:
1. Plot Scale: 1" = 20'
 2. Bases of bearings: Recorded Plat
 3. Easements for utilities CF 93-45801
 4. 5/8" iron rods found at all corners unless otherwise noted.
 5. Roads dedicated by recorded plat unless otherwise noted.




The property shown on this survey plat lies in Zone X as shown on FEMA Flood Map Panel 13000-001 dated 8/19/93. These maps are subject to changes, and may not reflect the actual on site flood conditions.

Lot 11, Block 2, of The Woodlands VILLAGE ON ALDEN BRIDGE, SECTION TWENTY-SIX (26), a subdivision in Montgomery County, Texas, according to the map of plat thereof recorded in Cabinet 11, Sheet 19-411 thru 186A, of the Map Records of Montgomery County, Texas.

Purchaser: Leonard Proctor and Belinda Proctor
100 Autumn Branch Drive
Address: The Woodlands, Texas 77302

GF No: 359630-Z Date: January 05, 1998
Job No: 07637



To: American Title and Advantage Home Mortgage
I, Michael Glezman, a Registered Professional Land Surveyor, State of Texas, hereby certify that the property has been surveyed on the ground under my supervision, is true and correct, the corner monuments have been found or set, that there are no encroachments or conflicts except as noted; this survey and professional services conform to the Texas Society of Professional Surveyors Standards and Specifications for a Category 1A, Condition III survey.
This drawing is the property of Glezman Surveying, Inc. and shall not be used for any purpose without the written consent of an authorized agent of Glezman Surveying, Inc. Glezman Surveying, Inc. accepts no responsibility for the use of this drawing for any purpose other than that for which it was prepared and for which it is intended.
Copyright 1997, Glezman Surveying, Inc.

Surveying Southwestern Texas since 1957
GLEZMAN SURVEYING, INC.
1110 N. Loop 336 W. Suite 210
Georgetown, Texas 77626
Office: (409) 786-5500 Home: (409) 444-5501

