Coello & Associates, Inc.

2122 South West Avenue
Waukesha, WI 53189

Phone: 262-650-1300
Fax: 262-650-1301

www.pouredfoundations.com

October 31, 2025

This letter is regarding the Southeast corner of the foundation located at 407 Century Oak Drive Waukesha, WI.

We have inspected the vertical crack in the southeast corner of the foundation. The crack is a standard shrinkage crack that started in a tie line and continued to the corner of the foundation. No substantial deflection has occurred, and no water has infiltrated the crack. There is a substantial amount of steel reinforcement in the corner of the foundation as well. We feel the foundation is structurally sound and will be for generations to come.

Please feel free to reach out with any questions.

Sincerely,

Nicholas Coello

Nicholas Coello
Account Manager