THE DETAILS

1183 Aspen Ct Grafton

Recent Home Improvements & Updates

• Exterior Painting & Wood Repair – Exterior painting completed along with wood repairs as needed.

• Interior Painting – Interior painting completed to refresh the home.

• Concrete Raising – Rear Patio Area – CRC Concrete Raising to level and improve the rear patio area. To be completed prior to closing.

• Window Glass & Seal Replacement – 11 window panes and seals replaced by Argo Glass & Window. To be completed prior to closing.

• Newer Carpeting Throughout – Newer carpeting throughout the home.