

1956 W WINDSOR CIRCLE | GLENDALE WI 53209

Home Updates

A list of improvements and replacements completed on the property (per seller)

Roof - Minor repairs (2023)

Kitchen - Windows replaced (2010)

Flooring - Upstairs primary bathroom (toilet room) new tile (2021)

HVAC - Regular maintenance

First floor furnace replaced 2021

Second floor furnace replaced 2021 | repaired September 2026

Water Heater - First floor hot water heater replaced 2016

Second floor hot water heater replaced 2021

Exterior paint and minor repairs (September 2026)