

(No Subject)

From: charbrenzel <charbrenzel@aol.com>

To: charbrenzel@aol.com

Date: Sep 20, 2026, 2:31 PM

Lake County Environmental Laboratory

IDPH Registry # 17541

Sample Must Reach Laboratory
within 24 Hours After Collection.

Date and Time in Laboratory:

8/6/26

Mail Report To

Collected:

-2

Name:

by:

Purpose:

BEACH PUMP & WELL

use by Community and Non-Community Supplies Only):

Address:
10453 BOYCE LANE

☐ Routine ☐ Replacement

City: State: Zip Code:
BEACH PARK, IL 60087

☐ New Construction

☐ Repeat:

☐ Invalid Sample:

Daytime Phone Number: 847-249-0628

Orig. Smpl. Lab

File No:

Facility e: ☐ Community Water Supply

☒ Individual Water Supply

Name of Facility:

(Please Check) ☐ Surface

☐ Non-Community Water Supply

PIN/County:

☒ Well

☐ Other: _____

email:

Sample kept chilled after collection? ☐ Yes

Temp. at lab _____ °C

Check Analysis Required:

MM0-MUG

2000

Nitrate Screen

Nitrate-Nitrite

Sample Site No. or Address

Sample
Point

Sample
Type*

Time
Collected

Res
C*

Laboratory Number

2000

1233 3rd Ave

SAMPLE
TAP ON D 7

-C

2000

Total coliform

E.coli

Volume, mL:

100

100

No. of Positive Cells L/S

0/0

0/0

MPN/100 mL

< 1

< 1

Opinion

☒ Satisfactory

Satisfactory

☐ Unsatisfactory

Nitrate Test: ☐ Satisfactory (<10 ppm) ☐ Unsatisfactory

☐ See Attached Report

Test Date:

Nitrate - Nitrite Test: ☐ See Attached Report

Repeat Sample Required for: ☐ Microbiology

☐ Nitrate

Reported By /

Reviewed

Notification for Unsatisfactory Results: Person Notified:

Date:

By: _____

Batch # BAH0135

Analysis start date / time: 8/6/26

13:34 CRM

Analysis end date/time: 8/7/26

0840 CRM

Sent from my Galaxy