

Property Updates & Features

5076 N 47th St

Milwaukee, WI 53218

01 Major Systems & Mechanicals

Electrical	New electrical system (2022)
Furnace	Replaced in 2015
Water heater	Replaced in 2015
Plumbing	Partial plumbing updates

02 Interior Features & Upgrades

Bathrooms	Fully updated
Lighting	Updated light fixtures throughout
Condition	Clean, well-maintained and move-in ready

03 Exterior & Parking

Garage	2-car garage
Backyard	Fully fenced

Updates, dates and condition descriptions were provided by the seller. Buyers should independently verify details. This summary supplements the listing information and does not replace the seller's Real Estate Condition Report.