

Back To Search

Municipality	<input type="text" value="Town of Rhine"/>	Parcel No.	<input type="text" value="59018254107"/>
Alternate Parcel No.	<input type="text"/>		
☐ Density Development Zone	Zoning District	<input type="text" value="R-1 (R-1)"/>	
Overlay District(s)	<input type="text"/>		
Site Address	<input type="text" value="W6077 BRADY LN"/>		
Additional Info	<input type="text" value="W6077 BRADY LN"/>		
Owner Name	Legal Description		
<input type="text" value="TANNER NM ROSSO"/>	<input type="text" value="PRT SW SW,SEC 16, LOT 2 CSM V5 P166, DESCRIBED AS COM S89 DEG 48'E 233.50'FROM NW COR CSM V5 P 118,TH S0 DEG 12'W 283.09',S89 DEG 48'E 233.50',N0 DEG 12'E 283.09', TH N89 DEG 48'W 233.50'TO BEG."/>		
Mailing Address	☐ Alternate Address		
<input type="text" value="TANNER NM ROSSO SAMANTHA C ROSSO W6077 BRADY LN ELKHART LAKE WI 53020-1529"/>			

<input type="text" value="Hearings"/>
<input type="text" value="Permits"/>



Sheboygan County

Permit Number 3069
Parcel Number 59018254107
Site Address W6077 BRADY LN
Maintenance Company Name Harper Pumping, LLC
Filed Date 08/26/2025
Filed By Andrew Harper
Service Date 05/15/2025
Gallons 1000

Component	Question	Response
-----------	----------	----------

Conventional

Effluent from POWTS was not discharging to the ground surface? True

No areas of dispersal component were found to have soft or spongy ground? True

Septic Tank(s)

Tank compartment(s) are structurally sound and watertight? True

Inlet and outlet baffles are present and in good condition? True

Manhole cover(s) located above grade have an effective locking device and/or riser(s) is(are) located below grade? True

No backflow was observed after pumping? True

No scaling of concrete in the tank and riser(s) present? True

Notes

Wednesday, October 7, 2026

[Return to search results](#)

Permit

Permit Type	Sanitary	Permit No.	3069	Application No.	
State Transaction		County No.			
Permit Subtype	New System	Additional Types			
Building Type	<None>	Addl. Explanation			
Original Applicant	WEISS, PAUL W				
Additional Info					
WI Fund Date		WI Fund Amount	0	☐ ISD	
Application Date		Issued On	10/12/1979	Expires On	10/11/1981
Permit Status	Approved	Permit Issuer	None		
Contact Phone		Contact Email			

Document

Properties

Powls System

System Type	Conventional	Installer	
Design Flow(gpd)	0	Soil Application Rate(gpdsf)	0
Soil Horizon ^d	None	System Elevation	0
Dispersal Area(sf): Req'd.	0	Proposed	0
Final Inspection	10/12/1979	Status	Active

	Capacity New	Capacity Existing	Total	Compartments	Tanks	Manufacturer	Type
Tank	1000		1000	1	1	Unknown	Prefab Concrete
Chamber			0				
Pretreatment			0				

Components

Components

Type	Manufacturer	Interval	Last Service	Next Service	Status	Description	Restricted Service
Septic Tank(s)	Unknown Manufacturer (concrete)	36	5/15/2025	5/15/2028	Current	1000	

Maintenance
Fees
Notices