SLABY SEPTIC SERVICE, LLC
S 2129 COUNTY RD E
WAUMANDEE, WI 54622
608-626-3371

DATE: 4-5-19

NAME: ReMax Sheryl

ADDRESS: W544 Co Rd P
Fountain City, Wi

TANK PUMPED AND INSPECTED ON 4-3-19
(date)

- [x] BAFFLES INSPECTED
- [ ] FILTER CLEANED
- [ ] CONDITION OF DRYWELL UNKNOWN
- [x] CONDITION OF DRAINFIELD UNKNOWN
- [ ] IN MY OPINION, THE SEPTIC SYSTEM WAS, ON THE DATE OF MY INSPECTION, IN GOOD WORKING ORDER AND IN COMPLIANCE WITH ALL APPLICABLE STATE AND LOCAL CODES.

COMMENTS: No Pump Chamber Alarm Found. Alarm box needs to be installed and working.

Thank You

Joe T. Slaby
Joe T. Slaby
DNR # 2022

This inspection does not express a guarantee that the system will not show signs of failure in the future as defined in Wisconsin Statutes 145.245.

SLABY SEPTIC SERVICE, LLC
S 2129 COUNTY RD E
WAUMANDEE, WI 54622
608-626-3371

****

DATE: 4-5-19

NAME: ReMax Sheryl

ADDRESS: W544 C Rd P
Fountain City, Wi

TANK PUMPED AND INSPECTED ON 4-3-19 (date).

☒ BAFFLES INSPECTED

☐ FILTER CLEANED

☐ CONDITION OF DRYWELL UNKNOWN

☒ CONDITION OF DRAINFIELD UNKNOWN

☐ IN MY OPINION, THE SEPTIC SYSTEM WAS, ON THE DATE OF MY INSPECTION, IN GOOD WORKING ORDER AND IN-COMPLIANCE WITH ALL APPLICABLE STATE AND LOCAL CODES.

COMMENTS: No Pump Chamber Alarm Found. Alarm box needs to be installed and working.

* New Alarm box has been Installed in Garage (4-15-19)

Thank You

Joe T. Slaby
Joe T. Slaby
DNR # 2022

Ken A. Kelle

This inspection does not express a guarantee that the system will not show signs of failure in the future as defined in Wisconsin Statutes 145.245.