State of Wisconsin
Department of Natural Resources
dnr.wi.gov

Property Transfer Well(s) and Pressure System(s) Inspection

Form 3300-221 (R 10/14)

Notice: Pursuant to ch. 280, Wis. Stats., and ch. NR 812, Wis. Adm. Code, this form shall be used to document any well and pressure system inspection conducted as part of a property transfer. Inspections are voluntary, and well owners are not required to bring systems into compliance as a result of the inspection. Inspectors must provide the completed form to the requester of the inspection. Do not send forms to DNR.

Contact Information

Inspection Requested By	Telephone Number
SHERYL REEDY	608-582-3338

Mailing Address	City	State	ZIP Code
	GALESVILLE	WI	54630

Owner's Name	Telephone Number
MICHELLE ABTS	

Mailing Address	City	State	ZIP Code
W544 CO. RD P	FOUNTAIN CITY	WI	54629

Property Location

County of Water System Location	Grid or Street Address or Road Name and Number (if available)	City	ZIP Code
BUFFALO	W544 CO. RD P	FOUNTAIN CITY	54629

Township	Gov't Lot #	¼ of the	¼	Section	Town N	Range E/W	Unique Well Number

Known Noncomplying Features

Identified noncomplying features are noted below with a check mark.

1. ☐ Unused Well Should be Filled and Sealed
2. ☐ Stovepipe or Thin-Walled Casing
3. ☐ Dug Well
4. ☐ Unprotected Buried Suction Line
5. ☐ Alcove (Subsurface Pumproom) or Pit
6. ☐ Non-Walkout Basement or Below-Grade Crawl Space Well
7. ☐ Poor Casing Condition (Badly Corroded or Cracked)
8. ☐ Contaminant Source less than minimum separation distance from well: _____
9. ☐ Well in Floodway or Flood Fringe
10. ☐ Well at Risk from Localized Flooding
11. ☐ Cross-Connection
12. ☐ Driven Point Well (installed after 1-31-1991) without construction report
13. ☐ Nonpressure Conduit
14. ☐ Hand Pump
15. ☐ Offset Pump or Piping Height < 12" Above Floor
16. ☐ Yard Hydrant
17. ☐ Materials for Pump and Supply Piping
18. ☐ Flowing Well Installation
19. ☐ Check Valve Location
20. ☐ Well Cap or Seal
21. ☐ Casing Height
22. ☐ Electrical Wires Not Properly Enclosed in Conduit
23. ☐ Sample Faucet is Missing or Incorrect
24. ☐ Casing less than 6" in diameter for a well in limestone, dolomite, shale, quartz or granite
25. ☐ Health/Safety Hazard

Comments

- ☐ Pre-1991 Driven Point Pipe Depth < 25 feet
- ☐ Well Construction Report Not on File or Unlocatable
- ☐ Well Located in Special Well Casing Depth Area
- ☐ Pre-1979 Two-Wire Submersible Pump
- ☐ Evidence of Some Corrosion on Well Casing Pipe
- ☐ Inaccessible or Difficult Location for Future Well Work
- ☐ Inaccessible or Difficult Location for Future Pump Work
- ☐ Non-Vermin-Proof Well Cap or Well Seal
- ☐ Other:

Based on my personal inspection of the real property, the well(s) and pressure system(s): ☑ **Complies** ☐ **Does not comply** with Wis. Adm. Code.

☐ More comprehensive or additional research is needed regarding:
☐ an unused well ☐ floodways/floodplains ☐ contaminant sources ☐ other:

This form lists the visible conditions of the well(s) and pressure system(s) on the property at the time of inspection and does not imply or give any guarantee.

Signature of Licensed Water Well Driller or Pump Installer	Individual License #	Date	Telephone Number
Dan Nilan	6340	3-15-19	780-2011

Ann A. Kelle

LA CROSSE COUNTY
Health Department
Nationally Accredited

Laboratory *201900245-002*

MILLERS PUMP INSTALLING
W22744 WILLIAM MILLER LN
GALESVILLE, WI 54630

Lab Sample ID: 201900245-002
Date Sampled: 3/18/2019 12:30
Date Received: 3/18/2019 1:56:00 PM
Sample Location: Pressure Tank Tap
Unique Well ID:

Submitter:	Client:	Sample Address:
MILLERS PUMP INSTALLING W22744 WILLIAM MILLER LN GALESVILLE, WI 54630	MICHELLE ABTS W544 COUNTY RD P FOUNTAIN CITY, WI54629	MICHELLE ABTS W544 COUNTY RD P FOUNTAIN CITY, WI54629

Requested Analysis

Analysis	Method	LOD	LOQ	Result	Unit	Result Description
ARSENIC	SM3113B	0.6	1.9	0.8	PPB(ug/L)	
ARSENIC IN DRINKING WATER: The Health Standard for Arsenic is 10 ug/L. If your water is less than 10 ug/L it is safe to drink and use for food preparation. Arsenic analysis performed by La Crosse County Health Dept @ 300 4th St N La Crosse WI 54601 Ph: 608-785-9733. WI Lab Certification #632072980. Method SM 3113B-1999						
Coliform Bacteria	SM9223B			Absent		Bacteriologically Safe
E. coli	SM9223B			Absent		
Nitrate	SM4500D-2000	1.0	1.6	1.6	mg/L	

Coliform - The presence of Coliform bacteria in water indicates that a pathway exists allowing surface water or shallow ground water to enter your water supply. Your water should be tested annually or anytime it has been repaired, modified, or there is a change in appearance, taste, odor or flow.
E. coli - The presence of E. coli indicates the presence of fecal material. Their presence indicates that water may be contaminated with organisms that can cause disease.

When bacteria are found in your water supply the following recommendations apply:
1. Do not consume your water or use for food preparation unless it has been boiled for 5 minute at a rolling boil.
2. Check for well construction or plumbing defects.
3. Correct any defects found.
4. Disinfect the entire well system after corrections are made.
5. Re-test the water from the well after all traces of chlorine have been flushed from the system.

Note: Boiling water for a long time reduces the volume of water and can increase the concentration of any nitrate that may be present in the water. This can make the water more hazardous for infants.

NITRATE NITROGEN: If your nitrate level is greater than 10 mg/L, your water exceeds state and federal standards for nitrate in public drinking water supplies. High nitrate levels in drinking water pose a serious risk to infants. If there is an infant or pregnant woman in your household and your water exceeds the federal nitrate standard, do not use your well water for drinking or cooking. The Wisconsin Division of Public Health recommends that people of all ages avoid long-term consumption of water that has a nitrate level greater than 10 mg/L.
Reverse Osmosis is a very effective and low maintenance treatment system for the removal of nitrate. Units are installed at the kitchen sink and are available from licensed plumbers, water treatment specialists and home improvement retailers. It is VERY IMPORTANT to have the RO treated water tested for nitrate after installation of a system to insure the system is working properly.
Nitrate Method SM 4500D-2000

Other Notes:

Email Sheryl Reedy with results

WDNR Laboratory Certification ID No. 632072980
WDATCP Laboratory Certification ID No. 115041-D3, ID No. 105-013

Printed on 3/20/2019 2:04:18 PM

300 4th Street North, 2nd Floor, La Crosse WI 54601 | 608-785-9872 Phone | 608-793-6565 Fax | lacrossecounty.org/health