Sheboygan County

Permit Number	NA-390
Parcel Number	59004036350
Site Address	W2931 PINE TREE CIR
Maintenance Company Name	East Central Pumping, Inc.
Filed Date	11/26/2025
Filed By	Amy Winkler
Service Date	09/16/2025
Gallons	1000

Component	Question	Response
Conventional		
	Effluent from POWTS was not discharging to the ground surface?	True
	No areas of dispersal component were found to have soft or spongy ground?	True
Septic Tank(s)		
	Tank compartment(s) are structurally sound and watertight?	True
	Inlet and outlet baffles are present and in good condition?	True
	Manhole cover(s) located above grade have an effective locking device and/or riser(s) is(are) located below grade?	True
	No backflow was observed after pumping?	True
	No scaling of concrete in the tank and riser(s) present?	True

Notes