Continuous Radon Monitor

Model Number: 1028
Serial Number: 100315018
Calibration Date: 04/05/2021
CF: 2.68
Monitor Time: 7/29/2021 19:17

Inspection Company

Accurate Home Inspections
1711 13th Street
Coralville, Iowa-52241
Phone Number: (319) 341-4344
License Number: RNTST10036

Billing Information

Jessica Cox
214 E Center Street
Oxford, Iowa-52322

Site Information

Jessica Cox
214 E Center Street
Oxford, Iowa-52322

Site & Condition


Wind: NA
Year Built: NA
Mitigation System: Not Installed
SqFt: NA

Atmospheric Condition: NA
Structure Type: NA
Monitor Location: NA

Test Summary

Start Time: 07/25/2021 10:57
End Time: 07/27/2021 10:57
Measurement Interval(hr): 1.0
Exposure Time: 2 Days 0 hrs

Overall Avg: 2.5 pCi/l
EPA Avg: 2.6 pCi/l



********* 07/25/2021 *********

Time	Counts pCi/l	Flags
11:57	1.9	
12:57	1.5	
13:57	3.7	
14:57	0.7	
15:57	0.7	
16:57	0.7	
17:57	1.1	
18:57	0.7	
19:57	0.0	
20:57	0.4	
21:57	1.9	
22:57	1.1	
23:57	1.9	

********* 07/26/2021 *********

Time	Counts pCi/l	Flags
00:57	2.2	
01:57	3.0	
02:57	2.6	
03:57	1.9	
04:57	3.7	
05:57	5.6	
06:57	4.8	
07:57	2.2	
08:57	3.0	
09:57	5.6	
10:57	3.7	
11:57	8.2	
12:57	3.4	
13:57	3.4	
14:57	1.9	
15:57	1.1	
16:57	0.7	
17:57	2.2	
18:57	0.4	
19:57	1.5	
20:57	1.1	
21:57	1.9	
22:57	0.4	
23:57	0.7	

********* 07/27/2021 *********

Time	Counts pCi/l	Flags
00:57	1.1	

********* 07/27/2021 *********

Time	Counts pCi/l	Flags
01:57	4.5	
02:57	1.9	
03:57	3.7	
04:57	4.5	
05:57	5.2	
06:57	4.5	
07:57	3.0	
08:57	4.5	
09:57	4.1	
10:57	3.0	

Error Flags:
M Motion:

Inspector Signature _____

PC Software Version: 2.2.0
Embedded Software Version: 109